



Sea-Bird Electronics, Inc. FAX: (425) 643-9954

1808 136th Place NE, Bellevue, Washington 98005 USA Tel: (425) 643-9866

Website: <http://www.seabird.com>

Email: seabird@seabird.com

Service Report

SBE Job Number: 37363

Date: October 25, 2004

Customer: US Department of Commerce, NOAA

Customer Identified Problem:

1. Calibrate SBE 9Plus, S/N 09P10779-0363.

Problems Found:

1. SBE 9Plus, S/N 09P10779-0363.
The transmitter card was found to be burnt.
This may have been caused by the Sea-Cable being connected to the pump connector.

Services Performed:

1. Calibrations and services performed on SBE 9Plus, S/N 09P10779-0363.
Replaced the transmitter card.
Replaced the main piston "O"-Rings.
Performed hydrostatic pressure test.
Calibrated the pressure sensor.
Replaced the anodes.
Performed full diagnostic evaluation.