

Company	US Department of Commerce, NOAA	Date	4/10/2012
Contact	Ulises Rivero		
PO Number	Credit Card		
-			

Serial Number	03P5233
Model Number	SBE 03P

## Services Requested:

- 1. Evaluate/Repair Instrumentation.
- 2. Perform Routine Calibration Service.

#### **Problems Found:**

#### Services Performed:

- 1. Performed initial diagnostic evaluation.
- 2. Performed "Post Cruise" calibration of the temperature sensor.



Company	US Department of Commerce, NOAA	Date	4/10/2012
Contact	Ulises Rivero		
PO Number	Credit Card		
-			

Serial Number	03P5237
Model Number	SBE 03P

## Services Requested:

- 1. Evaluate/Repair Instrumentation.
- 2. Perform Routine Calibration Service.

#### **Problems Found:**

#### Services Performed:

- 1. Performed initial diagnostic evaluation.
- 2. Performed "Post Cruise" calibration of the temperature sensor.



Company	US Department of Commerce, NOAA	Date	4/10/2012
Contact	Ulises Rivero		
PO Number	Credit Card		

## Services Requested:

- 1. Evaluate/Repair Instrumentation.
- 2. Perform Routine Calibration Service.

#### **Problems Found:**

#### Services Performed:

- 1. Performed initial diagnostic evaluation.
- 2. Performed "Post Cruise" calibration of the temperature sensor.



Company	US Department of Commerce, NOAA	Date	4/10/2012
Contact	Ulises Rivero		
PO Number	Credit Card		
-			

## Services Requested:

- 1. Evaluate/Repair Instrumentation.
- 2. Perform Routine Calibration Service.

## Problems Found:

#### Services Performed:

- 1. Performed initial diagnostic evaluation.
- 2. Performed "Post Cruise" calibration of the conductivity sensor.



Company	US Department of Commerce, NOAA	Date	4/10/2012
Contact	Ulises Rivero		
PO Number	Credit Card		
_			_

## Services Requested:

- 1. Evaluate/Repair Instrumentation.
- 2. Perform Routine Calibration Service.

#### **Problems Found:**

#### Services Performed:

- 1. Performed initial diagnostic evaluation.
- 2. Performed "Post Cruise" calibration of the conductivity sensor.



Company	US Department of Commerce, NOAA	Date	4/10/2012
Contact	Ulises Rivero		
PO Number	Credit Card		

## Services Requested:

1. Evaluate/Repair Instrumentation.

## **Problems Found:**

## Services Performed:

- 1. Performed initial diagnostic evaluation.
- 2. Performed internal inspection and O-ring and thrust washer replacements.
- 3. Performed hydrostatic pressure test.



Company U	S Department of Commerce, NOAA	Date	4/10/2012
Contact U	llises Rivero		
PO Number	redit Card		

Serial Number	055946
odel Number	SBE 05T

## Services Requested:

1. Evaluate/Repair Instrumentation.

## **Problems Found:**

#### Services Performed:

- 1. Performed initial diagnostic evaluation.
- 2. Performed internal inspection and O-ring and thrust washer replacements.
- 3. Performed hydrostatic pressure test.



Report	RMA Number	68422	
Customer Information:			
Company US Department of Commerce, NOA	A	Date	4/10/2012

Contact Ulises Rivero Credit Card PO Number

Serial Number	430730
Model Number	SBE 43

#### Services Requested:

- 1. Evaluate/Repair Instrumentation.
- 2. Perform Routine Calibration Service.

## **Problems Found:**

1. Customer has requested a refurb and has already used their one-time free refurb and cal (under 63129). \*\* This is not a warranty service.\*\*

## Services Performed:

- 1. Performed initial diagnostic evaluation.
- 2. Performed "Post Cruise" calibration of the oxygen sensor.
- 3. Replaced the lid and membrane assembly (0.5 mil).
- Replaced the electrolyte with new fluid.
  Performed "Final" calibration of the oxygen sensor.
- 6. Performed full diagnostic evaluation.



Service Report	RMA Number	68422	
Customer Information:			
Company US Department of Commo	erce, NOAA	Date	4/10/2012

Contact Ulises Rivero **PO Number** Credit Card

Serial Number	431266
Model Number	SBE 43

#### Services Requested:

- 1. Evaluate/Repair Instrumentation.
- 2. Perform Routine Calibration Service.

## **Problems Found:**

1. Customer has requested a refurb and has already used their one-time free refurb and cal (under 63129). \*\* This is not a warranty service.\*\*

## Services Performed:

- 1. Performed initial diagnostic evaluation.
- 2. Performed "Post Cruise" calibration of the oxygen sensor.
- 3. Replaced the lid and membrane assembly (0.5 mil).
- Replaced the electrolyte with new fluid.
  Performed "Final" calibration of the oxygen sensor.
- 6. Performed full diagnostic evaluation.