

	Report	RMA Number	6100	)9	
Customer Inf	ormation:				
Company	US Department of Commerce, NOAA			Date	9/9/2010
Contact	Ulises Rivero				
PO Number	Credit Card				

Model Number   SBE 09Plus

## Services Requested:

- 1. Evaluate/Repair Instrumentation.
- 2. Perform Routine Calibration Service.

## Problems Found:

1. Pressure port capillary assembly was found to be cracked at base of swagelok threads.

## Services Performed:

- 1. Performed initial diagnostic evaluation.
- 2. Calibrated the pressure sensor.
- 3. Installed NEW nylon swagelock.
- 4. Performed complete system check and full diagnostic evaluation.

## **Special Notes:**