



SEA-BIRD ELECTRONICS, INC.

13431 NE 20th St. Bellevue, Washington 98005 USA

Phone: (425) 643-9866 Fax: (425) 643-9954 www.seabird.com

Service
Report

RMA Number

79271

Customer Information:

Company US Department of Commerce, NOAA **Date** 5/9/2014

Contact Grant Rawson

PO Number NO CHARGE

Serial Number 03P5237

Model Number SBE 03P

Services Requested:

1. Evaluate/Repair Instrumentation.

Problems Found:

Services Performed:

1. Performed initial diagnostic evaluation.
2. Performed "Post Cruise" calibration of the temperature sensor.

Special Notes:



SEA-BIRD ELECTRONICS, INC.

13431 NE 20th St. Bellevue, Washington 98005 USA

Phone: (425) 643-9866 Fax: (425) 643-9954 www.seabird.com

Service
Report

RMA Number

79271

Customer Information:

Company	US Department of Commerce, NOAA	Date	5/9/2014
----------------	---------------------------------	-------------	----------

Contact	Grant Rawson
----------------	--------------

PO Number	NO CHARGE
------------------	-----------

Serial Number	03P5898
Model Number	SBE 03

Services Requested:

1. Evaluate/Repair Instrumentation.

Problems Found:

Services Performed:

1. Performed initial diagnostic evaluation.
2. Performed "Post Cruise" calibration of the temperature sensor.

Special Notes:



SEA-BIRD ELECTRONICS, INC.

13431 NE 20th St. Bellevue, Washington 98005 USA

Phone: (425) 643-9866 Fax: (425) 643-9954 www.seabird.com

Service
Report

RMA Number

79271

Customer Information:

Company US Department of Commerce, NOAA **Date** 5/9/2014

Contact Grant Rawson

PO Number NO CHARGE

Serial Number	043854
Model Number	SBE 04C

Services Requested:

1. Evaluate/Repair Instrumentation.

Problems Found:

Services Performed:

1. Performed initial diagnostic evaluation.
2. Performed "Post Cruise" calibration of the conductivity sensor.

Special Notes:



SEA-BIRD ELECTRONICS, INC.

13431 NE 20th St. Bellevue, Washington 98005 USA

Phone: (425) 643-9866 Fax: (425) 643-9954 www.seabird.com

Service
Report

RMA Number

79271

Customer Information:

Company	US Department of Commerce, NOAA	Date	5/9/2014
----------------	---------------------------------	-------------	----------

Contact	Grant Rawson
----------------	--------------

PO Number	NO CHARGE
------------------	-----------

Serial Number	043861
Model Number	SBE 04C

Services Requested:

1. Evaluate/Repair Instrumentation.

Problems Found:

Services Performed:

1. Performed initial diagnostic evaluation.
2. Performed "Post Cruise" calibration of the conductivity sensor.

Special Notes:



SEA-BIRD ELECTRONICS, INC.

13431 NE 20th St. Bellevue, Washington 98005 USA

Phone: (425) 643-9866 Fax: (425) 643-9954 www.seabird.com

Service
Report

RMA Number

79271

Customer Information:

Company US Department of Commerce, NOAA **Date** 5/9/2014

Contact Grant Rawson

PO Number NO CHARGE

Serial Number 044229

Model Number SBE 04

Services Requested:

1. Evaluate/Repair Instrumentation.

Problems Found:

Services Performed:

1. Performed initial diagnostic evaluation.
2. Performed "Post Cruise" calibration of the conductivity sensor.

Special Notes:



SEA-BIRD ELECTRONICS, INC.

13431 NE 20th St. Bellevue, Washington 98005 USA

Phone: (425) 643-9866 Fax: (425) 643-9954 www.seabird.com

Service
Report

RMA Number

79271

Customer Information:

Company	US Department of Commerce, NOAA	Date	5/9/2014
----------------	---------------------------------	-------------	----------

Contact	Grant Rawson
----------------	--------------

PO Number	NO CHARGE
------------------	-----------

Serial Number	09P76233-1165
Model Number	SBE 09



SEA-BIRD ELECTRONICS, INC.

13431 NE 20th St. Bellevue, Washington 98005 USA

Phone: (425) 643-9866 Fax: (425) 643-9954 www.seabird.com

Service
Report

RMA Number

79271

Customer Information:

Company	US Department of Commerce, NOAA	Date	5/9/2014
Contact	Grant Rawson		
PO Number	NO CHARGE		

Services Requested:

1. Evaluate/Repair Instrumentation.

Problems Found:

1. All top end cap connectors replaced due to Flooding.
2. All top end cap connectors replaced due to Flooding.
3. All top end cap connectors replaced due to Flooding.
4. All top end cap connectors replaced due to Flooding.
5. All top end cap connectors replaced due to Flooding.
6. All top end cap connectors replaced due to Flooding.
7. All top end cap connectors replaced due to Flooding.

Services Performed:

1. Performed initial diagnostic evaluation.
2. Installed NEW two pin bulkhead connector(s).
3. Installed NEW three pin bulkhead connector(s).
4. Installed NEW six pin bulkhead connector(s).
5. Installed NEW top end plate card assembly.
6. Performed internal inspection and O-ring replacement.
7. Performed hydrostatic pressure test.
8. Calibrated the pressure sensor.
9. Replaced anode(s).
10. Performed complete system check and full diagnostic evaluation.

Special Notes:

--