

19890803HI. RADAR

AUG 5 1989

E.5 Doppler Radar Scientist (On-Board)

The on-board Doppler radar scientist (DRS) is responsible for data collection from all radar systems on his/her assigned aircraft. Detailed operational procedures and check lists are contained in the operator's manual supplied to each operator. General supplementary procedures follow. (Check off and initial.)

E.5.1 Preflight

- YMD 1. Determine the status of equipment and report results to the on-board lead project scientist (LPS).
- YMD 2. Confirm mission and pattern selection from the on-board LPS.
- YMD 3. Select the operational mode for radar system(s) after consultation with the HRD/DRS and the on-board LPS.
- YMD 4. Complete the appropriate preflight calibrations and check lists as specified in the radar operator's manual.

E.5.2 In-Flight

- YMD 1. Operate the system(s) as specified in the operator's manual and as directed by the HRD/DRS, unless superseded by directions from the on-board LPS or as required for aircraft safety as determined by the OAO flight director or aircraft commander.

E.5.3 Postflight

- YMD 1. Complete the summary check lists and all other appropriate check lists and forms.
- YMD 2. Brief the on-board LPS on equipment status and turn in completed forms to the LPS.
- YMD 3. Hand-carry all radar tapes and arrange delivery as follows:
 - a. Outside of Miami - to the HRD operations center (FGOC).
 - b. In Miami - to MGOC or to AOML/HRD. [Note: all data removed from the aircraft by HRD personnel should be cleared with the OAO flight director.]
- YMD 4. Debrief at the appropriate operations center (FGOC or MGOC).
- YMD 5. Determine the status of future missions and notify the appropriate operations center (FGOC or MGOC) as to where you can be contacted.

910805 H1

Form E-5
Page 1 of 3

Doppler Radar Scientist Check List

Flight ID 890805 H1
Aircraft # 42
Operators P BLACK, DORST
Radar Tech. ROLES

AUG 5 1989

Number of digital magnetic tapes on board 20

Number of tape labels on board ∞

Component systems up and checked:

MARS ✓

Computer ✓

DMTR1 ✓

DMTR2 ✓

LF ✓

R/T# 103M

TA ✓

R/T# 9320 (?)

Time correction between radar time and digital time _____

Radar Postflight Summary

Number of digital tapes used:

DMTR1 _____

DMTR2 _____

Significant recorder down time:

DMTR 1 _____

Radar LF _____

DMTR 2 _____

Radar TA _____

Other problems:

[illegible]

Operator P BLACK/DORST

Sheet 1 of

[illegible]

Item List: DMTR1, DMTR2, COMP, RDSC, LF, TA, DSC1, DSC2.


890805H1 - Energetics Exp into
Hurricane Dean, RACING NORTH
from Puerto Rico (2 plane exp).
LPS - Dr Frank Marks, ODW - Dr HEW
Radar / AXBT. Dr P Black, CPS - R Black
Sailory bay - N Dorst

T/O San Juan 1314Z LAND San Juan ²² 13Z

1314Z - Beautiful sunny day as we
leave SJU, light swell on ocean,
no sign of DEAN here. We have
a guest from NWSFO on board.

J Thompson is our radar tech.

1410Z - Some minor problems getting
radar system UP, but now it seems
to run fine. Way north of us we
are getting some echoes. Not recording
yet!


1428Z - 43 has problem w/ 2 antennas
but they're continuing on. We have
eye ~ 150 NM out. Seems to have a
 closed eye, but were
too far out.

1440Z - Started recording radar data
at altitude 3500 m, tilt at 3° the
new system is very sensitive to
adjustment.


1454 - Starting eye penetration
25 km from eye wall



15Z - TA reflectivity problem
1504Z - Still working on TA. In
the eye



1507Z - TA back
in service




1516Z -
in the eyewall →

1600Z - Radar restart
going thru eye wall on our
way out West.

1602Z - TA problems (on STBY)

1631Z - TA still out, South of storm
in calm area. My sunning was

settled enough for me to enjoy
some Chicarrones. Yum.



1640Z - TA seems to be running
again. Keep your fingers crossed.
1644Z - You didn't keep your fingers
crossed! TA down again, they're
trying a restart.

1700Z - Restarted WFO's radar system
w/ new R/T for TAIL. Doppler velocities
suspect, but LF seems OK. Think
radar sys overheated

1732Z - In middle of a turn TA
began to 'Slatter', reset TA at 1737Z
since new R/T at 17Z the doppler
velocities have been bad. They're
about useless, but reflectivity seems
OK if suspect. LF is OK.

1811Z - During turn TA began to 'SPLATER'
again. Boys are too busy to work on
it now. Cleared up 1813Z

1825 Z - Descend to 500m

1843 Z - Bump caused TA to go
'SLATTER'


1858 Z - Eyewall at 500m, it's
pretty rough. TA continues
to act up 'splits'

1902 Z - TA on 'STNOB!'

1909 Z - TA working, but 'splits'
persist.

1918 Z - Stopped recording Doppler vel.

1939 Z - Heading for HEAVY
Eyewall at 500m!!



2015 Z - We climb up & N of eye.
I toss my lunch. Luckily, I only
ate 1/2 my Sandwich.

RADAR
2044 Z - System crash. Leaving the
hurricane, so we end radar recording
now.

2213 Z - Land at SJU