



Sea-Bird Electronics, Inc. FAX: (425) 643-9954

1808 136th Place NE, Bellevue, Washington 98005 USA Tel: (425) 643-9866

Website: <http://www.seabird.com>

Email: seabird@seabird.com

Service Report

SBE Job Number: 38879

Date: 24, March 2005

Customer: US Department of Commerce, NOAA

Customer Identified Problem:

1. Repair SBE 9Plus, S/N 09P8531-0367.

Problems Found:

1. SBE 9Plus, S/N 09P8531-0367.
The pump transmitter card was found to be damaged.
The customer reported problem could not be duplicated.

Services Performed:

1. Calibrations and services performed on SBE 9Plus, S/N 09P8531-0367.
Replaced the pump transmitter card. (*No Charge*)
Replaced the modem board as a precaution. (*No Charge*)
Replaced the main piston "O"-Rings.
Performed hydrostatic pressure test.
Calibrated the pressure sensor.
Performed full diagnostic evaluation.