Lead Project Scientist

Storm or Project Gabrielle Remnants **Experiment name** Genesis Survey
Flight ID 130907H1 **Mission ID** WB07A Gabrielle

Preflight

____ 1. Participate in general mission briefing.

____ 2. Determine specific mission and flight requirements for assigned aircraft.

____ 3. Determine from AOC flight director/meteorologist whether aircraft has operational fix responsibility and the mission designation.

____ 4. Contact HRD members of crew to:
   a. Assure availability for mission.
   b. Review field program safety checklist
   c. Arrange ground transportation schedule when deployed.
   d. Determine equipment status.

____ 5. Meet with AOC flight director and navigator at least 3 hours before take-off for initial briefing.

____ 6. Meet with AOC flight crew at least 2 hours before take-off for crew briefing. Provide copies of flight requirements and provide a formal briefing for the flight director, navigator, and pilots.

____ 7. Report status of aircraft, systems, necessary on-board supplies and crews to MGOC in Miami.

____ 8. Before take-off, brief the on-board GPS dropsonde operator on times and positions of drop times.

____ 9. Make sure each HRD flight crew member has a life vest.

____ 10. Perform a headset operation check with all HRD flight crew members. Make sure everyone can hear and speak using the headset.

In-Flight

____ 1. Confirm from AOC flight director that satellite data link is operative (information).

____ 2. Confirm camera mode of operation.

____ 3. Confirm data recording rate.

____ 4. Complete Lead Project Scientist Form.

____ 5. Check in with the flight director to make sure the mission is going as planned (i.e. turns are made when they are supposed to be made).

Post flight

____ 1. Debrief scientific crew.

____ 2. Gather completed forms for mission and turn in to data manager at HRD.

____ 3. Obtain a copy of the 10-s flight listing from the AOC flight director. Turn in with completed forms.

____ 4. Obtain a copy of the radar DAT tapes. Turn in with completed forms.

____ 5. Obtain a copy of serial flight data on thumb drive. Turn in with completed forms.

[**Note**: all data removed from the aircraft by HRD personnel should be cleared with the AOC flight director.]

____ 6. Report landing time, aircraft, crew, and mission status along with supplies (tapes, *etc.*) remaining aboard the aircraft to MGOC.

____ 7. Determine next mission status, if any, and brief crews as necessary.

____ 8. Notify MGOC as to where you can be contacted and arrange for any further coordination required.

____ 9. Prepare written mission summary using **Mission Summary** form.

Lead Project Scientist Check List

Storm or Project_____ **Experiment name**_____

Flight ID _____ **Mission ID**_____

A. Participants:

HRD		AOC	
Function	**Participant**	**Function**	**Participant**
Lead Project Scientist	JASON DUNION	Flight Director	Henning
Radar/Workstation	Lisa Bucci	Pilots	Giramonte Kilabey Kearns
		Navigator	Siegel
Cloud Physics		Systems Engineer	Klippel / Puls
		Data Technician	
Dropwindsonde	Joe Cione	Electronics Technician	~~Bosko~~ / Lynch
AXBT/AXCP		Other	
Photographer/Observers/Guests			

B. Take-off and Landing Times and Locations:

Take-Off: 1516 UTC Location: St. Croix

Landing: 2238 UTC Location: St. Croix

Number of Eye Penetrations: NA

C. Past and Forecast Storm Locations:

Date/Time	Latitude	Longitude	MSLP	Maximum Wind

D. Mission Briefing:

deep convection limited to mainly 1-2, 5-6 S-N runs

Storm or Project_____ **Experiment name**_____

Flight ID _____ **Mission ID**_____

E. —Equipment Status (Up ↑, Down ↓, Not Available **N/A**, Not Used **O**)

Equipment	Pre-Flight	In-Flight	Post-Flight	# DATs / CDs /Expendables/ Printouts
Radar/LF				
Doppler Radar/TA				
Cloud Physics				
Data System				
GPS sondes				
AXBT/AXCP				
Ozone instrument				
Workstation				
Cameras				

Single PRF
PRF 2100

REMARKS:

10 = 20562
11 = 2118



1 20.5 N 67.0W 1608Z
2 23.5 N 67.0W
3 23.5N 71.0W
4 20.5 N 71.0W
5 20.5N 67.5W
6 22.5 N 67.5W
7 22.5 N 70.0W
8 21.0 N 70.0W
9 21.0N 68.0W
10 22.0N 68.0W
11 22.0N 69.5W

All pts BT-Sonde combo
except missed pt 5 (no visual for ship traffic)