

RADAR PREFLIGHT CHECKLIST

FLIGHT # 830816H

A.C. # 42

OPERATOR DORST / FEINBERG

RADAR TECH SHRICKER

NUMBER OF DIGITAL MAGNETIC TAPES ONBOARD 12

NUMBER OF VIDEO TAPES ONBOARD 3

NUMBER OF TAPE LABELS ON BOARD 2100

COMPONENT SYSTEMS UP AND CHECKED.

RDSC ✓  
COMPUTER ✓  
DMTR1 ✓  
DMTR2 ✓

VTR ✓  
DSC1 ✓  
DSC2 ✓  
SCOPES ✓

NO ✓  
LF ✓  
TA ✓

Time correction between radar time and digital time 01 SEC

RADAR POSTFLIGHT SUMMARY

NUMBER OF DIGITAL TAPES USED DMTR 1 3  
DMTR 2 2

NUMBER OF VIDEO TAPES USED 1

SIGNIFICANT RECORDER DOWN TIME (other than for tape changes).

DMTR: LF LAST 60 MIN  
NO \_\_\_\_\_  
TA \_\_\_\_\_

VTR: LF FIRST HOUR  
NO \_\_\_\_\_  
TA \_\_\_\_\_ } ? CONNECTION FAULTY

OTHER PROBLEMS: (stabilization, interference, etc.)

AUG 15 1983



# NHEML RADAR LOG

OPERATOR DORST / KEINBERG  
 SHEET 1 OF     

RADAR DOWN-TIME LOG

AUG 15 1983

<u>ITEM</u>	<u>TIME DOWN</u>	<u>TIME UP</u>	<u>PROBLEM</u>
INPUT THRESHOLD'S LEVEL CAUSE COMMAND ERROR, SET TO LF #5	<u>0350</u>	<u>0350</u>	<del>BLIGHT TAPE CHANGE</del>
	<del>0553 S2</del>		
	0740	0811	SUEEP ON LF STOPPED

ITEM LIST: VTR, DMTRI, DMTR2, COMP, ROSC, LF, NO, TA, DSCI, DSC2