

# Radar Scientist Form

(Updated 31 May 2019)

Flight ID 201903141 Storm DORZAN

HRD Radar Scientist (Aircraft/Ground) SIPPEL / REASUR

AOC Radar Operator \_\_\_\_\_

The aircraft radar scientist is responsible for data collection from all radar systems on his/her assigned aircraft, working with the ground radar scientist to ensure successful transmission of all radar products from the aircraft in a timely manner, and contributing to mission science by communicating real-time radar products to the LPS. Specific responsibilities are detailed in the *Aircraft Radar Support Guide* located on the radar workstation desktop and in the flight bag.


## § Pre-flight Notes.

Indicate below any existing radar instrumentation issues, pre-flight radar repairs or other instrumentation issues (e.g., GPS swapout) that might impact radar data collection or analyses. If none, then simply write NONE below.

## § Pre-flight Setup with Ground Radar Scientist.

Preferably before the planeside briefing, establish Xchat communication with the ground radar scientist on #radar. Check off the following tasks.

- Communicate any pre-flight issues noted above.
- Confirm latest flight pattern. Sketch to the right.  
Indicate legs constituting proposed analyses.
- Go through Steps 1-3 of Aircraft Radar Support Guide.



### § In-flight Setup with Ground Radar Scientist.

After radar recording has begun, reestablish Xchat communication with the ground radar scientist on #radar. Check off the following tasks.

- Go through Steps 4-7 of Aircraft Radar Support Guide.

Indicate below any issues identified during Steps 4-7, in particular any radar instrumentation issues evident in the radar displays. If none, then simply write NONE below.

### § In-pattern Radar and Weather Event Log.

Indicate below any radar down times or significant weather observations that might be helpful for interpreting radar analyses (e.g., flight through sparse shallow convection).

Time (HHMMSS)	Event (Radar or Weather)
0955-1000	shallower convection (deep abs.) seen in TDR & <del>unusually</del>
100721	moderate convection out left window, to 12 km TDR
1029	JP
1036	shallow conv left window
	2nd DW leg messy due to nav trying to miss convection

