

Radar Scientist Checklist

Flight # 19831010 I L RADAR

A. C. # 43 RF

Operator Markes / Bogert / Lemone

Radar Tech. Dugran rut / Shrocker

Number of digital magnetic tapes on board > 20

Number of video tapes on board > 7

Number of tape labels on board > 100

Component systems up and checked:

RDSC X

VTR X

Computer X

DSC1 X

DMTR1 X

DSC2 X

DMTR2 X

Scopes X

NO

LF X

TA X

Time correction between radar time and digital time ~ 1 sec

Radar Postflight Summary

Number of digital tapes used DMTR 1 4

DMTR 2 3

Number of video tapes used 1

Significant recorder down time (other than for tape changes):

DMTR: LF None
NO
TA

VTR: LF None
NO
TA

Other problems: (stabilization, interference, etc.)

SHEET 1 OF 7

75

NHRL DOPPLER RADAR TAPE LOG

FLIGHT 830101

AIRCRAFT 43

OPERATOR

Marks

SHEET / OF

[illegible]