

Radar Scientist Checklist

JUL 24 1984

Tramm

Flight # 19840724E1 - RADAR
A. C. # 43RF
Operator Marks - Dodge
Radar Tech. Goldstein

Number of digital magnetic tapes on board > 20

Number of video tapes on board > 4

Number of tape labels on board > 100

Component systems up and checked:

RDSC ✓

VTR ✓

Computer ✓

DSC1 ✓

DMTR1 ✓

DSC2 ✓

DMTR2 ✓

Scopes ✓

NO ✓

LF ✓

TA ✓

Time correction between radar time and digital time ~ 15

Radar Postflight Summary

Number of digital tapes used DMTR 1 3

DMTR 2 3

Number of video tapes used 0

Significant recorder down time (other than for tape changes):

DMTR: LF

VTR: LF

NO

NO

TA

TA


Other problems: (stabilization, interference, etc.)

JUL 24 1984

Form E-4
Page 4 of 4

HRD DOPPLER RADAR TAPE LOG

[illegible]



every $\frac{10 \text{ rpm}}{6}$

$$\begin{array}{r} 120 \\ 1.2 \\ \hline 144 \text{ kw} \end{array}$$

JUL 24 1984

FLIGHT 840724I1 AIRCRAFT 43RF

OPERATOR *HAWKINS*
Bochen

SHEET 2 OF 1

[illegible]