

# NOAA Aircraft Operations Center - NOAA 43 Flight Manifest

68  
43  
25  
66  
50  
16  
13  
8  
21

FLIGHT INFORMATION				CREW MANIFEST				MISSION INFORMATION					
FILE ID	OPERATION	FLT #	FLY	AC	Price	CP(s)	SW	Pressure	Dropsondes	Good	Bad	Sent	AXBT
1908		1906		SEB	Smith	Parley	Haystack			Good	Bad	Sent	
Out:	1343	Out:	1350	FE(s)	Lalonde	Olney	SansSouci	Wx Station	Takeoff	Good	Bad	Sent	
Total:	5.4	Total:	5.3	FD(s)	Sears	Visitors:		Wx Station	Land				
Sponsoring Org:	NWS			SEB:	Peek			Storm Number ID:					
Program:	Hurricane Surveillance			SSA:	Naeher			TOPOD/WSPOD Mission					
Purpose:	Ferry (Danny Ops)			AVAPS:				(fe: NOAA2 2418A SANDY)					
AS REQUIRED BY ORM				REMARKS				OBSERVATIONS					
VOLCANIC ASH				Y	N			Fix Number	Obs Number	Fix Time	SLP		
SCIENCE MISSION WITHIN BDRY LAYER				X									
LACK OF PRECIPITATION				N									
RELATIVE HUMIDITY ≥ 80%				NA									
LARGE AIR-SEA TEMP GRADIENT				N	X								
HIGH SURFACE WINDS				N	X								
LONG FETCH / DURATION OF SFC WIND				N	X								
SEA SALT ACCRETION FORECAST				N	X								
SEA SALT ACCRETION OBSERVED				N	X								

Additional Remarks: **knuck** / **TBRB - 070 16** \*Highlighted items must be submitted to Flt Ops before departure.

VA  
SEA SKT } 1056

WX 120 04 CLR 105m  
POT 000k WX

WXWX  
TZRIN