

NOAA Aircraft Operations Center - NOAA 43 Flight Manifest

FLIGHT INFORMATION				CREW MANIFEST			MISSION INFORMATION				
FLT ID:	2016100311	FLT #:		AC:	Kerns	Scientists:	Pressure		Dropsondes		
From:	TISX	ETD:	1500Z	CP(s):	Martin	Paul Chang	A/C Takeoff		Good	Bad	Sent
To:	TISX	ETA:	2300Z		Kahn	Zorona Jelenak					
Block Time		Flight Time		Nav(s):	Gallagher	Joe Sapp	Wx Station Takeoff		BTs		
In:	1832	In:	1823		Freeman					Good	Bad
Out:	1437	Out:	1443	FE(s):	Darby		A/C Land				
					LaLonde						
Total:	3.9	Total:	3.7	FD(s):	Parrish		Wx Station Land				
					Williams						
Sponsoring Org:		HRD		SEB:	Kregelka		Storm Number ID:		AL 142016		
Program:		PHX			Peek		(ie: AL072012)				
Purpose:		Ocean Winds transit		SSA:	Naeher		TCPOD/WSPOD Mission		WXWXA MATTHEW		
							(ie: NOAA2 2418A SANDY)				
				AVAPS:	Olney		OBSERVATIONS				
AS REQUIRED BY ORM				Y	N	REMARKS		Fix Number	Obs Number	Fix Time	SLP
VOLCANIC ASH					X						
SCIENCE MISSION WITHIN BDRY LAYER					X						
LACK OF PRECIPITATION					X						
RELATIVE HUMIDITY ≥ 80%				X							
LARGE AIR-SEA TEMP GRADIENT					X						
HIGH SURFACE WINDS				X							
LONG FETCH / DURATION OF SFC WND					X						
SEA SALT ACCRETION FORECAST					X						
SEA SALT ACCRETION OBSERVED											
Additional Remarks:						*Highlighted items must be completed before departure.					
Cockpit Gmax:				Gmin:							