

Company	US Department of Commerce, NOAA	Date	4/2/2009
Contact	Carlos Fonseca		
PO Number	TBD		

Serial Number	)31652
Model Number	SBE 03-02/F


# Services Requested:

- 1. Evaluate/Repair Instrumentation.
- 2. Perform Routine Calibration Service.

#### **Problems Found:**

#### Services Performed:

- 1. Performed initial diagnostic evaluation.
- 2. Performed "Post Cruise" calibration of the temperature sensor.



Company	US Department of Commerce, NOAA	Date	4/2/2009
Contact	Carlos Fonseca		
PO Number	TBD		

Serial Number 031692
Model Number SBE 03-02/F

# Services Requested:

- 1. Evaluate/Repair Instrumentation.
- 2. Perform Routine Calibration Service.

#### Problems Found:

#### Services Performed:

- 1. Performed initial diagnostic evaluation.
- 2. Performed "Post Cruise" calibration of the temperature sensor.



Company	US Department of Commerce, NOAA	Date	4/2/2009
Contact	Carlos Fonseca		
PO Number	TBD		

Serial Number	031701
Model Number	SBE 03-02/F

# Services Requested:

- 1. Evaluate/Repair Instrumentation.
- 2. Perform Routine Calibration Service.

#### **Problems Found:**

#### Services Performed:

- 1. Performed initial diagnostic evaluation.
- 2. Performed "Post Cruise" calibration of the temperature sensor.



Company	US Department of Commerce, NOAA	Date	4/2/2009
Contact	Carlos Fonseca		
PO Number	TBD		

Serial Number	3P2946
Model Number	BE 03Plus


# Services Requested:

- 1. Evaluate/Repair Instrumentation.
- 2. Perform Routine Calibration Service.

#### **Problems Found:**

#### Services Performed:

- 1. Performed initial diagnostic evaluation.
- 2. Performed "Post Cruise" calibration of the temperature sensor.



Company	US Department of Commerce, NOAA	Date	4/2/2009
Contact	Carlos Fonseca		
PO Number	TBD		

Serial Number	3P2958
Model Number	BE 03Plus


# Services Requested:

- 1. Evaluate/Repair Instrumentation.
- 2. Perform Routine Calibration Service.

#### Problems Found:

#### Services Performed:

- 1. Performed initial diagnostic evaluation.
- 2. Performed "Post Cruise" calibration of the temperature sensor.



Company	US Department of Commerce, NOAA	Date	4/2/2009
Contact	Carlos Fonseca		
PO Number	TBD		

Serial Number	3P4799
Model Number	BE 03Plus

# Services Requested:

- 1. Evaluate/Repair Instrumentation.
- 2. Perform Routine Calibration Service.

#### Problems Found:

#### Services Performed:

- 1. Performed initial diagnostic evaluation.
- 2. Performed "Post Cruise" calibration of the temperature sensor.



Company	US Department of Commerce, NOAA	Date	4/2/2009
Contact	Carlos Fonseca		
PO Number	TBD		
-			

Serial Number	041346
Model Number	SBE 04-02/0


# Services Requested:

- 1. Evaluate/Repair Instrumentation.
- 2. Perform Routine Calibration Service.

#### Problems Found:

#### Services Performed:

- 1. Performed initial diagnostic evaluation.
- 2. Performed "Post Cruise" calibration of the conductivity sensor.



Company	US Department of Commerce, NOAA	Date	4/2/2009
Contact	Carlos Fonseca		
PO Number	TBD		
-			

Serial Number	41347
Model Number	BE 04-02/0

# Services Requested:

- 1. Evaluate/Repair Instrumentation.
- 2. Perform Routine Calibration Service.

#### Problems Found:

#### Services Performed:

- 1. Performed initial diagnostic evaluation.
- 2. Performed "Post Cruise" calibration of the conductivity sensor.



Service	Report	RMA Number	53938	
Customer In	formation:			
Company	US Department of Commerce, NOAA		Date	4/2/2009

# Contact Carlos Fonseca PO Number TBD

Serial Number	042973
Model Number	SBE 04C

# Services Requested:


- 1. Evaluate/Repair Instrumentation.
- 2. Perform Routine Calibration Service.

# Problems Found:

1. One end of the conductivity cell was found cracked.

# Services Performed:

- 1. Performed initial diagnostic evaluation.
- 2. Performed "Post Cruise" calibration of the conductivity sensor.
- 3. Replaced the conductivity cell.
- 4. Performed internal inspection and O-ring replacement.
- 5. Performed hydrostatic pressure test.
- 6. Performed "Final" calibration of the conductivity sensor.



Company	US Department of Commerce, NOAA	Date	4/2/2009
Contact	Carlos Fonseca		
PO Number	TBD		

Serial Number	042980
Model Number	SBE 04C


# Services Requested:

- 1. Evaluate/Repair Instrumentation.
- 2. Perform Routine Calibration Service.

# Problems Found:

#### Services Performed:

- 1. Performed initial diagnostic evaluation.
- 2. Performed "Post Cruise" calibration of the conductivity sensor.



Company	US Department of Commerce, NOAA	Date	4/2/2009
Contact	Carlos Fonseca		
PO Number	TBD		
-			

Serial Number	043338
Model Number	SBE 04C


# Services Requested:

- 1. Evaluate/Repair Instrumentation.
- 2. Perform Routine Calibration Service.

#### **Problems Found:**

#### Services Performed:

- 1. Performed initial diagnostic evaluation.
- 2. Performed "Post Cruise" calibration of the conductivity sensor.



Company	US Department of Commerce, NOAA	Date	4/2/2009
Contact	Carlos Fonseca	-	
PO Number	ТВО		

rial Number 430154
odel Number   SBE 43


# Services Requested:

- 1. Evaluate/Repair Instrumentation.
- 2. Perform Routine Calibration Service.

#### Problems Found:

# Services Performed:

- 1. Performed initial diagnostic evaluation.
- 2. Performed "Post Cruise" calibration of the oxygen sensor.
- 3. Performed full diagnostic evaluation.



Company	US Department of Commerce, NOAA	Date	4/2/2009
Contact	Carlos Fonseca		
PO Number	TBD		


# Services Requested:

- 1. Evaluate/Repair Instrumentation.
- 2. Perform Routine Calibration Service.

#### Problems Found:

#### Services Performed:

- 1. Performed initial diagnostic evaluation.
- 2. Performed "Post Cruise" calibration of the oxygen sensor.
- 3. Performed "Final" calibration of the oxygen sensor.
- 4. Performed full diagnostic evaluation.



Company	US Department of Commerce, NOAA	Date	4/2/2009
Contact	Carlos Fonseca		
PO Number	ТВО		
,			

Serial Number	l31348
Model Number	SBE 43

# Services Requested:

- 1. Evaluate/Repair Instrumentation.
- 2. Perform Routine Calibration Service.

#### **Problems Found:**

#### Services Performed:

- 1. Performed initial diagnostic evaluation.
- 2. Performed "Post Cruise" calibration of the oxygen sensor.
- 3. Performed full diagnostic evaluation.