

1808 - 136th Place Northeast, Bellevue, Washington 98005 USA

Phone: (425) 643-9866 Fax: (425) 643-9954 www.seabird.com

	_							
Service			RMA Number	5448	80			
	Report			<u> </u>				
Customer Info	ormation:							
Company	US Department of Co	mmerce, NOAA			Date	6/2/2009		
Contact	Sommyr Pochan							
PO Number	Mastercard							
Serial Number	380207							
Model Number	er SBE 38							
Services Requested:								
<ol> <li>Evaluate/Re</li> <li>Perform Rou</li> </ol>	pair Instrumentation. Itine Calibration Service	).						
Problems For	und:							
Services Perf	ormed:							
	nitial diagnostic evaluat Post Cruise" calibration		ure sensor.					
	omplete system check							
Special Notes								
opeciai Notes	).							

Tuesday, June 02, 2009 Page 1 of 2



1808 - 136th Place Northeast, Bellevue, Washington 98005 USA

Phone: (425) 643-9866 Fax: (425) 643-9954 www.seabird.com

Service									
Sei vice	Poport		RMA Number	5448	30				
	Report		•						
<b>Customer Infe</b>	ormation:								
Company	US Department of 0	Date	6/2/2009						
Contact	Sommyr Pochan								
PO Number	Mastercard								
Serial Number	4539646-0139								
Model Number	er SBE 45								
Services Req	uested:								
Evaluate/Repair Instrumentation.     Perform Routine Calibration Service.									
Z. Pellollii hou	illile Calibration Serv	ice.							
Problems Found:									
Services Perf	formed:								
	nitial diagnostic evalu	ation.							
2. Performed "I	Post Cruise" calibrat	on of the tempera		ensors.					
	nternal inspection an ydrostatic pressure t		ent.						
	omplete system che		tic evaluation.						
<b>Special Notes</b>	<b>S</b> :								

Tuesday, June 02, 2009 Page 2 of 2