

## Customer Information:

Company	US Department of Commerce, NOAA	Date	7/11/2012
Contact	Ulises Rivero		
PO Number	TBD		

Serial Number	031701
Model Number	SBE 03-02/F

## Services Requested:

- 1. Evaluate/Repair Instrumentation.
- 2. Perform Routine Calibration Service.

## Problems Found:

# Services Performed:

- 1. Performed initial diagnostic evaluation.
- 2. Performed "Post Cruise" calibration of the temperature sensor.
- 3. Backfilled sensor with ARGON gas.
- 4. Performed internal inspection and O-ring replacement.
- 5. Performed hydrostatic pressure test.
- 6. Performed "Final" calibration of the temperature sensor.

#### **Special Notes:**



	Report	RMA Number	69711	
Customer Inf	ormation:			
Company	US Department of Commerce, NOAA		Date	7/11/2012
Contact	Ulises Rivero			
PO Number	TBD			

## Services Requested:

- 1. Evaluate/Repair Instrumentation.
- 2. Perform Routine Calibration Service.
- 3. Perform Membrane Replacement and Re-fill Electrolyte.

## Problems Found:

1. A full refurb was requested.

## Services Performed:

- 1. Performed initial diagnostic evaluation.
- 2. Performed "Post Cruise" calibration of the oxygen sensor.
- 3. Replaced the lid and membrane assembly (0.5 mil).
- 4. Replaced the electrolyte with new fluid.
- 5. Performed "Final" calibration of the oxygen sensor.
- 6. Performed full diagnostic evaluation.

#### Special Notes: