

High-density XBT cruise AX180614 report

Ship : Triton Ace

Call sign : 3FFC7

Ship Rider : Dr. YURQUINA Luis Roque (PH Oceanographic Technician - environmental rights Specialist)

Dates XBT's deployed :

- a) **XBTs deployed : 263**
- b) **Drifters deployed: none**

Profiling floats deployed: none

d) Equipment tools and supplies needed:

e) New Adjustable Stainless Steel Sign Mounting Bracket Set for Poles, new screw driver for the brackets.

f) A inflatable mattress, one alarm clock (powerfull), electric contacts cleaner (spray).

g) **Other narrative:**

The Spare CPU freeze it every 2 hours. And when the AVG (antivirus) it's running. The primary CPU does not open the AMVERSEAS program properly "XBT t-12 Lcni Ver. 3.2 problem" T&T tranreceiver interface freeze every 10 hours. The primary Automatic Launcher: tube 7 have a connection problem, drops missed because sometimes don't recognize the probe. Tube 3 trigger pin, sometimes retracted it alone.

h) **Ship contact:** Captain Rajeesh Bist.
email: