

JUN 4 1982

OTHER PROBLEMS: (stabilization, interference, etc.)

JUN 4 1982

OPERATOR **FEINBERG** ~~SECRET~~ / **GRIFIN** 1 OF

[illegible]

820604I

Alberto

033400 - start recording ; nose & tail
tail on min data rate

What a way to spend an evening and oh gosh
we have 3 boys from CBS along with us

040400 - step thru the VTR in about 1 minute.
That Bob is really fast!

041000 - LF tilt really seems to bounce a lot.

041647 - LF tilt seems awfully touchy and I don't
know if I believe it

042700 - LF tilt bouncing all over

042800 - hit EOT on TAPE 1

042830 - switch to second drive

043000 - mysterious blob on LF has disappeared
only a few specks of anything is visible
now

043415 - switched DSC 2 to TAIL

043624 - set thresholds for TAIL


043800 - Alberto ; makes you want to run right out
and wash your hair. That would be the only
exciting thing about now. Yawn

050400 - switched tail recording rate to MAX

050615 - step thru channels

050553 - computer hang metro variables

050745 - restart



Heading 90

24.82, 96.5

820604I - continued

051320 - so far max wind speed @ 17 ms'
but its increasing

051748 - hit EOT drive 2

051818 - start drive 1 tape 2

052700 - radars are pretty much empty now

054020 - switched TAIL back to min rate

055750 - EOT on 1

055820 switch to drive 2

060320 step thru channels

060600 - what is a person to do for a thrill?
this storm is following in the tradition
of Dennis and those other greats

062830 - DSC 2 to LF

063930 - step thru channels


064700 - action packed adventure galore!

065550 EOT drive 2

065614 start drive 1

070500 - step thru channels

070625





current picture
of storm

24.52 , 84.58

EITHER NO RADAR OR NO STORM. WHICH??

820604J continued

0744046 VTR 1 stop
074137 VTR 2 start and step thru
075440 EOT drive 1 red light not working properly
075550 start 2
075811 DSC 2 on TAIL
082030 MAX data rate for TAIL
082115 step thru channels



083930 EOT 2
084000 start 1
090200 MIN data rate for tail
091105 EOT 1 hung up
091750 restart radar system
092012 start drive 2
100025 MAX data rate for TAIL ; hung up SW
we are missing the storm now

820604 I

102250 - AL Jarvis cannot get the ROsc to
work any more ; so it looks like we
are finished all rapped up etc. . No
more data for us today