

RADAR PREFLIGHT CHECKLIST

FLIGHT # 19830816HI-RADAR

A.C. # 42

OPERATOR DORST / FEINBERG

RADAR TECH SHRICKER

NUMBER OF DIGITAL MAGNETIC TAPES ONBOARD 12

NUMBER OF VIDEO TAPES ONBOARD 3

NUMBER OF TAPE LABELS ON BOARD 2100

COMPONENT SYSTEMS UP AND CHECKED.

RDSC ✓
COMPUTER ✓
DMTR1 ✓
DMTR2 ✓

VTR ✓
DSC1 ✓
DSC2 ✓
SCOPES ✓

NO ✓
LF ✓
TA ✓

Time correction between radar time and digital time 01 SEC

RADAR POSTFLIGHT SUMMARY

NUMBER OF DIGITAL TAPES USED DMTR 1 3
DMTR 2 2

NUMBER OF VIDEO TAPES USED 1

SIGNIFICANT RECORDER DOWN TIME (other than for tape changes).

DMTR: LF LAST 50 MIN
NO _____
TA _____

VTR: LF FIRST hour
NO _____
TA _____ } ? CONNECTION FAULTY

OTHER PROBLEMS: (stabilization, interference, etc.)

AUG 15 1983

NHEML RADAR LOG

OPERATOR DORST / FEINBERG
 SHEET 1 OF

RADAR DOWN-TIME LOG

AUG 15 1983

<u>ITEM</u>	<u>TIME DOWN</u>	<u>TIME UP</u>	<u>PROBLEM</u>
INPUT THRESHOLD'S LEVEL CAUSE COMMAND ERROR, SET TO LF #'S	<u>0350</u>	<u>0350</u>	BLIND TAP CHANGE
	035352		
	0740	0811	SUEEP ON LF STOPPED









