

Radar Scientist Checklist

SEP 1 1984

Flight # 19840911H1-RADAR D. Diana
A. C. # N42RF
Operator Kohler, Wiggert Blumstein
Radar Tech. Berles, Torri

Number of digital magnetic tapes on board 24

Number of video tapes on board 4

Number of tape labels on board enough

Component systems up and checked:

RDSC ✓

VTR ✓

Computer ✓

DSC1 ✓

DMTR1 ✓

DSC2 ✓

DMTR2 ✓

Scopes —

NO —

LF ✓

TA ✓

Time correction between radar time and digital time +1^s

Radar Postflight Summary

Number of digital tapes used DMTR 1 6

DMTR 2 5

Number of video tapes used 3

Significant recorder down time (other than for tape changes):

DMTR: LF None

VTR: LF None

NO —

NO —

TA None

TA None

Other problems: (stabilization, interference, etc.)

SHEET 1 OF 1

COMMENTS

152326

L/R

RNG MK

40 MI

8
4
0
9
1
1
H

HDG

090

TILT

1.0

DMTR

1-REC

2-OFF