# 1989401411-RADAR

#### E.5 Doppler Radar Scientist (On-Board)

The on-board Doppler radar scientist (DRS) is responsible for data collection from all radar systems on his/her assigned aircraft. Detailed operational procedures and check lists are contained in the operator's manual supplied to each operator. General supplementary procedures follow. (Check off and initial.)

#### E.5.1 Preflight

1.

3.

\_\_\_\_\_

OCT 1 4 1989

Determine the status of equipment and report results to the on-board lead project scientist (LPS).

- 2. Confirm mission and pattern selection from the on-board LPS.
- \_\_\_\_
- Select the operational mode for radar system(s) after consultation with the HRD/DRS and the on-board LPS.
- 4. Complete the appropriate preflight calibrations and check lists as specified in the radar operator's manual.

## E.5.2 In-Flight

1. Operate the system(s) as specified in the operator's manual and as directed by the HRD/DRS, unless superseded by directions from the on-board LPS or as required for aircraft safety as determined by the OAO flight director or aircraft commander.

### E.5.3 Postflight

- 1. Complete the summary check lists and all other appropriate check lists and forms.
- 2. Brief the on-board LPS on equipment status and turn in completed forms to the LPS.
- 3. Hand-carry all radar tapes and arrange delivery as follows:
  - a. Outside of Miami to the HRD operations center (FGOC).
  - b. In Miami to MGOC or to AOML/HRD. [Note: all data removed from the aircraft by HRD personnel should be cleared with the OAO flight director.]
- \_\_\_\_\_
- 4. Debrief at the appropriate operations center (FGOC or MGOC).
- 5. Determine the status of future missions and notify the appropriate operations center (FGOC or MGOC) as to where you can be contacted.

Form E-5 Page 1 of 3

Doppler Radar Sci	ientist Check List
Flight ID 891014	II
Aircraft # N43RF	
Operators GAMACHE	·
Radar Tech.	
Number of digital magnetic tapes on boar	rd <b>2</b> 8
Number of tape labels on board _ENO	UGIt
Component systems up and checked:	
MARS	Computer
DMTR1	DMTR2
LF Flyt	B/T# S/NI 21 2 replaced with
TA 1213	R/T#
Time correction between radar time and o	digital time <u>1 Sec</u>
Radar Postflig	ght Summary
Number of digital tapes used:	DMTR1 2
	DMTR2/
Significant recorder down time:	
DMTR1 None	Radar LF None
DMTR2 None	Radar TA Last 73 gtlight

AATAR-ITHIONPERI

Other problems:

OCT 1 4 1989

Form E-5 Page 2 of 3

HRD Radar Tape Log

Flight 891014II Aircraft N43RF Operator GAMACHE Sheet 1 of \_\_\_\_

Tape #	Time On	Time Off	Comments
D1-1	93245	110000	
D2-1		1457	1213 - TArecordingstopped RT to be
D1-2	1457	1600	
A.			
		1 Maria	
		Sel .	

Form E-5 Page 3 of 3

HRD Radar Down-Time Log

Operator GAMALHE

Sheet / of \_

Time Down Tir	me Up	Problem
100582 100	0	TA NOT UPDATING
1213	1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1	TA keys catting out. Popping : Gave up on Dycplus at this point
		. ,, .,

Item List: DMTR1, DMTR2, COMP, RDSC, LF, TA, DSC1, DSC2.