	Lead Project Scientist			
C4	75. Dime 7			
	or Project 12, Danny Experiment name 12, Comy 2			
Preflig	Mission ID WX OSA Danny 2			
There	" A CONTRACT ON CONTRACT OF THE STATE OF THE			
7	1. Participate in general mission briefing.			
Dus	2. Determine specific mission and flight requirements for assigned aircraft.			
out	3. Determine from AOC flight director/meteorologist whether aircraft has operational fix responsibility and the mission designation.			
048	 4. Contact HRD members of crew to: a. Assure availability for mission. b. Review field program safety checklist c. Arrange ground transportation schedule when deployed. d. Determine equipment status. 			
The	5. Meet with AOC flight director and navigator at least 3 hours before take-off for initial briefing.			
- Jas	6. Meet with AOC flight crew at least 2 hours before take-off for crew briefing. Provide copies of flight requirements and provide a formal briefing for the flight director, navigator, and pilots.			
THEY	7. Report status of aircraft, systems, necessary on-board supplies and crews to MGOC in Miami.			
703	8. Before take-off, brief the on-board GPS dropsonde operator on times and positions of drop times.			
Red	Make sure each HRD flight crew member has a life vest.			
-963	10. Perform a headset operation check with all HRD flight crew members. Make sure everyone can hear and speak using the headset. The of start of flight the large surfelies.			
In Flig	ht			
3868	1. Confirm from AOC flight director that satellite data link is operative (information).			
(2. Confirm camera mode of operation.			
	3. Confirm data recording rate.			
Say	4. Complete Lead Project Scientist Form.			
Day	Check in with the flight director to make sure the mission is going as planned (i.e. turns are made when they are supposed to be made).			
Post fli	ght			
No 8	1. Debrief scientific crew.			
608	2. Gather completed forms for mission and turn in to data manager at HRD.			
Do	3. Obtain a copy of the 10-s flight listing from the AOC flight director. Turn in with completed forms.			
Der	4. Obtain a copy of the radar DAT tapes. Turn in with completed forms.			
800	5. Obtain a copy of serial flight data on thumb drive. Turn in with completed forms.			
[Note: all c	lata removed from the aircraft by HRD personnel should be cleared with the AOC flight director.]			
The	6. Report landing time, aircraft, crew, and mission status along with supplies (tapes, etc.) remaining aboard the aircraft to MGOC.			
0 3	Determine next mission status, if any, and brief crews as necessary.			
0	8. Notify MGOC as to where you can be contacted and arrange for any further coordination required.			

Prepare written mission summary using Mission Summary form.

Jahrolf 07 5450

HRD Function			AOC	J.	
	Participant	Function	100000000000000000000000000000000000000	Participan	
Lead Project Scientist	Pe Loighten	Flight Directo	or Ia	n Sers / Bi	
Radar/Workstation)	Pilots	B, C	hoy Ch New	
	0111	Navigator	Giriman	el /	
Cloud Physics	P. Leyhh	Systems Engi	ineer 7	5/0gn/1	
Photographer/Observer	198	- Data Technic	1_1	ald to	
/Guests	WA	Data Technic	B	Pech/T.	
Dropwindsonde	T. 2he	Electronics T	Electronics Technician		
AXBT/AXCP	Tun Shin	Other	V	/	
3. Take-off and Landing Take-Off: 075/50UTC Landing:UTC	Location: Mac	- 11 1	3		
Number of Eye Penetration C. Past and Forecast Sto		7		in and	
Number of Eye Penetration C. Past and Forecast Sto	orm Locations:	ongitude	MSLP	Maximu Wind	
Number of Eye Penetration C. Past and Forecast Storm Date/Time	orm Locations:		MSLP		
Number of Eye Penetration C. Past and Forecast Storm Date/Time	orm Locations:	ongitude	MSLP		

Lead Project Scientist Check List

D. Mission Briefing:

Twon 3001 1234547 \$ 9 0 11 12 14

	40 phrunds
Storm or Project 75, Demy	Experiment name by her Mush
Flight ID 0908271	Mission ID WXOSA Damy2

E. —Equipment Status (Up ↑, Down ↓, Not Available N/A, Not Used O)

Equipment	Pre-Flight	In-Flight	Post-Flight	# DATs / CDs /Expendables/ Printouts	
Radar/LF	g	7	T	1	
Doppler Radar/TA	9	1	1		
Cloud Physics	9		1		
Data System	31	7	4		
GPS sondes	1 20/2	1 14	9	14	
AXBT/AXCP	1 20	1 20	7	70	
Ozone instrument	7		1	7/4/3/1	
Workstation	77	7	1		
Cameras	7	9	1	SKATE	

REMARKS:

27000

Lead Project Scientist Event Log

Date 7 Ag 69 Flight ID 096827II LPS P. Leyron

57082 2706 12.02

Time	Atorp	27.06 72.02 Position		Comments
875450	Taheoff	MAEDI	IAFB	
080300		Beens		allws pres 7
580900	Restr + Loder cap	tun		
082130	J	27 16	8056	Woot Rh Beach
083700	XBT Prop # 1			let XBT DRO
085300		. 5 day		
085400		26,81 1-		
				stin 78° Bt drop 13
90800	BT#2	76,92	26.81	No temps
91830	Rebot WS	76,03		More Not Marin
091940	12T # 3	76,00	76.87	- 8
053100	B+# 4	75,00	26,97	
94830	B+ # 5	7400	2701	28,25
5954 40	BT#6	73,00	2702	\$382 2 Stot does
	TP Combio		27,02	
0100:00				12000 St
	· ·	2721	7	
03/00	Suge only		27-211	271284 7/53 70
04620	Sude	33		
1056	Cuso	27,22	6597	
102		27,3	6916	tun 4 3/5
112500		28.55	71.	Am 4 222
114320	Sude	27.62	7161	
115520	3T/only	27 15	7238	27.8 Cerl #:
20655	Sande	2644	72,61	282
21929	Combo day	2568	727	Links 90
24720	day sne	26,97	71,90	7.1.34

27.4N 72.1W

Lead Project Scientist Event Log

Date 090827 Flight ID 090827IT LPS-P. Leight

Time	Event	Position		Comments
1251 20	Ru dan	2727	ruge	mountily
130110	Coulso	2792	7239	of Hound be
13/414	Coubo	28,66	7303	of Hand beg
				\$* · · · · · · · · · · · · · · · · · · ·
				(A) (1)
135800	lost of prop	2732		and the second s
14 1800:	Behrus	27,38	78,61	
145/30	Dith Decent	27.16 to Le	81.67	Almist home
15:10:22		27.84		mxc Dell
V	. Pais 76	21.83	82,52	
		. 100		
\$				
* /				
		St. C.	1000	