Flight ID 120824H1 Storm Isaac Radar Scientist Paul Reas of

The on-board radar scientist is responsible for data collection from all radar systems on his/her assigned aircraft. Detailed operational procedures and checklists are contained in the operator's manual. General supplementary procedures follow. (Check off or initial.)

Preflight	
1.	Determine the status of equipment and report results to the lead project scientist (LPS).
	Confirm mission and pattern selection from the LPS.
3.	Select the operational mode for radar system(s) after consultation with the LPS.
4.	Complete the appropriate preflight calibrations and check lists as specified in the radar operator's manual.
In-Flight	
1.	Operate the system(s) as specified in the operator's manual and as directed by the LPS or as required for aircraft safety as determined by the AOC flight director or aircraft commander.
	Maintain the Radar Scientist's form as well as a written commentary in the radar logbook of tape and event times, such as the start and end times of F/AST legs. Also document any equipment problems or changes in R/T, INE, or signal status.
Post flight	
1.	Complete the summary checklists and all other appropriate forms.
2.	Download all radar data files to thumb drive.
3.	Brief the LPS on equipment status and turn in completed forms and thumb drives to the LPS.
4.	Debrief at the base of operations.
5.	Determine the status of future missions and notify HFP Director as to where you can be contacted

HRD Rudar Scientist Chick List

	Flight ID: VEO	<u> </u>		n verige
	Aircraft Number:	N42		
	Radar Operators:	Paul.	Reason	
	Radar Technician:	Joe	Bosko	
	Status(Up † , Down	Shania at the Maria	ilable N/A, N	ot Used
Radar Computer	1			
Lower Fuselage a	ntenna		N.94	
Tail Antenna	1			
Time	correction between r	adar time a	nd digital tim	ė:
	Radar Pos	flight Sur	nmary	
gnificant down time				
Radar LF		÷		
Radar TA		_		
ther Problems:				
The state of the s		学得7%。开始认	X 14 1 11	6. (39)

HRD Radar Event Log

Flight ID <u>170874171</u> Aircraf Radar Scientists <u>Paul</u> <u>Re</u> a	Sheet of	
LF RPM	TA RPM	
(Include start and end times of recording as w	vell as times of F/AST legs and any	changes of radar equipment status)

Event Time Event F/AST Tape # (HHMMSS) On?

HRD Radar Problem Log

Flight ID 1708	24H)	_ Aircraft	N42	Sheet	of
			Radar Technician	Joe Bosko	

(Include times of when recording ended and was restarted)

Tape #	Time (HHMMSS)	Problem
	Company (Co.)	
	er albumann	
e se e l'entre e		

Doppler Wind parameters

	FLIGHT	TID: 12	.0824	Dopp H)	ler fligh			se in automa Scientis		d analy	rsis)			
	Leg Start Time	Leg End Time	Storm N		Time	Center Fix	x Longitude	Max Radius (km)	Horz. Res	Inbound	Outbound	ja?	Angle check?	Sent?
	HHMMSS	HHMMSS	Degrees	Knots	HHMMSS	(Deg/Min)	(Deg/Min)	49/98/147/196	1/2/3/4	track	track	H/TS	(Y/N)	(Y/N)
W	094600	102730	275	13	100900	1700	70 30	245 hm	Sum	255	255			
2	102900	102800								13				>
U	105930	112500	275	13	111200	16 00	7000	V	7	345	nla			Y
W	112530	114400	275	13	113200	1649	7056			n/a	255			
									2					
		4												
						>								
				V		W 1921								

Note: Use every other line to indicate start and end time of downwind leg

