Lead Project Scientist

		Project 113 K ARL Experiment name NAP X
		20160922 II Mission ID WF12A KARL
Prefli	ght	
	1.	Participate in general mission briefing.
	2.	Determine specific mission and flight requirements for assigned aircraft.
	3.	Determine from AOC flight director/meteorologist whether aircraft has operational fix responsibility and the mission designation.
	4.	Contact HRD members of crew to: a. Assure availability for mission. b. Review field program safety checklist c. Arrange ground transportation schedule when deployed. d. Determine equipment status.
	5.	Meet with AOC flight director and navigator at least 3 hours before take-off for initial briefing.
	6.	Meet with AOC flight crew at least 2 hours before take-off for crew briefing. Provide copies of flight requirements and provide a formal briefing for the flight director, navigator, and pilots.
	7.	Report status of aircraft, systems, necessary on-board supplies and crews to MGOC in Miami.
	8.	Before take-off, brief the on-board GPS dropsonde operator on times and positions of drop times.
×	9.	Make sure each HRD flight crew member has a life vest,
	10.	Perform a headset operation check with all HRD flight crew members. Make sure everyone can hear and speak using the headset.
In-Fli	ght	
	1.	Confirm from AOC flight director that satellite data link is operative (information).
	2.	Confirm camera mode of operation.
	3.	Confirm data recording rate.
	4.	Complete Lead Project Scientist Form.
	5.	Check in with the flight director to make sure the mission is going as planned (i.e. turns are made when they are supposed to be made).
Post f	light	
	1.	Debrief scientific crew.
······································	2.	Gather completed forms for mission and turn in to data manager at HRD.
	3.	Obtain a copy of the 10-s flight listing from the AOC flight director. Turn in with completed forms.
	4.	Obtain a copy of the radar DAT tapes. Turn in with completed forms.
	5.	Obtain a copy of serial flight data on thumb drive. Turn in with completed forms.
Note: all	l data r	emoved from the aircraft by HRD personnel should be cleared with the AOC flight director.]
	6.	Report landing time, aircraft, crew, and mission status along with supplies (tapes, etc.) remaining aboard the aircraft to MGOC.
	7.	Determine next mission status, if any, and brief crews as necessary.
-	8.	Notify MGOC as to where you can be contacted and arrange for any further coordination required.
	9.	Prepare written mission summary using Mission Summary form.

Lead Project Scientist Check List

Storm or Project KARL	Experiment name RAPX
Flight ID 20160922 II	Mission ID WF12A KARL

A. Participants:

HR	D	AOC		
Function	Participant	Function	Participant	
Lead Project Scientist	BUCCI	Flight Director	SEARS/BELSON	
Radar/Workstation	KLOTZ .	Pilots	PRICE KAHN, REES	
Cloud Physics		Navigator Systems Engineer Data Technician	SIEGEL HEYSTEK NAEHER	
Dropwindsonde	CHRISTOPH ERSEN	Electronics Technician	PEEK, HORTBERGE	
AXBT/AXCP Photographer/Observer s/Guests		Other	SAPP	

B. Take-off and Landing Times and Location	u Locations	and 1	1 imes	Landing	L	and	3-OII	1 ake	ь.
--	-------------	-------	--------	---------	---	-----	-------	-------	----

Take-Off: 1731	_UTC	Location:	STX	
Landing: <u>0037</u>	_UTC	Location:	STX	

Number of Eye Penetrations:

C. Past and Forecast Storm Locations:

Date/Time	Latitude	Longitude	MSLP	Maximum Wind

D. Mission Briefing:

TD Karl is at 30 kts, 400 miles north of St. Croix moving NW at 17 Kts. It is embedded in a region of 25-15 kts of SE shear (higher shear on the west side). The plane is for a rotated figure-4, ourpping sondes at mids and diagonal end pts. no AxBts or 18 sondes. Fly 8000 ft radar altitude w/ 90 nm legs

Mission Summary Storm name YYMMDDA# Aircraft 43RF

Scientific Crew (43RF)
Lead Project Scientist Bucci
Radar Scientist <u>klotZ</u>
Cloud Physics Scientist
Dropwindsonde Scientist CHRISTOPHERSEN
Boundary-Layer Scientist
Workstation Scientist
Observers (affiliation)
,

Mission Briefing: (include sketch of proposed flight track or page #)

Mission Synopsis: (include plot of actual flight track)

Completed pattern up until the N-S pass and ended early of the equipment smoking. Propped a center sunde on 1st and 3rd pass to find a pressure decrease of 4-5 mb. Dry air in the sound W with convection to the N and E, Max winds 36 kts at Surface, so kts on FL Evaluation: (did the experiment meet the proposed objectives?)

storm appears to be deepening as the SE shear decreases, was not alse to sample convection to the east side due to the incomplete pattern. Based on radar composites, the 2 km and 5 km vortecies appear to be aligning.

Problems: (list all problems)

Acc server was up & down, Brad had to process radar on plane cooling fan fried and arched around N enapoint

Expendables used in mission:	
GPS sondes : AXBTs :	
Sonobuoys:	

Lead Project Scientist Event Log

Date 26 16 - 9 - 22 Flight ID 2018 092217 LPS BUCCI

Time	Event	Position	Comments
1731	takeoff	STX	early!
1912	drop 1	SE endpt	clear cirrus above
1922	drop2	SE midpt	230° 19 lets
1946	arop3	25°46' 63°10'	Center 345° 2kts 10
1958	drop 4	NW midpt	Stratiform rain 30
2010	anops	NW enapt	40° 22Kts
2039	droplo	sw endp+	n 55-70°/. to 3000+1 >de
			355° 1915
2050	drop 7	SW midpt	330° 18 1cts
2107	fix	center	2615'63°24'
2120	drop 8	NE midpt	125° 25 Kts
શારૂ ડ	drop 9	NE end pt	105 nm lea - extend from
ଥିବ ଓ ।	aropio	N midpt	30° 29 km
2247	drop 11	26°06 63°29'	center 35° 24 kts
<i>ୡ</i> ୭	drop 12	smidpt	
23001		Send pt	
0037	landed	STX	
1			

90 nm