

NOAA Aircraft Operations Center - NOAA 43 Flight Manifest

FLIGHT INFORMATION				CREW MANIFEST			MISSION INFORMATION				
FLT ID:	2016092911	FLT #:		AC:	Kerns	Scientists:	Pressure		Dropsondes		
From:	KMCF	ETD:	1600Z	CP(s):	Martin	Paul Chang	A/C Takeoff		Good	Bad	Sent
To:	TISX	ETA:	2100Z		Kahn	Zorona Jelenak			0		
Block Time		Flight Time		Nav(s):	Gallagher	Joe Sapp	Wx Station Takeoff		BTs		
In:	2119	In:	2116		Freeman				Good	Bad	Sent
Out:	1705	Out:	1716	FE(s)	Darby		A/C Land		0		
Total:	4.2	Total:	4.0		LaLonde						
Sponsoring Org:	HRD	Program:	PHX	FD(s):	Parrish	Visitors:	Wx Station Land				
	Purpose:		Repo		Williams						
SEB:	HRD	SSA:	PHX	Kregelka					Storm Number ID:		
				Peek						(ie: AL072012)	
AVAPS:	Repo		PHX	Naeher					TCPOD/WSPOD Mission		
				Olney						(ie: NOAA2 2418A SANDY) WXWXA TRAIN	
AS REQUIRED BY ORM				Y	N	REMARKS	Fix Number	Obs Number	Fix Time	SLP	
VOLCANIC ASH					X						
SCIENCE MISSION WITHIN BDRY LAYER					X						
LACK OF PRECIPITATION					X						
RELATIVE HUMIDITY ≥ 80%					x						
LARGE AIR-SEA TEMP GRADIENT					X						
HIGH SURFACE WINDS					x						
LONG FETCH / DURATION OF SFC WND					X						
SEA SALT ACCRETION FORECAST					X						
SEA SALT ACCRETION OBSERVED											
Additional Remarks:						*Highlighted items must be completed before departure.					
Cockpit Gmax:		1.05		Gmin:		0.95					
AccZref/9.86 + 1:		0.61				1.35					