

NOAA Aircraft Operations Center - NOAA 49 Flight Manifest

FLIGHT INFORMATION				CREW MANIFEST				MISSION INFORMATION				
FLT ID:	20180823N1	FLT #:		AC:	Twining	Scientists:		Pressure		Dropsondes		
From:	PHNL	ETD:		CP(s):	Waddington			A/C Takeoff		Good	Bad	Sent
To:	KLGB	ETA:			Sims							
Block Time		Flight Time		Nav(s):				Wx Station Takeoff		BTs		
In:	2146	In:	2141	FE(s)				A/C Land		Good	Bad	Sent
Out:	1633	Out:	1650	FD(s):	Sears			Wx Station Land				
Total:		Total:			Flaherty			Visitors:				
Sponsoring Org:				SEB:	Hartberger	Rotteveel		Storm Number ID:				
Program:					Smith			(ie: AL072012)				
Purpose:				SSA:	Defeo			TCPOD/WSPOD Mission				
				AVAPS:	Miller			(ie: NOAA2 2418A SANDY)				
AS REQUIRED BY ORM				Y	N	REMARKS		Fix Number	Obs Number	Fix Time	SLP	
VOLCANIC ASH					X							
SCIENCE MISSION WITHIN BDRY LAYER					X							
LACK OF PRECIPITATION					X							
RELATIVE HUMIDITY ≥ 80%					X							
LARGE AIR-SEA TEMP GRADIENT					X							
HIGH SURFACE WINDS					X							
LONG FETCH / DURATION OF SFC WND					X							
SEA SALT ACCRETION FORECAST					X							
SEA SALT ACCRETION OBSERVED												
Additional Remarks:								*Highlighted items must be completed before departure.				
Cockpit Gmax:				Gmin:								

Phone #: 863.500.3986

ACAT-4 Version = 7.1

APPENDIX 2 – GIV QC Checklist

Flight ID:	20180823N1
Flight Director(s):	Sears

Pressure Comparison		
	T/O	Land
Aircraft	1012.2	1012.8
Tower	1012.1	1012.1

UWZ.d mean: 0.09


	Raw 1Hz Mean File Parameters				C File Parameters	
<input checked="" type="checkbox"/> Accelerometer	AccAXI.1	AccAYI.1	AccAZI.1		AccZref	
	AccAXI.2	AccAYI.2	AccAZI.2			
	AccAXI.3	AccAYI.3	AccAZI.3			
<input checked="" type="checkbox"/> Altitude	AltGPS.1	AltI.1	AltPaADDU.1	AltBCADDU.1	ALTref	
	AltGPS.2	AltI.2	AltPaADDU.2	AltBCADDU.2	ALTPA.d	
	AltGPS.3	AltI.3	AltRA.1		ALTGA.d	
<input checked="" type="checkbox"/> Ground Speed	GsXI-GPS.1	GsXI.1	GsGPS.1	GsXGPS.1	GSXref	
	GsXI-GPS.2	GsXI.2	GsGPS.2	GsXGPS.2	GSYref	
	GsYI-GPS.1	GsXI.3		GsYGPS.1	GSZref	
	GsYI-GPS.2	GsYI.1	GsZI.1	GsYGPS.2		
	GsZI-GPS.1	GsYI.2	GsZI.2	GsZGPS.1		
	GsZI-GPS.2	GsYI.3	GsZI.3	GsZGPS.2		
<input checked="" type="checkbox"/> Lat/Lon	LatGPS.1	LatI.1	LonGPS.1	LonI.1	LATref	
	LatGPS.2	LatI.2	LonGPS.2	LonI.2	LONref	
	LatGPS.3		LonGPS.3			
<input checked="" type="checkbox"/> Pressure	PDALPHA.1	PQALPHA.1	PQM.1	PSM.1	PDALPHAref	PQMref
	PDALPHA.2	PQALPHA.2	PQM.2	PSM.2	PDBETAref	PQ.c
	PDBETA.1	PQBETA.1	PQM.11	PSM.11	PQALPHAref	PSMref
	PDBETA.2	PQBETA.2			PQBETAref	PS.c
<input checked="" type="checkbox"/> Air Speed	CasADDU.1	TasADDU.1	IasADDU.1		IAS.d	TAS.d
<input checked="" type="checkbox"/> Pitch/Roll	PitchI.1	PitchRateI.1	RollI.1	RollRateI.1	PITCHref	
	PitchI.2	PitchRateI.2	RollI.2	RollRateI.2	ROLLref	
	PitchI.3	PitchRateI.3	RollI.3	RollRateI.3		
<input checked="" type="checkbox"/> Temp/Dewpt	TTM.1	TTM.11	TDM.1		TD.c	TTMref
	TTM.2	TTM.13	TDM.2		TDMref	TA.d
	TTM.3	TTM.4	TDM.11			
<input checked="" type="checkbox"/> Miscellaneous (must check)					UWZ.d	WS.d
					DPJ_WSZ	WD.d
					HUM	

Mission Documents:

<input checked="" type="checkbox"/>	Error Summary
<input checked="" type="checkbox"/>	Crew Manifest
<input checked="" type="checkbox"/>	QC checklist
<input checked="" type="checkbox"/>	Dropwindsonde Log(s) – AVAPS and FD if completed
<input checked="" type="checkbox"/>	Miscellaneous FD notes

NOTES:

2018-08-23, 16:17:27-21:47:02



	mean	sigma	min	max
— LatI.1 (deg), 1 s/sec	27.18	4.33	21.19	33.86
— LonI.1 (deg), 1 s/sec	-139.78	13.13	-157.94	-117.96