



Sea-Bird Scientific
13431 NE 20th Street
Bellevue, WA 98005
USA

+1 425-643-9866
seabird@seabird.com
www.seabird.com

SENSOR SERIAL NUMBER: 4346
CALIBRATION DATE: 09-Dec-20

SBE 4 CONDUCTIVITY CALIBRATION DATA
PSS 1978: C(35,15,0) = 4.2914 Siemens/meter

COEFFICIENTS:

g = -9.89079153e+000
h = 1.29411821e+000
i = -2.49191220e-003
j = 2.50384772e-004

CPcor = -9.5700e-008 (nominal)
CTcor = 3.2500e-006 (nominal)

BATH TEMP (° C)	BATH SAL (PSU)	BATH COND (S/m)	INSTRUMENT OUTPUT (kHz)	INSTRUMENT COND (S/m)	RESIDUAL (S/m)
0.0000	0.0000	0.00000	2.76991	0.00000	0.00000
-1.0001	34.6007	2.78881	5.41592	2.78882	0.00001
1.0000	34.6011	2.95932	5.53673	2.95931	-0.00001
15.0000	34.6000	4.24788	6.37561	4.24789	0.00001
18.5000	34.5990	4.59264	6.58174	4.59262	-0.00002
29.0000	34.5917	5.66966	7.18727	5.66968	0.00002
32.5000	34.5790	6.03927	7.38342	6.03926	-0.00001

f = Instrument Output (kHz)

t = temperature (°C); p = pressure (decibars); δ = CTcor; ϵ = CPcor;

Conductivity (S/m) = $(g + h * f^2 + i * f^3 + j * f^4) / 10 (1 + \delta * t + \epsilon * p)$

Residual (Siemens/meter) = instrument conductivity - bath conductivity

