

RADAR PREFLIGHT CHECKLIST

SEP 11 1981

FLIGHT # 8109 11 I

A.C. # 43RF

OPERATOR LORD

RADAR TECH BURLISS

NUMBER OF DIGITAL MAGNETIC TAPES ONBOARD 17

NUMBER OF VIDEO TAPES ONBOARD 4

NUMBER OF TAPE LABELS ON BOARD 710<sup>6</sup>

COMPONENT SYSTEMS UP AND CHECKED.

RDSC \_\_\_\_\_  
COMPUTER \_\_\_\_\_  
DMTR1 \_\_\_\_\_  
DMTR2 \_\_\_\_\_

VTR \_\_\_\_\_  
DSC1 \_\_\_\_\_  
DSC2 \_\_\_\_\_  
SCOPES \_\_\_\_\_

NO   
LF down  
TA down

Time correction between radar time and digital time 0

RADAR POSTFLIGHT SUMMARY

NUMBER OF DIGITAL TAPES USED DMTR 1 1  
DMTR 2 1

NUMBER OF VIDEO TAPES USED 2

SIGNIFICANT RECORDER DOWN TIME (other than for tape changes).

DMTR: LF NONE  
NO \_\_\_\_\_  
TA \_\_\_\_\_

VTR: LF NONE  
NO \_\_\_\_\_  
TA \_\_\_\_\_

OTHER PROBLEMS: (stabilization, interference, etc.)



# NHEML RADAR LOG

OPERATOR GRIFIN WIGGAT

SHEET 1 OF 1

## RADAR DOWN-TIME LOG

<u>ITEM</u>	<u>TIME DOWN</u>	<u>TIME UP</u>	<u>PROBLEM</u>
			<p>Interference possible                      ~ 1230Z on both radars                      (from sister ship?)</p> <p>"                      DATA" indicator lamp                      on DMTR 2 <u>not</u>                      flashing as of ~ 1700Z</p>

ITEM LIST: VTR, DMTR1, DMTR2, COMP, ROSC, LF, NO, TA, DSCI, DSC2