

RADAR PREFLIGHT CHECKLIST

NOV 06 1981

FLIGHT # 8110541

A.C. # 42

OPERATOR Stan Foderberg

RADAR TECH Frank Revitte

NUMBER OF DIGITAL MAGNETIC TAPES ONBOARD _____

NUMBER OF VIDEO TAPES ONBOARD 4

NUMBER OF TAPE LABELS ON BOARD ~36

COMPONENT SYSTEMS UP AND CHECKED.

RDSC _____
COMPUTER _____
DMTR1 _____
DMTR2 _____

VTR _____
DSC1 _____
DSC2 _____
SCOPES _____

NO _____
LF _____
TA _____

Time correction between radar time and digital time ✓

RADAR POSTFLIGHT SUMMARY

NUMBER OF DIGITAL TAPES USED DMTR 1 3
DMTR 2 3

NUMBER OF VIDEO TAPES USED 1

SIGNIFICANT RECORDER DOWN TIME (other than for tape changes).

DMTR: LF _____
NO _____
TA _____

VTR: LF _____
NO _____
TA _____

OTHER PROBLEMS: (stabilization, interference, etc.)

11/5/81

- G Katrina -

RF 42 Log

- Radar operator Stan Goldsberg -

tape 1 - 2346 - PA, PA-464, 520
20.78 N, 80.0 W

2349 - Cursor 1

- 0015 - Channel pass

~~380~~
CHANNEL PASSES

Time Counter

CP 2346 ~ 000

CP 0015 380

(through levels 1-5 at 0035) (~570)

CP 0042 642

CP 0117 910

[0134 - 1004] Good level 4 to the WNW)

[0142 - Tail Radar, 1090

CP 0147 - 1121)

CP 0216 - 1304 (some tail)

[0220 - Comp. Down - (ie no radar on scope)
Video ~~to~~ Tapes paused]

0223 - Comp. tape stopped

Flight 811105H1

(2)

Backup - (Vibe & Comp.) at 0230

Stopped - (02432) Both Vibe & Comp

(Because of AC failure -

all comp. shut down before

3E fix) —

Reserved at

0351Z (Book tapes)

(AT 5000ft)

CP 0351 1410

CP 0432 1628

EOT - #1729 at 0500Z

~~Open tape at~~

~~0503~~

0534 - down again to 1500⁰ft

Going Home

(0555)