

RADAR PREFLIGHT CHECKLIST

NOV 6 1981

FLIGHT # 1811106 I - RADARA.C. # 43RFOPERATOR PARIZISRADAR TECH JAZVINNUMBER OF DIGITAL MAGNETIC TAPES ONBOARD 7+NUMBER OF VIDEO TAPES ONBOARD 3NUMBER OF TAPE LABELS ON BOARD 20+

COMPONENT SYSTEMS UP AND CHECKED.

RDSC ✓
COMPUTER ✓
DMTR1 ✓
DMTR2 ✓VTR ✓
DSC1 ✓
DSC2 ✓
SCOPES ✓NO ✓
LF ✓
TA ✓Time correction between radar time and digital time +1 secRADAR POSTFLIGHT SUMMARYNUMBER OF DIGITAL TAPES USED DMTR 1 2
DMTR 2 2NUMBER OF VIDEO TAPES USED 2

SIGNIFICANT RECORDER DOWN TIME (other than for tape changes).

DMTR: LF _____
NO _____
TA _____VTR: LF _____
NO _____
TA _____

OTHER PROBLEMS: (stabilization, interference, etc.)

SHORT IN VCR CABLE CAUSES INTERMITTENT RETURN

NOV 6 1981

AIRCRAFT 431ZF

OPERATOR *ARRISIT*

SHEET / OF

[illegible]

NOV 6 1981

NHEML RADAR LOG

OPERATOR PAZISHSHEET 1 OF

RADAR DOWN-TIME LOG

<u>ITEM</u>	<u>TIME DOWN</u>	<u>TIME UP</u>	<u>PROBLEM</u>
LF RADAR	TAKEOFF		REBUILT ANT. MOTOR - IS BEING KEPT IN RESERVE
* LF	131000		ATTEMPTED TO START UP LF - ANTENNA MOTOR WORKS, BUT GETTING LITTLE RETURN - SHUT DOWN AT 1318

ITEM LIST: VTR, DMTRI, DMTR2, COMP, ROSC, LF, NO, TA, DSCI, DSC2