

19840801H1-RADAR

540801 H TRAINING & CALIBRATION
TAKE OFF 11:35 Z
LF RADAR ON 11:40 Z NO RECORDING
TA " " 11:43 "
INPUT THRESHOLD 5/12/18/22/25/28
11:47 Z RADARS OFF "

1451 step thru for VCR (for memory scan)
1539 " (924)
No tape data saved
VCR off ~ 1600

August 1 1984 day 214

1130GMT

Intercompany by OAC of P3's.

Arbair ~~type~~ @ USD

Later Tape drive activated 1521 Z

VTR @ 1615 ; began step thru

step thru @ 1625

" " @ 1645

Radars off @ ~1648

Landing @ MEA ~1700GMT