## Radar Scientist

Flight ID	110826#1	Storm Name	Hurr-	IRENG
Radar Scien	tist LORSOCO	Radar Technicia	an	SKO
on his/her ass	oard radar scientist is responsi signed aircraft. Detailed operat or's manual. General supplemen	ional procedures	and checkli	sts are contained
Preflight				
1.	Determine the status of equipm (LPS).	ent and report res	ults to the lea	d project scientist
	Confirm mission and pattern sele	ection from the LP	S.	
2. 3. 4.	Select the operational mode for i	radar system(s) afte	er consultation	with the LPS.
4.	Complete the appropriate preflication radar operator's manual.	ght calibrations an	d check lists	as specified in the
In-Flight				
1.	Remind the AOC data technician	n to start the radar o	capture files.	
2.	Operate the system(s) as specifical LPS or as required for aircraft saircraft commander.			
3.	Maintain the Radar Scientist's f logbook of tape and event time Also document any equipment p	s, such as the star	t and end tim	es of F/AST legs.
Post flight				
1.	Complete the summary checklist	ts and all other app	ropriate forms	s.
2.	Obtain from the AOC data tech drive to download the radar capt		apes and give	him a thumbnail
3.	Brief the LPS on equipment st drive, and all radar tapes to the HRD personnel should be cleare	LPS. [Note: all da	ta removed fr	
4.	Debrief at the base of operations			
5.	Determine the status of future montacted.	nissions and notify	MGOC as to	where you can be

## HRD Radar Scientist Check List

Flight ID: 110826 H/

Rada	scientist r Operators: _	LOR	5010	Roman Schenika
Rada	r Technician:	Bo.	SKO	1005410
Num	ber of DAT ta	pes on board	l:	
Component Systems	Status(Up †, I	Down ↓, Not	Available N/A,	Not Used O):
Device	Pre-flight	In-flight	Post-flight	R/T Serial #
Radar Computer				)
DAT drives				
Lower Fuselage antenna				
Tail Antenna				
		st flight Sun	d digital time: _	
Number of DAT tapes used	d:			
Significant down time:				
Radar Computer _		Rac	lar LF	
DAT drives		Rac	dar TA	
Other Problems:	Control draw			
We had t	· reset	- the	TH AGE	a few time
but no	major	1	Roblem	S.

66

## **HRD Radar Event Log**

Flight ID (1) Radar Scientist				IRE NO		Sheet 1	of 2
	LF RPM	10	TA R	PM	10		

(Include start and end times of recording as well as times of F/AST legs and any changes of radar equipment status)

Tape #	F/AST On?	Event Time (HHMMSS)	Event
	V		
		1957-00	Take-off
		2005	Start recording rudar data.
			Pass #1.
		210500	Shart Time of penetraro
			Pass #1: Shart Time of pevetrare (ab 30° 17° Cong. 77, 21
		2179	Center Pocition.
			Storm motion 360, 12
			lat 31 45 long 77 15"
		2201	End of penetration
		2301	End of downwind
			Page # Z
*		2301	Start.
		1330	Conta possicia
			motion: 025 10 kg
		0.053	lat 22° 03 lang 77° 05
		2333	End penetration
		2418	Fred of Darnwind

## **HRD Radar Problem Log**

ght ID dar Scier	ntist St	orm Name Sheet or						
(Include times of when recording ended and was restarted)								
Таре #	Time (HHMMSS)	Problem						
	373	Pas # 3						
	24 17	OT - L						
	2447	Center position						
		Center position lat: 32° 17' lag: 77°						
	2011	8. 1 ° 1' ' h						
	2) 19	End penelisation						
	2538	Stop recording						
	2621	Landing						
	1							

**Doppler Wind parameters** 

Doppler flight-leg notes (for use in automatic QC and analysis)  FLIGHT ID: 110926 H1 Scientist: LORSOLO													
Leg Start Time	Leg End Time	Storm I		Time	Center Fix	Longitude	Max Radius (km)	Horz. Res (km)	Inbound track	Outbound track	ja?	Angle check?	Sent?
HHMMSS	HHMMSS	Degrees	Knots	HHMMSS	(Deg/Min)	(Deg/Min)	49/98/147/196	1/2/3/4	Azimuth (deg)	Azimuth (deg)	H/TS	(Y/N)	(Y/N)
2105	201	360	17	2129	31°45	77 15	245	5	359	0	F	N	Y
1201	35/16	15	0	2330	32°02′		145	5	117	150	Jo	$\sim$	7
2418	1514	17	11	2447	32° 17	77°0'	245	4	244	239	Ja	$\sim$	