

NOAA Aircraft Operations Center - NOAA 43 Flight Manifest

FLIGHT INFORMATION				CREW MANIFEST				MISSION INFORMATION			
FLT ID:	2016101911	FLT #:		AC:	Kerns	Scientists:		Pressure		Dropsondes	
From:	KPIE	ETD:	1500Z	CP(s):	Martin Rees			A/C Takeoff	Good	Bad	Sent
To:	KPIE	ETA:	2300Z	Nav(s):	Gallagher Freeman			Wx Station Takeoff			
Block Time			Flight Time		Visitors:				BTs		
In:		In:		Darby Heystek				A/C Land	Good	Bad	Sent
Out:		Out:		Sears Williams				Wx Station Land			
Total:		Total:		Flaherty Obs: Patel, Ashkar				Storm Number ID: (ie: AL072012)			
Sponsoring Org:	NHC	SEB:		Obs: Naeher Richards				TCPOD/WSPOD Mission (ie: NOAA2 2418A SANDY) 01GGA INVEST			
Program:	PRX	SSA:		AVAPS: Wernecke				OBSERVATIONS			
Purpose:	AL 99	AS REQUIRED BY ORM		REMARKS							
		Y	N								
	VOLCANIC ASH		X								
	SCIENCE MISSION WITHIN BDRY LAYER		X								
	LACK OF PRECIPITATION		X								
	RELATIVE HUMIDITY ≥ 80%		X								
	LARGE AIR-SEA TEMP GRADIENT		X								
	HIGH SURFACE WINDS		X								
	LONG FETCH / DURATION OF SFC WND		X								
	SEA SALT ACCRETION FORECAST		X								
	SEA SALT ACCRETION OBSERVED		X								
Additional Remarks:				*Highlighted items must be completed before departure.							
Cockpit Gmax:											

Gmin: