N42RF ERROR SUMMARY 20230918H1

Flight ID: 20230918H1

Sensor or System	Number or Name
Static Pressure Probe	PSM.2
Dynamic Pressure Probe	PQM.2
Total Temperature Probe	TTM.1
Dewpoint Temp. Probe	TDM.2
Vertical Accelerometer	AccZfilterI-GPS.1
Altimeter	AltGPS.3
INE Selection	1
Differential Attack Pressure Probe	PDALPHA.1
Differential Sideslip Pressure Probe	PDBETA.1
Dynamic Attack Pressure Probe	PQALPHA.1
Dynamic Sideslip Pressure Probe	PQBETA.1

Flight Directory

acdata/2023/MET/20230918H1

Local	Met Data	Takeoff	KLAL	(1627Z)	Landing	TXKF	(1925Z)
	Dynamic Correction	ons			Y€	s	
	AttackAngleInter	cept			2.	305	
	AttackAngleSlope				6.	07576	
	SlipAngleInterce	ot			0.	235	
	SlipAngleSlope				7.	01112	
	AttackAngleInter	cept2			2.	06219	
	AttackAngleSlope2	2			5.99068		
	SlipAngleInterce	ot2			0.	125	
	SlipAngleSlope2				6.	9873	

Notes:

There were no edits made in the measured parameters used to calculate meteorological and navigational parameters.

Takeoff/Landing data: Data during landing and takeoff are potentially suspect. It is recommended that ground data not be used for scientific analysis.

I.3 for Pitch and Roll is not operational

TTM.3 is not operational

TRadU.1 is not operational

TDM.1 deviates from TDM.2 several degrees at times throughout the transit with some erroneous spikes higher and lower than TDM.2

TDM.2 is the better (consistently) behaving sensor and TDMref is set to TDM.2; TDM.1 should not be used; TDM.3 has erroneous data throughout the flight and should not be used

PDALPHAref, PDBETAref, PQALPHAref, PQBETAref, and DPJ_WSZ are not provided since _AC file is not produced; all other 'C' file parameters checked are from the _A file

Expendable Type	# deployed	# good	<pre># transmitted</pre>

Dropsondes	0	0	0
Test sondes	0	0	0
AXBTs	0	0	0
AXCPs	0	0	0
AXCTDs	0	0	0
UAS	0	0	0

Flight Director: Zawislak / Parrish Phone #: 305-707-4359

ACAT-4 Version = 7.4

U.S. Department of Commerce / NOAA / OMAO / Aircraft Operations Center - N42RF Manifest FLIGHT INFORMATION **CREW MANIFEST** MISSION INFORMATION FY23-20230918H1 FLT ID: FLT #: AC: Abitbol Scientists: Pressure **Dropsondes** KLAL ETD: 1200L / 1600Z Paul Chang (NESDIS) Good From: Doremus Bad Sent 1008.7 CP(s): A/C Takeoff 1600L / 1900Z Zorana Jelenak (NESDIS) **TXKF** To: ETA: Gaston 0 0 0 Utama / Schaefer Joe Sapp (NESDIS) **Block Time** Flight Time NAV: 1008.7 **ASOS Takeoff** Gee BTs 16:12 16:27 Out: T/0: FE(s): Wysinger Good Bad Sent A/C Land Zawislak 19:31 19:26 FD(s): Land: ln: 0 0 0 Parrish **ASOS** Land 1015.7 McAlister Visitors: SSA: 3.3 3.0 Total: Total: Waggoner Storm Number ID: AVAPS: N/A HX - NESDIS Flaherty (PM) Sponsoring Org: (ie: AL072012) PND Kerns (CO) TCPOD/WSPOD Mission Program: SEB: **NOAA2 WXWXA TRAIN** (ie: NOAA2 2418A SANDY) Repo KLAL to Bermuda Purpose: MX: **OBSERVATIONS** Kregelka / Decker YN AS REQUIRED BY ORM **REMARKS** Fix Number Obs Number Fix Time SLP **VOLCANIC ASH** Χ 1 SCIENCE MISSION WITHIN BDRY LAYER LACK OF PRECIPITATION 2 RELATIVE HUMIDITY ≥ 80% Χ LARGE AIR-SEA TEMP GRADIENT Χ 3 HIGH SURFACE WINDS Χ LONG FETCH / DURATION OF SFC WND 4 SEA SALT ACCRETION FORECAST SEA SALT ACCRETION OBSERVED Pennies: *Highlighted items must be completed before departure.

*Highlighted items must be completed before departure.

Remarks:

P-3 QC Checklist

Overall Assessment	Minor instrument issue(s) - no mission impact.
Uveraii Assessment	MINOT INSTRUMENT ISSUE(S) - NO MISSION IMPACT.

Flight ID:	20230918H1	
Flight Director(s):	Zawislak / Parrish	
Mission:	Ferry	
UWZ.d mean:	0.15	

Pressure Comparison			
T/O Land			
Aircraft	1008.7	No good measurement	
Tower	1008.7	1015.7	

		Raw 1Hz M	ean File Parameters	C File Parameters
Accelerometer	AccAXI.1	AccAYI.1	AccAZI.1 AccZfilter-GPS.1	✓ AccZref
	AccAXI.2	AccAYI.2	AccAZI.2 AccZfilter-GPS.2	
	AccAXI-GPS.1	AccAYI-GPS.1	AccAZI-GPS.1	
	AccAXI-GPS.2	AccAYI-GPS.2	AccAZI-GPS.2	
✓ Altitude	✓ AltGPS.1	Alti-GPS.1	AltPaADDU.1 AltRA.1	✓ ALTref ✓ AltRA1.c
	AltGPS.2	Alti-GPS.2	AltRA.2	ALTPA.d AltRA2.c
	AltGPS.3			ALTGA.d
	AltGPS.4			
Ground Speed	GsXI-GPS.1	GsYI-GPS.1	GsZI-GPS.1	GSXref
	GsXI-GPS.2	GsYI-GPS.2	GsZI-GPS.2	GSYref
				GSZref GSZref
✓ Lat / Lon	✓ LatGPS.1	Lati-GPS.1	LonGPS.1 LonI-GPS.1	✓ LATref
	LatGPS.2	Lati-GPS.2	LonGPS.2 Lonl-GPS.2	LONref
	LatGPS.3		LonGPS.3	
	LatGPS.4		LonGPS.4	
✓ Pressure	PDALPHA.1	PQALPHA.1	PQM.1 PSM.1	X PDLAPHAref PQMref
	PDALPHA.2	PQBETA.1	PQM.2 PSM.2	X PDBETAref PQ.c
	PDBETA.1		PQM.3 PTM.1	X PQALPHAref PSMref
	PDBETA.2		PQM.4	X PQBETAref PS.c
✓ Air Speed	CasADDU.1	▼ TasADDU.1	✓ lasADDU.1	✓ IAS.d ✓ TAS.d
Pitch / Roll	Pitchl.1	PitchRatel.1	RollI.1 RollRatel.1	PITCHref
	Pitchl.2	PitchRatel.2	Rolll.2 RollRatel.2	ROLLref
	X Pitchl.3	X PitchRatel.3	X Rolli.3 X RollRatel.3	
✓ Temp / Dewpt	TTM.1	X TDM.1	TRadD.1	▼ TD.c ▼ TTMref
	TTM.2	TDM.2	TRadS.1	TDMref TA.d
	X TTM.3	X TDM.3	X TRadU.1	
Misc. (Must check)		-		✓ UWZ.d ✓ WS.d
				X DPJ_WSZ WD.d
				HUM

FLID_Mission_Documents.pdf:					
>	Error Summary				
>	Crew Manifest				
>	QC Checklist				
Х	Dropwindsonde Log(s) - AVAPS and FD if completed				
>	Flight Track				
>	Miscellaneous FD Notes				

QC Key	
Not checked	
/alid	\checkmark
Errors (note)	Х

NOTES:

I.3 for Pitch and Roll is not operational

TTM.3 is not operational

TRadU.1 is not operational

TDM.1 deviates from TDM.2 several degrees at times throughout the transit with some erroneous spikes higher and lower than TDM.2

TDM.2 is the better (consistently) behaving sensor and TDMref is set to TDM.2; TDM.1 should not be used; TDM.3 has erroneous data throughout the flight and should not be used PDALPHAref, PDBETAref, PQALPHAref, PQBETAref, and DPJ_WSZ are not provided since _AC file is not produced; all other 'C' file parameters checked are from the _A file



