

Sea-Bird Electronics, Inc.

13431 NE 20th Street, Bellevue, WA 98005-2010 USA

Phone: (+1) 425-643-9866 Fax (+1) 425-643-9954 Email: seabird@seabird.com

SENSOR SERIAL NUMBER: 5140
CALIBRATION DATE: 15-Aug-12

SBE3 TEMPERATURE CALIBRATION DATA
ITS-90 TEMPERATURE SCALE

ITS-90 COEFFICIENTS

g = 4.36479183e-003
h = 6.41256361e-004
i = 2.24826612e-005
j = 2.11896591e-006
f0 = 1000.0

IPTS-68 COEFFICIENTS

a = 3.68121209e-003
b = 5.99498220e-004
c = 1.54898454e-005
d = 2.12044802e-006
f0 = 3017.156

BATH TEMP (ITS-90)	INSTRUMENT FREQ (Hz)	INST TEMP (ITS-90)	RESIDUAL (ITS-90)
-1.5000	3017.156	-1.5000	0.00002
1.0000	3191.221	1.0000	-0.00002
4.5000	3446.954	4.5000	-0.00001
8.0000	3717.089	8.0000	-0.00001
11.5000	4002.015	11.5000	0.00001
15.0000	4302.112	15.0001	0.00008
18.5000	4617.721	18.4999	-0.00005
22.0000	4949.224	21.9999	-0.00006
25.5000	5296.960	25.5000	0.00004
29.0000	5661.232	29.0000	0.00002
32.5000	6042.365	32.5000	-0.00001

Temperature ITS-90 = $1/\{g + h[\ln(f_0/f)] + i[\ln^2(f_0/f)] + j[\ln^3(f_0/f)]\} - 273.15$ (°C)

Temperature IPTS-68 = $1/\{a + b[\ln(f_0/f)] + c[\ln^2(f_0/f)] + d[\ln^3(f_0/f)]\} - 273.15$ (°C)

Following the recommendation of JPOTS: T_{68} is assumed to be $1.00024 * T_{90}$ (-2 to 35 °C)

Residual = instrument temperature - bath temperature

