

Sea-Bird Electronics, Inc.

13431 NE 20th Street Bellevue, WA 98005 United States

SERVICE REPORT

Phone Fax

PO Number:

+1-425-643-9866 +1-425-643-9954 www.seabird.com

Service Request 1005508969 **Date** 01-NOV-2019 **Sales Order** 315775437

CUSTOMER INFORMATION

Name: NOAA - ATLANTIC OCEANOGRAPHIC AND METEOROLOGICAL LAB

Account: 40279759 **GRANT RAWSON**

GRANT.RAWSON@NOAA.GOV

(305) 361-4363

Bill To Address 4301 RICKENBACKER CAUSEWAY; MIAMI,FL,33149,US

Ship To Address 4301 RICKENBACKER CAUSEWAY; MIAMI,FL,33149,US

PRODUCT INFORMATION

Item: 09P.LEGACY

Item Description: (LEGACY) SBE 09Plus CTD

Serial: 09P76233-1165

Special Notes Services Requested:

Evaluate/Repair Instrumentation. Perform Routine Calibration Service.

Services Performed:

Perform initial diagnostic evaluation. Performed pressure calibration.

Replaced the O-rings.

Performed a hydrostatic pressure test.

Item	Item Description	Qty
CONCERT9A	Confirm and recertify SBE 9plus. Complete external inspection. Test all functions and input channel responses. Replace anodes if necessary. Cross-check pressure sensor (room temperature comparison to SBE reference Digiquartz giving new slope/offset coefficients.) Cost of sensor calibrations, major repairs or modifications is extra.	1

Unbilled Items

Item	Item Description	Qty



Sea-Bird Electronics, Inc.

13431 NE 20th Street Bellevue, WA 98005 United States

SERVICE REPORT

Phone Fax

+1-425-643-9866 +1-425-643-9954 www.seabird.com

Service Request Date Sales Order 1005508969 01-NOV-2019 315775437

PRODUCT INFORMATION

Item: 09P.LEGACY

Item Description: (LEGACY) SBE 09Plus CTD

Serial: 09P79223-1207

Special Notes

Services Requested:

Evaluate/Repair Instrumentation.
Perform Routine Calibration Service.

Services Performed:

Perform initial diagnostic evaluation.

Performed pressure calibration.

Replaced the O-rings.

Performed a hydrostatic pressure test.

Item	Item Description	Qty
17628	Bulkhead connector, 6-pin Standard, AG-306-HP-SS	1
CONCERT9A	Confirm and recertify SBE 9plus. Complete external inspection. Test all functions and input channel responses. Replace anodes if necessary. Cross-check pressure sensor (room temperature comparison to SBE reference Digiquartz giving new slope/offset coefficients.) Cost of sensor calibrations, major repairs or modifications is extra.	1

Unbilled Items

Item	Item Description	Qty