

Drop , ile Name, atitude, ongitude, ime, Notes

pos: 001, X150301N01.bin, 35 10.08 S, 056 21.02 W, 03/01/2015 15:04,test drop, ground conected and unconnected, you can see bad readings wile the groun wire it is disconnected.

pos: 002, X150301N02.bin, 34 54.15 S, 056 12.66 W, 03/01/2015 22:43,test probe at harbor

pos: 003, X150302N01.bin, 35 27.61 S, 052 38.87 W, 03/02/2015 13:56,

pos: 004, X150302N02.bin, 35 33.56 S, 052 23.98 W, 03/02/2015 14:53,

pos: 005, X150302N03.bin, 35 33.96 S, 052 22.86 W, 03/02/2015 14:57,

pos: 006, X150302N04.bin, 35 39.41 S, 052 07.92 W, 03/02/2015 15:54,

pos: 007, X150302N05.bin, 35 43.96 S, 051 52.77 W, 03/02/2015 16:51,

pos: 008, X150302N06.bin, 35 48.26 S, 051 37.03 W, 03/02/2015 17:47,

pos: 009, X150302N07.bin, 35 53.13 S, 051 21.78 W, 03/02/2015 18:32,

pos: 010, X150302N08.bin, 35 58.56 S, 051 06.39 W, 03/02/2015 19:29,

pos: 011, X150302N09.bin, 36 03.37 S, 050 51.41 W, 03/02/2015 20:26,

pos: 012, X150302N10.bin, 36 08.63 S, 050 35.68 W, 03/02/2015 21:28,

pos: 013, X150302N11.bin, 36 14.00 S, 050 19.79 W, 03/02/2015 22:30,

pos: 014, X150302N12.bin, 36 19.35 S, 050 02.96 W, 03/02/2015 23:32,

pos: 015, X150303N01.bin, 36 24.72 S, 049 44.41 W, 03/03/2015 00:37>manual AL

pos: 016, X150303N02.bin, 36 29.74 S, 049 28.15 W, 03/03/2015 01:34,

pos: 017, X150303N03.bin, 36 34.66 S, 049 12.58 W, 03/03/2015 02:31,

pos: 018, X150303N04.bin, 36 39.05 S, 048 56.99 W, 03/03/2015 03:28,

pos: 019, X150303N05.bin, 36 43.88 S, 048 42.05 W, 03/03/2015 04:25,

pos: 020, X150303N06.bin, 36 48.42 S, 048 26.87 W, 03/03/2015 05:22,

pos: 021, X150303N07.bin, 36 52.60 S, 048 11.67 W, 03/03/2015 06:19,

pos: 022, X150303N08.bin, 36 57.07 S, 047 55.68 W, 03/03/2015 07:21,

pos: 023, X150303N09.bin, 37 02.30 S, 047 38.49 W, 03/03/2015 08:28,

pos: 024, X150303N10.bin, 37 07.10 S, 047 20.97 W, 03/03/2015 09:35,

pos: 025, X150303N11.bin, 37 12.03 S, 047 02.85 W, 03/03/2015 10:42,

pos: 026, X150303N12.bin, 37 17.99 S, 046 42.19 W, 03/03/2015 11:45,

pos: 027, X150303N13.bin, 37 22.82 S, 046 24.80 W, 03/03/2015 12:36,

pos: 028, X150303N14.bin, 37 27.43 S, 046 07.65 W, 03/03/2015 13:33,

pos: 029, X150303N15.bin, 37 31.96 S, 045 50.65 W, 03/03/2015 14:30,

pos: 030, X150303N16.bin, 37 32.30 S, 045 49.12 W, 03/03/2015 14:35>manual AL

pos: 031, X150303N17.bin, 37 35.89 S, 045 32.55 W, 03/03/2015 15:32,

pos: 032, X150303N18.bin, 37 39.58 S, 045 15.68 W, 03/03/2015 16:29,

pos: 033, X150303N19.bin, 37 42.38 S, 044 58.74 W, 03/03/2015 17:26,

pos: 034, X150303N20.bin, 37 45.53 S, 044 39.93 W, 03/03/2015 18:23,

pos: 035, X150303N21.bin, 37 48.50 S, 044 23.50 W, 03/03/2015 19:18,

pos: 036, X150303N22.bin, 37 51.91 S, 044 06.97 W, 03/03/2015 20:15,

pos: 037, X150303N23.bin, 37 56.00 S, 043 50.79 W, 03/03/2015 21:12,

pos: 038, X150303N24.bin, 38 00.01 S, 043 34.70 W, 03/03/2015 22:09,bad at 700 mts

pos: 039, X150303N25.bin, 38 04.16 S, 043 18.41 W, 03/03/2015 23:06,

pos: 040, X150304N01.bin, 38 08.55 S, 043 02.38 W, 03/04/2015 00:03,

pos: 041, X150304N02.bin, 38 12.87 S, 042 45.86 W, 03/04/2015 01:00,

pos: 042, X150304N03.bin, 38 17.06 S, 042 28.80 W, 03/04/2015 01:57,

pos: 043, X150304N04.bin, 38 21.49 S, 042 11.82 W, 03/04/2015 02:54,

pos: 044, X150304N05.bin, 38 25.86 S, 041 54.76 W, 03/04/2015 03:51,

pos: 045, X150304N06.bin, 38 30.22 S, 041 37.97 W, 03/04/2015 04:48,

pos: 046, X150304N07.bin, 38 34.53 S, 041 20.97 W, 03/04/2015 05:45,

pos: 047, X150304N08.bin, 38 38.55 S, 041 03.73 W, 03/04/2015 06:41,

pos: 048, X150304N09.bin, 38 43.08 S, 040 46.49 W, 03/04/2015 07:39,

pos: 049, X150304N10.bin, 38 44.24 S, 040 41.99 W, 03/04/2015 07:54,

pos: 050, X150304N11.bin, 38 48.58 S, 040 24.97 W, 03/04/2015 08:51,

pos: 051, X150304N12.bin, 38 53.10 S, 040 07.27 W, 03/04/2015 09:51,
pos: 052, X150304N13.bin, 38 57.25 S, 039 46.96 W, 03/04/2015 10:56,manual AL
pos: 053, X150304N14.bin, 39 00.67 S, 039 26.12 W, 03/04/2015 11:50,
pos: 054, X150304N15.bin, 39 03.78 S, 039 07.98 W, 03/04/2015 12:48,manual AL, velocity ship changed
pos: 055, X150304N16.bin, 39 07.60 S, 038 46.28 W, 03/04/2015 14:02,
pos: 056, X150304N17.bin, 39 10.80 S, 038 25.66 W, 03/04/2015 15:12,
pos: 057, X150304N18.bin, 39 14.29 S, 038 05.13 W, 03/04/2015 16:22,
pos: 058, X150304N19.bin, 39 17.90 S, 037 44.57 W, 03/04/2015 17:32,
pos: 059, X150304N20.bin, 39 21.34 S, 037 23.09 W, 03/04/2015 18:42,bad profile.
pos: 060, X150304N21.bin, 39 21.57 S, 037 21.70 W, 03/04/2015 18:46,manual AL
pos: 061, X150304N22.bin, 39 25.21 S, 037 00.46 W, 03/04/2015 19:50,manual AL
pos: 062, X150304N23.bin, 39 28.69 S, 036 39.49 W, 03/04/2015 21:00,bad at 200 mts.
pos: 063, X150304N24.bin, 39 28.87 S, 036 38.37 W, 03/04/2015 21:04,manual AL
pos: 064, X150304N25.bin, 39 32.38 S, 036 17.03 W, 03/04/2015 22:14,
pos: 065, X150304N26.bin, 39 36.02 S, 035 55.87 W, 03/04/2015 23:24,
pos: 066, X150305N01.bin, 39 39.65 S, 035 34.10 W, 03/05/2015 00:34,
pos: 067, X150305N02.bin, 39 43.03 S, 035 13.55 W, 03/05/2015 01:39,
pos: 068, X150305N03.bin, 39 46.48 S, 034 52.91 W, 03/05/2015 02:44,
pos: 069, X150305N04.bin, 39 50.09 S, 034 32.02 W, 03/05/2015 03:49,
pos: 070, X150305N05.bin, 39 53.60 S, 034 10.66 W, 03/05/2015 04:54,
pos: 071, X150305N06.bin, 39 57.03 S, 033 49.08 W, 03/05/2015 05:59,
pos: 072, X150305N07.bin, 40 00.63 S, 033 27.41 W, 03/05/2015 07:04,
pos: 073, X150305N08.bin, 40 04.23 S, 033 05.74 W, 03/05/2015 08:09,
pos: 074, X150305N09.bin, 40 07.82 S, 032 44.31 W, 03/05/2015 09:14,
pos: 075, X150305N10.bin, 40 11.15 S, 032 24.88 W, 03/05/2015 10:08,
pos: 076, X150305N11.bin, 40 14.47 S, 032 03.81 W, 03/05/2015 11:00,manual AL
pos: 077, X150305N12.bin, 40 18.74 S, 031 40.31 W, 03/05/2015 12:10,manual AL
pos: 078, X150305N13.bin, 40 22.13 S, 031 19.81 W, 03/05/2015 13:10,
pos: 079, X150305N14.bin, 40 25.25 S, 030 59.53 W, 03/05/2015 14:10,
pos: 080, X150305N15.bin, 40 28.60 S, 030 38.90 W, 03/05/2015 15:10,
pos: 081, X150305N16.bin, 40 32.14 S, 030 17.13 W, 03/05/2015 16:15,
pos: 082, X150305N17.bin, 40 35.05 S, 029 56.57 W, 03/05/2015 17:14,
pos: 083, X150305N18.bin, 40 36.73 S, 029 35.39 W, 03/05/2015 18:10,
pos: 084, X150305N19.bin, 40 38.42 S, 029 13.08 W, 03/05/2015 19:15,
pos: 085, X150305N20.bin, 40 40.02 S, 028 51.63 W, 03/05/2015 20:20,
pos: 086, X150305N21.bin, 40 41.33 S, 028 30.40 W, 03/05/2015 21:25,
pos: 087, X150305N22.bin, 40 42.80 S, 028 09.15 W, 03/05/2015 22:30,
pos: 088, X150305N23.bin, 40 44.33 S, 027 48.41 W, 03/05/2015 23:35,
pos: 089, X150306N01.bin, 40 45.72 S, 027 27.27 W, 03/06/2015 00:40,
pos: 090, X150306N02.bin, 40 46.98 S, 027 05.38 W, 03/06/2015 01:45,
pos: 091, X150306N03.bin, 40 48.79 S, 026 43.63 W, 03/06/2015 02:50,
pos: 092, X150306N04.bin, 40 50.63 S, 026 21.78 W, 03/06/2015 03:55,
pos: 093, X150306N05.bin, 40 52.09 S, 025 59.91 W, 03/06/2015 05:00,
pos: 094, X150306N06.bin, 40 53.51 S, 025 37.89 W, 03/06/2015 06:05,
pos: 095, X150306N07.bin, 40 54.96 S, 025 15.93 W, 03/06/2015 07:10,
pos: 096, X150306N08.bin, 40 56.64 S, 024 54.17 W, 03/06/2015 08:15,
pos: 097, X150306N09.bin, 40 58.04 S, 024 32.57 W, 03/06/2015 09:20,
pos: 098, X150306N10.bin, 40 59.57 S, 024 12.41 W, 03/06/2015 10:11,
pos: 099, X150306N11.bin, 41 01.16 S, 023 51.75 W, 03/06/2015 11:02,
pos: 100, X150306N12.bin, 41 02.58 S, 023 29.79 W, 03/06/2015 12:08,
pos: 101, X150306N13.bin, 41 04.08 S, 023 08.69 W, 03/06/2015 13:14,
pos: 102, X150306N14.bin, 41 06.26 S, 022 40.94 W, 03/06/2015 14:42,I fall sleep. mi bad, sorry
pos: 103, X150306N15.bin, 41 07.99 S, 022 18.56 W, 03/06/2015 15:54,Manual A.L, pin tube 2 does not retract properly

pos: 104, X150306N16.bin, 41 09.38 S, 021 56.07 W, 03/06/2015 17:02,
 pos: 105, X150306N17.bin, 41 11.06 S, 021 33.26 W, 03/06/2015 18:07,
 pos: 106, X150306N18.bin, 41 12.62 S, 021 10.63 W, 03/06/2015 19:17,
 pos: 107, X150306N19.bin, 41 14.04 S, 020 49.23 W, 03/06/2015 20:22,
 pos: 108, X150306N20.bin, 41 15.62 S, 020 27.51 W, 03/06/2015 21:27,
 pos: 109, X150306N21.bin, 41 16.91 S, 020 06.52 W, 03/06/2015 22:32,
 pos: 110, X150306N22.bin, 41 17.45 S, 019 45.37 W, 03/06/2015 23:37,
 pos: 111, X150307N01.bin, 41 16.88 S, 019 23.87 W, 03/07/2015 00:42,
 pos: 112, X150307N02.bin, 41 16.52 S, 019 00.79 W, 03/07/2015 01:52,
 pos: 113, X150307N03.bin, 41 16.49 S, 018 37.74 W, 03/07/2015 03:02,
 pos: 114, X150307N04.bin, 41 15.76 S, 018 14.86 W, 03/07/2015 04:12,
 pos: 115, X150307N05.bin, 41 15.42 S, 017 53.17 W, 03/07/2015 05:17,
 pos: 116, X150307N06.bin, 41 15.28 S, 017 31.30 W, 03/07/2015 06:22,bad profile
 pos: 117, X150307N07.bin, 41 15.25 S, 017 29.54 W, 03/07/2015 06:27,
 pos: 118, X150307N08.bin, 41 14.60 S, 017 07.85 W, 03/07/2015 07:32,
 pos: 119, X150307N09.bin, 41 14.40 S, 016 46.21 W, 03/07/2015 08:37,
 pos: 120, X150307N10.bin, 41 13.87 S, 016 26.14 W, 03/07/2015 09:28,
 pos: 121, X150307N11.bin, 41 13.66 S, 016 04.71 W, 03/07/2015 10:19,
 pos: 122, X150307N12.bin, 41 13.67 S, 016 03.33 W, 03/07/2015 10:23,
 pos: 123, X150307N13.bin, 41 13.67 S, 016 01.23 W, 03/07/2015 10:29,
 pos: 124, X150307N14.bin, 41 13.69 S, 015 59.42 W, 03/07/2015 10:34,bad wheater, hand launch after 3 fails
 pos: 125, X150307N15.bin, 41 13.50 S, 015 47.85 W, 03/07/2015 11:09,bad wheater, TEST GND WIRE.
 pos: 126, X150307N16.bin, 41 13.39 S, 015 34.60 W, 03/07/2015 11:49,Bad wheather, new automatic launcher,
 humidity inside the other.
 pos: 127, X150307N17.bin, 41 12.48 S, 015 11.80 W, 03/07/2015 12:59,Bad wheather, new automatic launcher,
 humidity inside the other.
 pos: 128, X150307N18.bin, 41 12.37 S, 014 49.18 W, 03/07/2015 14:09,
 pos: 129, X150307N19.bin, 41 11.40 S, 014 06.81 W, 03/07/2015 16:10,
 pos: 130, X150307N20.bin, 41 11.19 S, 013 45.31 W, 03/07/2015 17:20,BAD PROFILE
 pos: 131, X150307N21.bin, 41 11.18 S, 013 44.00 W, 03/07/2015 17:24,MANUAL AL
 pos: 132, X150307N22.bin, 41 10.87 S, 013 20.87 W, 03/07/2015 18:40,HAND LAUNCH
 pos: 133, X150307N23.bin, 41 10.52 S, 012 59.51 W, 03/07/2015 19:48,HAND LAUNCH
 pos: 134, X150307N24.bin, 41 10.30 S, 012 38.16 W, 03/07/2015 20:57,hand launch
 pos: 135, X150307N25.bin, 41 09.74 S, 012 16.27 W, 03/07/2015 22:07,launcher relocated far away of winds
 pos: 136, X150307N26.bin, 41 09.55 S, 011 53.98 W, 03/07/2015 23:17,
 pos: 137, X150308N01.bin, 41 09.07 S, 011 31.60 W, 03/08/2015 00:27,
 pos: 138, X150308N02.bin, 41 08.52 S, 011 09.63 W, 03/08/2015 01:37,
 pos: 139, X150308N03.bin, 41 08.21 S, 010 47.87 W, 03/08/2015 02:47,
 pos: 140, X150308N04.bin, 41 08.01 S, 010 26.24 W, 03/08/2015 03:57,
 pos: 141, X150308N05.bin, 41 07.35 S, 010 04.28 W, 03/08/2015 05:07,
 pos: 142, X150308N06.bin, 41 05.74 S, 009 42.73 W, 03/08/2015 06:17,
 pos: 143, X150308N07.bin, 41 03.71 S, 009 21.38 W, 03/08/2015 07:27,
 pos: 144, X150308N08.bin, 41 01.48 S, 008 59.85 W, 03/08/2015 08:37,
 pos: 145, X150308N09.bin, 40 58.75 S, 008 33.18 W, 03/08/2015 09:49,
 pos: 146, X150308N10.bin, 40 56.83 S, 008 11.55 W, 03/08/2015 10:49,ship speed not stable
 pos: 147, X150308N11.bin, 40 54.38 S, 007 48.42 W, 03/08/2015 12:01,
 pos: 148, X150308N12.bin, 40 52.25 S, 007 27.53 W, 03/08/2015 13:06,
 pos: 149, X150308N13.bin, 40 50.24 S, 007 07.17 W, 03/08/2015 14:11,
 pos: 150, X150308N14.bin, 40 48.20 S, 006 46.75 W, 03/08/2015 15:16,
 pos: 151, X150308N15.bin, 40 46.13 S, 006 24.63 W, 03/08/2015 16:21,
 pos: 152, X150308N16.bin, 40 43.92 S, 006 02.69 W, 03/08/2015 17:26,
 pos: 153, X150308N17.bin, 40 41.74 S, 005 41.99 W, 03/08/2015 18:31,
 pos: 154, X150308N18.bin, 40 39.85 S, 005 20.61 W, 03/08/2015 19:41,
 pos: 155, X150308N19.bin, 40 37.40 S, 004 59.10 W, 03/08/2015 20:51,

pos: 156, X150308N20.bin, 40 35.13 S, 004 37.32 W, 03/08/2015 22:01,
pos: 157, X150308N21.bin, 40 34.90 S, 004 35.03 W, 03/08/2015 22:08,
pos: 158, X150308N22.bin, 40 32.66 S, 004 13.35 W, 03/08/2015 23:18,
pos: 159, X150309N01.bin, 40 30.35 S, 003 50.72 W, 03/09/2015 00:28,
pos: 160, X150309N02.bin, 40 28.43 S, 003 29.08 W, 03/09/2015 01:38,
pos: 161, X150309N03.bin, 40 26.47 S, 003 06.91 W, 03/09/2015 02:48,
pos: 162, X150309N04.bin, 40 23.75 S, 002 43.86 W, 03/09/2015 04:01,
pos: 163, X150309N05.bin, 40 21.66 S, 002 22.17 W, 03/09/2015 05:11,
pos: 164, X150309N06.bin, 40 19.42 S, 002 00.32 W, 03/09/2015 06:21,
pos: 165, X150309N07.bin, 40 17.15 S, 001 38.92 W, 03/09/2015 07:31,
pos: 166, X150309N08.bin, 40 15.08 S, 001 16.70 W, 03/09/2015 08:41,
pos: 167, X150309N09.bin, 40 12.90 S, 000 52.08 W, 03/09/2015 09:42,
pos: 168, X150309N10.bin, 40 10.82 S, 000 33.83 W, 03/09/2015 10:36,
pos: 169, X150309N11.bin, 40 10.12 S, 000 27.58 W, 03/09/2015 10:56,
pos: 170, X150309N12.bin, 40 08.36 S, 000 09.89 W, 03/09/2015 11:53,
pos: 171, X150309N13.bin, 40 05.83 S, 000 07.43 E, 03/09/2015 12:50,
pos: 172, X150309N14.bin, 40 02.55 S, 000 24.77 E, 03/09/2015 13:47,
pos: 173, X150309N15.bin, 39 58.96 S, 000 42.53 E, 03/09/2015 14:44,
pos: 174, X150309N16.bin, 39 55.52 S, 001 01.39 E, 03/09/2015 15:41,
pos: 175, X150309N17.bin, 39 51.54 S, 001 22.26 E, 03/09/2015 16:42,manual AL
pos: 176, X150309N18.bin, 39 48.35 S, 001 39.43 E, 03/09/2015 17:37,
pos: 177, X150309N19.bin, 39 45.11 S, 001 56.46 E, 03/09/2015 18:32,
pos: 178, X150309N20.bin, 39 41.49 S, 002 14.21 E, 03/09/2015 19:30,manual AL
pos: 179, X150309N21.bin, 39 38.11 S, 002 31.86 E, 03/09/2015 20:27,
pos: 180, X150309N22.bin, 39 34.61 S, 002 49.62 E, 03/09/2015 21:24,
pos: 181, X150309N23.bin, 39 31.30 S, 003 06.82 E, 03/09/2015 22:19,
pos: 182, X150309N24.bin, 39 27.87 S, 003 23.74 E, 03/09/2015 23:14,
pos: 183, X150310N01.bin, 39 24.64 S, 003 41.15 E, 03/10/2015 00:09,
pos: 184, X150310N02.bin, 39 21.40 S, 003 58.52 E, 03/10/2015 01:04,
pos: 185, X150310N03.bin, 39 18.01 S, 004 15.80 E, 03/10/2015 01:59,
pos: 186, X150310N04.bin, 39 14.28 S, 004 33.06 E, 03/10/2015 02:54,
pos: 187, X150310N05.bin, 39 11.07 S, 004 50.63 E, 03/10/2015 03:49,
pos: 188, X150310N06.bin, 39 07.58 S, 005 07.91 E, 03/10/2015 04:44,
pos: 189, X150310N07.bin, 39 04.01 S, 005 25.49 E, 03/10/2015 05:39,
pos: 190, X150310N08.bin, 39 00.74 S, 005 43.12 E, 03/10/2015 06:34,bad reading
pos: 191, X150310N09.bin, 39 00.50 S, 005 44.27 E, 03/10/2015 06:38,
pos: 192, X150310N10.bin, 38 57.09 S, 006 01.45 E, 03/10/2015 07:33,
pos: 193, X150310N11.bin, 38 54.05 S, 006 17.20 E, 03/10/2015 08:15,
pos: 194, X150310N12.bin, 38 50.57 S, 006 33.62 E, 03/10/2015 08:57,
pos: 195, X150310N13.bin, 38 46.99 S, 006 51.26 E, 03/10/2015 09:52,
pos: 196, X150310N14.bin, 38 44.00 S, 007 07.50 E, 03/10/2015 10:47,
pos: 197, X150310N15.bin, 38 38.50 S, 007 34.33 E, 03/10/2015 12:26,manual AL
pos: 198, X150310N16.bin, 38 34.97 S, 007 51.23 E, 03/10/2015 13:28,
pos: 199, X150310N17.bin, 38 31.66 S, 008 07.97 E, 03/10/2015 14:30,
pos: 200, X150310N18.bin, 38 29.20 S, 008 22.74 E, 03/10/2015 15:15,
pos: 201, X150310N19.bin, 38 26.21 S, 008 38.20 E, 03/10/2015 16:00,
pos: 202, X150310N20.bin, 38 22.85 S, 008 55.17 E, 03/10/2015 17:02,
pos: 203, X150310N21.bin, 38 19.56 S, 009 12.04 E, 03/10/2015 18:04,
pos: 204, X150310N22.bin, 38 16.25 S, 009 28.91 E, 03/10/2015 19:06,
pos: 205, X150310N23.bin, 38 12.91 S, 009 45.22 E, 03/10/2015 20:08,
pos: 206, X150310N24.bin, 38 09.66 S, 010 01.59 E, 03/10/2015 21:10,
pos: 207, X150310N25.bin, 38 04.92 S, 010 17.47 E, 03/10/2015 22:12,
pos: 208, X150310N26.bin, 38 00.31 S, 010 33.46 E, 03/10/2015 23:14,
pos: 209, X150311N01.bin, 37 55.63 S, 010 49.18 E, 03/11/2015 00:16,

pos: 210, X150311N02.bin, 37 50.89 S, 011 05.30 E, 03/11/2015 01:20,
pos: 211, X150311N03.bin, 37 46.08 S, 011 21.65 E, 03/11/2015 02:23,
pos: 212, X150311N04.bin, 37 41.53 S, 011 37.97 E, 03/11/2015 03:26,suspicious profile
pos: 213, X150311N05.bin, 37 41.25 S, 011 39.02 E, 03/11/2015 03:30>manual AL
pos: 214, X150311N06.bin, 37 36.45 S, 011 55.13 E, 03/11/2015 04:35,
pos: 215, X150311N07.bin, 37 31.45 S, 012 11.09 E, 03/11/2015 05:40,wire probe bad.
pos: 216, X150311N08.bin, 37 31.15 S, 012 12.02 E, 03/11/2015 05:44>manual AL.
pos: 217, X150311N09.bin, 37 26.30 S, 012 27.70 E, 03/11/2015 06:46,
pos: 218, X150311N10.bin, 37 21.94 S, 012 43.72 E, 03/11/2015 07:45,
pos: 219, X150311N11.bin, 37 17.72 S, 012 59.74 E, 03/11/2015 08:27,back up A. Launcher.
pos: 220, X150311N12.bin, 37 12.94 S, 013 15.57 E, 03/11/2015 09:09,
pos: 221, X150311N13.bin, 37 07.83 S, 013 32.36 E, 03/11/2015 10:11,
pos: 222, X150311N14.bin, 37 02.79 S, 013 49.14 E, 03/11/2015 11:16,pin tube 2 stocked
pos: 223, X150311N15.bin, 36 57.94 S, 014 04.80 E, 03/11/2015 12:18,
pos: 224, X150311N16.bin, 36 53.77 S, 014 20.07 E, 03/11/2015 13:20,
pos: 225, X150311N17.bin, 36 49.12 S, 014 34.29 E, 03/11/2015 14:22,
pos: 226, X150311N18.bin, 36 44.50 S, 014 49.91 E, 03/11/2015 15:18>manual AL
pos: 227, X150311N19.bin, 36 40.38 S, 015 03.77 E, 03/11/2015 16:03,
pos: 228, X150311N20.bin, 36 35.49 S, 015 19.90 E, 03/11/2015 17:10,
pos: 229, X150311N21.bin, 36 30.74 S, 015 36.21 E, 03/11/2015 18:17,
pos: 230, X150311N22.bin, 36 25.99 S, 015 52.27 E, 03/11/2015 19:24,
pos: 231, X150311N23.bin, 36 21.30 S, 016 08.00 E, 03/11/2015 20:31,
pos: 232, X150311N24.bin, 36 16.92 S, 016 23.12 E, 03/11/2015 21:38,strange profile
pos: 233, X150311N25.bin, 36 16.60 S, 016 24.29 E, 03/11/2015 21:43,previous strange profile, check drop
pos: 234, X150311N26.bin, 36 11.55 S, 016 40.09 E, 03/11/2015 22:50,
pos: 235, X150312N01.bin, 36 06.55 S, 016 55.91 E, 03/11/2015 23:57,
pos: 236, X150312N02.bin, 36 01.96 S, 017 11.38 E, 03/12/2015 01:04,
pos: 237, X150312N03.bin, 35 57.37 S, 017 27.01 E, 03/12/2015 02:11,
pos: 238, X150312N04.bin, 35 53.05 S, 017 42.46 E, 03/12/2015 03:18,
pos: 239, X150312N05.bin, 35 48.52 S, 017 57.81 E, 03/12/2015 04:25,
pos: 240, X150312N06.bin, 35 44.03 S, 018 13.03 E, 03/12/2015 05:32,
pos: 241, X150312N07.bin, 35 39.13 S, 018 28.65 E, 03/12/2015 06:39,
pos: 242, X150312N08.bin, 35 34.94 S, 018 43.96 E, 03/12/2015 07:24,
pos: 243, X150312N09.bin, 35 31.15 S, 018 58.70 E, 03/12/2015 08:09,
pos: 244, X150312N10.bin, 35 25.54 S, 019 12.80 E, 03/12/2015 09:11,
pos: 245, X150312N11.bin, 35 22.41 S, 019 23.90 E, 03/12/2015 09:57,200 mts. reached, end cruise AX!80315.
Byee