



SEA-BIRD ELECTRONICS, INC.

13431 NE 20th St. Bellevue, Washington 98005 USA

Phone: (425) 643-9866 Fax: (425) 643-9954 www.seabird.com

Service
Report

RMA Number

61008

Customer Information:

Company	US Department of Commerce, NOAA	Date	9/9/2010
Contact	Ulises Rivero		
PO Number	Credit Card		

Serial Number	03P4663
Model Number	SBE 03Plus

Services Requested:

1. Evaluate/Repair Instrumentation.
2. Perform Routine Calibration Service.

Problems Found:

--

Services Performed:

1. Performed initial diagnostic evaluation.
2. Performed "Post Cruise" calibration of the temperature sensor.

Special Notes:

--



SEA-BIRD ELECTRONICS, INC.

13431 NE 20th St. Bellevue, Washington 98005 USA

Phone: (425) 643-9866 Fax: (425) 643-9954 www.seabird.com

Service
Report

RMA Number

61008

Customer Information:

Company US Department of Commerce, NOAA **Date** 9/9/2010

Contact Ulises Rivero

PO Number Credit Card

Serial Number 042973

Model Number SBE 04C

Services Requested:

1. Evaluate/Repair Instrumentation.
2. Perform Routine Calibration Service.

Problems Found:

--

Services Performed:

1. Performed initial diagnostic evaluation.
2. Performed "Post Cruise" calibration of the conductivity sensor.

Special Notes:

--



SEA-BIRD ELECTRONICS, INC.

13431 NE 20th St. Bellevue, Washington 98005 USA

Phone: (425) 643-9866 Fax: (425) 643-9954 www.seabird.com

Service
Report

RMA Number	61008
-------------------	-------

Customer Information:

Company	US Department of Commerce, NOAA	Date	9/9/2010
----------------	---------------------------------	-------------	----------

Contact	Ulises Rivero
----------------	---------------

PO Number	Credit Card
------------------	-------------

Serial Number	430703
Model Number	SBE 43

Services Requested:

1. Evaluate/Repair Instrumentation.
2. Perform Routine Calibration Service.

Problems Found:

--

Services Performed:

1. Performed initial diagnostic evaluation.
2. Performed "Post Cruise" calibration of the oxygen sensor.
3. Performed full diagnostic evaluation.

Special Notes:

--



SEA-BIRD ELECTRONICS, INC.

13431 NE 20th St. Bellevue, Washington 98005 USA

Phone: (425) 643-9866 Fax: (425) 643-9954 www.seabird.com

Service
Report

RMA Number	61008
-------------------	-------

Customer Information:

Company	US Department of Commerce, NOAA	Date	9/9/2010
Contact	Ulises Rivero		
PO Number	Credit Card		

Serial Number	430730
Model Number	SBE 43

Services Requested:

1. Evaluate/Repair Instrumentation.
2. Perform Routine Calibration Service.

Problems Found:

--

Services Performed:

1. Performed initial diagnostic evaluation.
2. Performed "Post Cruise" calibration of the oxygen sensor.
3. Performed full diagnostic evaluation.

Special Notes:

--



SEA-BIRD ELECTRONICS, INC.

13431 NE 20th St. Bellevue, Washington 98005 USA

Phone: (425) 643-9866 Fax: (425) 643-9954 www.seabird.com

Service
Report

RMA Number	61008
-------------------	-------

Customer Information:

Company	US Department of Commerce, NOAA	Date	9/9/2010
Contact	Ulises Rivero		
PO Number	Credit Card		

Serial Number	431266
Model Number	SBE 43

Services Requested:

1. Evaluate/Repair Instrumentation.
2. Perform Routine Calibration Service.

Problems Found:

--

Services Performed:

1. Performed initial diagnostic evaluation.
2. Performed "Post Cruise" calibration of the oxygen sensor.
3. Performed full diagnostic evaluation.

Special Notes:

--



SEA-BIRD ELECTRONICS, INC.

13431 NE 20th St. Bellevue, Washington 98005 USA

Phone: (425) 643-9866 Fax: (425) 643-9954 www.seabird.com

Service
Report

RMA Number	61008
-------------------	-------

Customer Information:

Company	US Department of Commerce, NOAA	Date	9/9/2010
----------------	---------------------------------	-------------	----------

Contact	Ulises Rivero
----------------	---------------

PO Number	Credit Card
------------------	-------------

Serial Number	431666
Model Number	SBE 43

Services Requested:

1. Evaluate/Repair Instrumentation.
2. Perform Routine Calibration Service.

Problems Found:

--

Services Performed:

1. Performed initial diagnostic evaluation.
2. Performed "Post Cruise" calibration of the oxygen sensor.
3. Performed full diagnostic evaluation.

Special Notes:

--