



SEA-BIRD ELECTRONICS, INC.

13431 NE 20th St. Bellevue, Washington 98005 USA

Phone: (425) 643-9866 Fax: (425) 643-9954 www.seabird.com

Service
Report

RMA Number

63128

Customer Information:

Company	US Department of Commerce, NOAA	Date	2/28/2011
Contact	Ulises Rivero		
PO Number	TBD		

Serial Number	03P2958
Model Number	SBE 03Plus

Services Requested:

1. Evaluate/Repair Instrumentation.
2. Perform Routine Calibration Service.

Problems Found:

--

Services Performed:

1. Performed initial diagnostic evaluation.
2. Performed "Post Cruise" calibration of the temperature sensor.

Special Notes:

--



SEA-BIRD ELECTRONICS, INC.

13431 NE 20th St. Bellevue, Washington 98005 USA

Phone: (425) 643-9866 Fax: (425) 643-9954 www.seabird.com

Service
Report

RMA Number

63128

Customer Information:

Company	US Department of Commerce, NOAA	Date	2/28/2011
Contact	Ulises Rivero		
PO Number	TBD		

Serial Number	03P4663
Model Number	SBE 03Plus

Services Requested:

1. Evaluate/Repair Instrumentation.
2. Perform Routine Calibration Service.

Problems Found:

--

Services Performed:

1. Performed initial diagnostic evaluation.
2. Performed "Post Cruise" calibration of the temperature sensor.

Special Notes:

--



SEA-BIRD ELECTRONICS, INC.

13431 NE 20th St. Bellevue, Washington 98005 USA

Phone: (425) 643-9866 Fax: (425) 643-9954 www.seabird.com

Service
Report

RMA Number

63128

Customer Information:

Company	US Department of Commerce, NOAA	Date	2/28/2011
Contact	Ulises Rivero		
PO Number	TBD		

Serial Number	042980
Model Number	SBE 04C

Services Requested:

1. Evaluate/Repair Instrumentation.
2. Perform Routine Calibration Service.

Problems Found:

--

Services Performed:

1. Performed initial diagnostic evaluation.
2. Performed "Post Cruise" calibration of the conductivity sensor.

Special Notes:

--



SEA-BIRD ELECTRONICS, INC.

13431 NE 20th St. Bellevue, Washington 98005 USA

Phone: (425) 643-9866 Fax: (425) 643-9954 www.seabird.com

Service
Report

RMA Number

63128

Customer Information:

Company US Department of Commerce, NOAA **Date** 2/28/2011

Contact Ulises Rivero

PO Number TBD

Serial Number 043338

Model Number SBE 04C

Services Requested:

1. Evaluate/Repair Instrumentation.
2. Perform Routine Calibration Service.

Problems Found:

--

Services Performed:

1. Performed initial diagnostic evaluation.
2. Performed "Post Cruise" calibration of the conductivity sensor.

Special Notes:

--



SEA-BIRD ELECTRONICS, INC.

13431 NE 20th St. Bellevue, Washington 98005 USA

Phone: (425) 643-9866 Fax: (425) 643-9954 www.seabird.com

Service
Report

RMA Number

63128

Customer Information:

Company	US Department of Commerce, NOAA	Date	2/28/2011
Contact	Ulises Rivero		
PO Number	TBD		

Serial Number	430730
Model Number	SBE 43

Services Requested:

1. Evaluate/Repair Instrumentation.
2. Perform Routine Calibration Service.
3. Perform Full Refurbishment.

Problems Found:

1. The membrane was punctured or torn.

Services Performed:

1. Performed initial diagnostic evaluation.
2. Performed "Post Cruise" calibration of the oxygen sensor.
3. Replaced the lid and membrane assembly (0.5 mil).
4. Replaced the electrolyte with new fluid.
5. Performed "Final" calibration of the oxygen sensor.
6. Performed full diagnostic evaluation.

Special Notes:

--