

13431 NE 20th Street Bellevue, WA 98005 United States Phone +1-425-643-9866

www.seabird.com

1005517004 14-DEC-2022

**Service Request Date** Sales Order 320379788

#### SERVICE REPORT

#### **CUSTOMER INFORMATION**

Name: NOAA - ATLANTIC OCEANOGRAPHIC AND METEOROLOGICAL LAB

Account: 40279759 **GRANT RAWSON** 

GRANT.RAWSON@NOAA.GOV

(305) 361-4363

**Bill To Address** 

NOAA - ATLANTIC OCEANOGRAPHIC AND METEOROLOGICAL LAB 4301 RICKENBACKER CAUSEWAY MIAMI,FL,33149,US

**Ship To Address** 

NOAA - ATLANTIC OCEANOGRAPHIC AND METEOROLOGICAL LAB 4301 RICKENBACKER CAUSEWAY

PO Number:

1333MJ22FNRMA0017

MIAMI,FL,33149,US

#### PRODUCT INFORMATION

Item: 43.LEGACY

Item Description: (LEGACY) SBE 43 Oxygen Sensor

**Serial:** 43-2949

**Special Notes** 

Services Requested:

CAL 43

Services Performed:

Perform initial diagnostic evaluation. Performed "POST" cruise calibration.

Item	Item Description	Qty
CAL_43	SBE 43 dissolved oxygen sensor calibration	1

Item	Item Description	Qty



**SERVICE REPORT** 

## Sea-Bird Electronics, Inc.

13431 NE 20th Street Bellevue, WA 98005 United States Phone +1-425-643-9866

www.seabird.com

Service Request Date Sales Order **1005517004** 14-DEC-2022 320379788

# PRODUCT INFORMATION

Item: 43.LEGACY

Item Description: (LEGACY) SBE 43 Oxygen Sensor

**Serial:** 43-2940

**Special Notes** Services Requested: CAL\_43

Services Performed:

Perform initial diagnostic evaluation. Performed "POST" cruise calibration.

Item	Item Description	Qty
CAL_43	SBE 43 dissolved oxygen sensor calibration	1

01121110 a 1101110		
Item	Item Description	Qty
		, and the second



13431 NE 20th Street Bellevue, WA 98005 United States Phone +1-425-643-9866

www.seabird.com

Service Request Date Sales Order **1005517004** 14-DEC-2022 320379788

# SERVICE REPORT

### PRODUCT INFORMATION

Item: 43.LEGACY

Item Description: (LEGACY) SBE 43 Oxygen Sensor

**Serial:** 430703

**Special Notes**Services Requested:

CAL\_43

Services Performed:

Perform initial diagnostic evaluation. Performed "POST" cruise calibration.

Item	Item Description	Qty
CAL_43	SBE 43 dissolved oxygen sensor calibration	1

Item	Item Description	Qty
•		, and the second



**SERVICE REPORT** 

## Sea-Bird Electronics, Inc.

13431 NE 20th Street Bellevue, WA 98005 United States Phone +1-425-643-9866

www.seabird.com

Service Request Date Sales Order **1005517004** 14-DEC-2022 320379788

# PRODUCT INFORMATION

Item: 43.LEGACY

Item Description: (LEGACY) SBE 43 Oxygen Sensor

**Serial:** 431348

**Special Notes** Services Requested: CAL\_43

Services Performed:

Perform initial diagnostic evaluation. Performed "POST" cruise calibration.

Item	Item Description	Qty
CAL_43	SBE 43 dissolved oxygen sensor calibration	1

Item	Item Description	Qty



13431 NE 20th Street Bellevue, WA 98005 United States Phone +1-425-643-9866

www.seabird.com

Service Request Date Sales Order **1005517004** 14-DEC-2022 320379788

### SERVICE REPORT

### PRODUCT INFORMATION

Item: 04C.210

Item Description: SBE4C COND SENSOR V2, 6800M, XSG, SCOTCHCAST

Serial: 044222

**Special Notes** Services Requested: CAL\_4C

Services Performed:

Perform initial diagnostic evaluation. Performed "POST" cruise calibration.

Item	Item Description	Qty
CAL_4C	SBE 4C Conductivity Calibration for CTD sensors (includes 6-point 35 PSU post deployment cal., and C&P with 6-point 35 PSU re-cal, if necessary)	1

Item	Item Description	Qty



13431 NE 20th Street Bellevue, WA 98005 United States Phone +1-425-643-9866

www.seabird.com

Service Request Date Sales Order **1005517004** 14-DEC-2022 320379788

# SERVICE REPORT

### PRODUCT INFORMATION

Item: 04C.210

Item Description: SBE4C COND SENSOR V2, 6800M, XSG, SCOTCHCAST

Serial: 044223

**Special Notes** Services Requested: CAL\_4C

Problems Found:

The conductivity cell was found to require cleaning and re-platinization.

Services Performed:

Perform initial diagnostic evaluation. Performed "POST" cruise calibration. Cleaned and replatinized the conductivity cell. Performed a "Final" Calibration.

Item	Item Description	Qty
CAL_4C	SBE 4C Conductivity Calibration for CTD sensors (includes 6-point 35 PSU post deployment cal., and C&P with 6-point 35 PSU re-cal, if necessary)	1

Olibinou itoliio		
Item	Item Description	Qty



13431 NE 20th Street Bellevue, WA 98005 United States Phone +1-425-643-9866

www.seabird.com

Service Request Date Sales Order 1005517004 14-DEC-2022 320379788

# SERVICE REPORT

### PRODUCT INFORMATION

Item: 03P.LEGACY

Item Description: (LEGACY) SBE 03Plus Temperature Sensor

**Serial:** 03P5237

**Special Notes**Services Requested:
CAL\_3

Services Performed:

Perform initial diagnostic evaluation. Performed "POST" cruise calibration.

Item	Item Description	Qty
CAL_3	SBE 3 Temperature sensor calibration; 11 points -1 to 31deg.C	1

Item	Item Description	Qty
•		, and the second



13431 NE 20th Street Bellevue, WA 98005 United States Phone +1-425-643-9866

www.seabird.com

Service Request Date Sales Order **1005517004** 14-DEC-2022 320379788

### SERVICE REPORT

### PRODUCT INFORMATION

Item: 03P.210

Item Description: SBE3PLUS TEMP, GE PROBE, 6800M, XSG

**Serial:** 03-5348

Special Notes
Services Requested:

CAL\_3

Services Performed:

Perform initial diagnostic evaluation. Performed "POST" cruise calibration.

Item	Item Description	Qty
CAL_3	SBE 3 Temperature sensor calibration; 11 points -1 to 31deg.C	1

Item	Item Description	Qty



**SERVICE REPORT** 

### Sea-Bird Electronics, Inc.

13431 NE 20th Street Bellevue, WA 98005 United States Phone +1-425-643-9866

www.seabird.com

Service Request Date Sales Order 1005517004 14-DEC-2022 320379788

### PRODUCT INFORMATION

Item: 43.LEGACY

Item Description: (LEGACY) SBE 43 Oxygen Sensor

Serial: 43-2934

**Special Notes** Services Requested: CAL\_43

Problems Found:

The air was found in the electrolyte.

Services Performed:

Perform initial diagnostic evaluation. Performed "POST" cruise calibration.

Replaced the lid and membrane assembly (0.5 mil).

Replaced the electrolyte with new fluid.

Replaced the O-rings.

Performed a hydrostatic pressure test.

Performed a "Final" Calibration.

Item Description	Qty
SBE 43 dissolved oxygen sensor calibration	1
	ļ.

Item	Item Description	Qty
801576	SBE43 LID & MEMBRANE SUB-ASSY, .5MIL MEMBRANE	1
22085	BATTERY, SANYO CR14250SE-SP1-1, 850 mA-h	2



13431 NE 20th Street Bellevue, WA 98005 United States Phone +1-425-643-9866

www.seabird.com

Service Request Date Sales Order 1005517004 14-DEC-2022 320379788

### **SERVICE REPORT**

### PRODUCT INFORMATION

Item: 43.LEGACY

Item Description: (LEGACY) SBE 43 Oxygen Sensor

Serial: 430154

**Special Notes** Services Requested: CAL\_43

Services Performed:

Perform initial diagnostic evaluation. Performed "POST" cruise calibration.

Item	Item Description	Qty
CAL_43	SBE 43 dissolved oxygen sensor calibration	1

***************************************		
Item	Item Description	Qty
•		