



# SEA-BIRD ELECTRONICS, INC.

13431 NE 20th St. Bellevue, Washington 98005 USA

Phone: (425) 643-9866 Fax: (425) 643-9954 www.seabird.com

<b>Service</b>
<b>Report</b>

**RMA Number**

67586

### Customer Information:

<b>Company</b>	US Department of Commerce, NOAA	<b>Date</b>	1/26/2012
<b>Contact</b>	Ulises Rivero		
<b>PO Number</b>	Credit Card		

<b>Serial Number</b>	043338
<b>Model Number</b>	SBE 04C

### Services Requested:

1. Evaluate/Repair Instrumentation.
2. Perform Routine Calibration Service.

### Problems Found:

--

### Services Performed:

1. Performed initial diagnostic evaluation.
2. Performed "Post Cruise" calibration of the conductivity sensor.

### Special Notes:

--



# SEA-BIRD ELECTRONICS, INC.

13431 NE 20th St. Bellevue, Washington 98005 USA

Phone: (425) 643-9866 Fax: (425) 643-9954 www.seabird.com

<b>Service</b>
<b>Report</b>

<b>RMA Number</b>	67586
-------------------	-------

### Customer Information:

<b>Company</b>	US Department of Commerce, NOAA	<b>Date</b>	1/26/2012
----------------	---------------------------------	-------------	-----------

<b>Contact</b>	Ulises Rivero
----------------	---------------

<b>PO Number</b>	Credit Card
------------------	-------------

<b>Serial Number</b>	043647
<b>Model Number</b>	SBE 04C

### Services Requested:

1. Evaluate/Repair Instrumentation.
2. Perform Routine Calibration Service.

### Problems Found:

--

### Services Performed:

1. Performed initial diagnostic evaluation.
2. Performed "Post Cruise" calibration of the conductivity sensor.

### Special Notes:

--



# SEA-BIRD ELECTRONICS, INC.

13431 NE 20th St. Bellevue, Washington 98005 USA

Phone: (425) 643-9866 Fax: (425) 643-9954 www.seabird.com

<b>Service</b>
<b>Report</b>

**RMA Number**

67586

### Customer Information:

<b>Company</b>	US Department of Commerce, NOAA	<b>Date</b>	1/26/2012
<b>Contact</b>	Ulises Rivero		
<b>PO Number</b>	Credit Card		

<b>Serial Number</b>	043657
<b>Model Number</b>	SBE 04C

### Services Requested:

1. Evaluate/Repair Instrumentation.
2. Perform Routine Calibration Service.

### Problems Found:

--

### Services Performed:

1. Performed initial diagnostic evaluation.
2. Performed "Post Cruise" calibration of the conductivity sensor.

### Special Notes:

--



# SEA-BIRD ELECTRONICS, INC.

13431 NE 20th St. Bellevue, Washington 98005 USA

Phone: (425) 643-9866 Fax: (425) 643-9954 www.seabird.com

<b>Service</b>
<b>Report</b>

**RMA Number**

67586

### Customer Information:

<b>Company</b>	US Department of Commerce, NOAA	<b>Date</b>	1/26/2012
<b>Contact</b>	Ulises Rivero		
<b>PO Number</b>	Credit Card		

<b>Serial Number</b>	043858
<b>Model Number</b>	SBE 04C

### Services Requested:

1. Evaluate/Repair Instrumentation.
2. Perform Routine Calibration Service.

### Problems Found:

--

### Services Performed:

1. Performed initial diagnostic evaluation.
2. Performed "Post Cruise" calibration of the conductivity sensor.

### Special Notes:

--



# SEA-BIRD ELECTRONICS, INC.

13431 NE 20th St. Bellevue, Washington 98005 USA

Phone: (425) 643-9866 Fax: (425) 643-9954 www.seabird.com

<b>Service</b>
<b>Report</b>

**RMA Number**

67586

### Customer Information:

<b>Company</b>	US Department of Commerce, NOAA	<b>Date</b>	1/26/2012
<b>Contact</b>	Ulises Rivero		
<b>PO Number</b>	Credit Card		

<b>Serial Number</b>	043860
<b>Model Number</b>	SBE 04C

### Services Requested:

1. Evaluate/Repair Instrumentation.
2. Perform Routine Calibration Service.

### Problems Found:

--

### Services Performed:

1. Performed initial diagnostic evaluation.
2. Performed "Post Cruise" calibration of the conductivity sensor.

### Special Notes:

--



# SEA-BIRD ELECTRONICS, INC.

13431 NE 20th St. Bellevue, Washington 98005 USA

Phone: (425) 643-9866 Fax: (425) 643-9954 www.seabird.com

<b>Service</b>
<b>Report</b>

<b>RMA Number</b>	67586
-------------------	-------

### Customer Information:

<b>Company</b>	US Department of Commerce, NOAA	<b>Date</b>	1/26/2012
----------------	---------------------------------	-------------	-----------

<b>Contact</b>	Ulises Rivero
----------------	---------------

<b>PO Number</b>	Credit Card
------------------	-------------

<b>Serial Number</b>	432040
<b>Model Number</b>	SBE 43

### Services Requested:

1. Evaluate/Repair Instrumentation.
2. Perform Routine Calibration Service.

### Problems Found:

--

### Services Performed:

1. Performed initial diagnostic evaluation.
2. Performed "Post Cruise" calibration of the oxygen sensor.
3. Performed full diagnostic evaluation.

### Special Notes:

--