

Customer Information:

| Company | US Department of Commerce, NOAA | Date | 5/22/2012 |
|-----------|---------------------------------|------|-----------|
| Contact | Ulises Rivero | | |
| PO Number | No Charge | | |
| | | | |

Services Requested:

- 1. Evaluate/Repair Instrumentation.
- 2. Perform Routine Calibration Service.

Problems Found:

Services Performed:

- 1. Performed initial diagnostic evaluation.
- 2. Performed "Post Cruise" calibration of the temperature sensor.

Special Notes:



Customer Information:

| Company | US Department of Commerce, NOAA | Date | 5/22/2012 |
|-----------|---------------------------------|------|-----------|
| Contact | Ulises Rivero | | |
| PO Number | No Charge | | |
| • | | | |

| Serial Number | 03P5237 |
|---------------|---------|
| Model Number | SBE 03P |

Services Requested:

- 1. Evaluate/Repair Instrumentation.
- 2. Perform Routine Calibration Service.

Problems Found:

Services Performed:

- 1. Performed initial diagnostic evaluation.
- 2. Performed "Post Cruise" calibration of the temperature sensor.

Special Notes: