

Customer	Information:
----------	--------------

Company	US Department of Commerce, NOAA	Date	7/6/2012
Contact	Ulises Rivero		
PO Number	TBD		
ł			

Serial Number	031075
Model Number	SBE 03-02/F

# Services Requested:

- 1. Evaluate/Repair Instrumentation.
- 2. Perform Routine Calibration Service.

## **Problems Found:**

## Services Performed:

- 1. Performed initial diagnostic evaluation.
- 2. Performed "Post Cruise" calibration of the temperature sensor.

## Special Notes:



	Report	RMA Number	69723	
Customer Inf	ormation:			
Company	US Department of Commerce, NOAA		Date	7/6/2012
Contact	Ulises Rivero	]		
PO Number	TBD			
Serial Number	er 431348			
Model Numb	er SBE 43			

# Services Requested:

- 1. Evaluate/Repair Instrumentation.
- 2. Perform Routine Calibration Service.
- 3. Perform Full Refurbishment.

## Problems Found:

1. Customer has requested refurb.

## Services Performed:

- 1. Performed initial diagnostic evaluation.
- 2. Performed "Post Cruise" calibration of the oxygen sensor.
- 3. Replaced the lid and membrane assembly (0.5 mil).
- 4. Replaced the electrolyte with new fluid.
- 5. Performed "Final" calibration of the oxygen sensor.
- 6. Performed full diagnostic evaluation.

#### Special Notes: