



# SEA-BIRD ELECTRONICS, INC.

13431 NE 20th St. Bellevue, Washington 98005 USA

Phone: (425) 643-9866 Fax: (425) 643-9954 www.seabird.com

<b>Service</b>
<b>Report</b>

**RMA Number**

71470

### Customer Information:

**Company** US Department of Commerce, NOAA **Date** 11/8/2012

**Contact** Ulises Rivero

**PO Number** TBD

**Serial Number** 031692

**Model Number** SBE 03-02/F

### Services Requested:

1. Evaluate/Repair Instrumentation.
2. Perform Routine Calibration Service.

### Problems Found:

--

### Services Performed:

1. Performed initial diagnostic evaluation.
2. Performed "Post Cruise" calibration of the temperature sensor.

### Special Notes:

--



# SEA-BIRD ELECTRONICS, INC.

13431 NE 20th St. Bellevue, Washington 98005 USA

Phone: (425) 643-9866 Fax: (425) 643-9954 www.seabird.com

<b>Service</b>
<b>Report</b>

<b>RMA Number</b>	71470
-------------------	-------

### Customer Information:

<b>Company</b>	US Department of Commerce, NOAA	<b>Date</b>	11/8/2012
<b>Contact</b>	Ulises Rivero		
<b>PO Number</b>	TBD		

<b>Serial Number</b>	03P4799
<b>Model Number</b>	SBE 03Plus

### Services Requested:

1. Evaluate/Repair Instrumentation.
2. Perform Routine Calibration Service.

### Problems Found:

--

### Services Performed:

1. Performed initial diagnostic evaluation.
2. Performed "Post Cruise" calibration of the temperature sensor.

### Special Notes:

--



# SEA-BIRD ELECTRONICS, INC.

13431 NE 20th St. Bellevue, Washington 98005 USA

Phone: (425) 643-9866 Fax: (425) 643-9954 www.seabird.com

<b>Service</b>
<b>Report</b>

**RMA Number**

71470

### Customer Information:

**Company** US Department of Commerce, NOAA **Date** 11/8/2012

**Contact** Ulises Rivero

**PO Number** TBD

**Serial Number** 03P5140

**Model Number** SBE 03Plus

### Services Requested:

1. Evaluate/Repair Instrumentation.
2. Perform Routine Calibration Service.

### Problems Found:

--

### Services Performed:

1. Performed initial diagnostic evaluation.
2. Performed "Post Cruise" calibration of the temperature sensor.

### Special Notes:

--



# SEA-BIRD ELECTRONICS, INC.

13431 NE 20th St. Bellevue, Washington 98005 USA

Phone: (425) 643-9866 Fax: (425) 643-9954 www.seabird.com

<b>Service</b>
<b>Report</b>

**RMA Number**

71470

### Customer Information:

<b>Company</b>	US Department of Commerce, NOAA	<b>Date</b>	11/8/2012
<b>Contact</b>	Ulises Rivero		
<b>PO Number</b>	TBD		

<b>Serial Number</b>	041335
<b>Model Number</b>	SBE 04-02/0

### Services Requested:

1. Evaluate/Repair Instrumentation.
2. Perform Routine Calibration Service.

### Problems Found:

--

### Services Performed:

1. Performed initial diagnostic evaluation.
2. Performed "Post Cruise" calibration of the conductivity sensor.

### Special Notes:

--



# SEA-BIRD ELECTRONICS, INC.

13431 NE 20th St. Bellevue, Washington 98005 USA

Phone: (425) 643-9866 Fax: (425) 643-9954 www.seabird.com

<b>Service</b>
<b>Report</b>

<b>RMA Number</b>	71470
-------------------	-------

### Customer Information:

<b>Company</b>	US Department of Commerce, NOAA	<b>Date</b>	11/8/2012
----------------	---------------------------------	-------------	-----------

<b>Contact</b>	Ulises Rivero
----------------	---------------

<b>PO Number</b>	TBD
------------------	-----

<b>Serial Number</b>	042973
<b>Model Number</b>	SBE 04C

### Services Requested:

1. Evaluate/Repair Instrumentation.
2. Perform Routine Calibration Service.

### Problems Found:

--

### Services Performed:

1. Performed initial diagnostic evaluation.
2. Performed "Post Cruise" calibration of the conductivity sensor.

### Special Notes:

--



# SEA-BIRD ELECTRONICS, INC.

13431 NE 20th St. Bellevue, Washington 98005 USA

Phone: (425) 643-9866 Fax: (425) 643-9954 www.seabird.com

<b>Service</b>
<b>Report</b>

**RMA Number**

71470

### Customer Information:

<b>Company</b>	US Department of Commerce, NOAA	<b>Date</b>	11/8/2012
<b>Contact</b>	Ulises Rivero		
<b>PO Number</b>	TBD		

<b>Serial Number</b>	043854
<b>Model Number</b>	SBE 04C

### Services Requested:

1. Evaluate/Repair Instrumentation.
2. Perform Routine Calibration Service.

### Problems Found:

--

### Services Performed:

1. Performed initial diagnostic evaluation.
2. Performed "Post Cruise" calibration of the conductivity sensor.

### Special Notes:

--



# SEA-BIRD ELECTRONICS, INC.

13431 NE 20th St. Bellevue, Washington 98005 USA

Phone: (425) 643-9866 Fax: (425) 643-9954 www.seabird.com

<b>Service</b>
<b>Report</b>

**RMA Number**

71470

### Customer Information:

<b>Company</b>	US Department of Commerce, NOAA	<b>Date</b>	11/8/2012
<b>Contact</b>	Ulises Rivero		
<b>PO Number</b>	TBD		

<b>Serial Number</b>	043861
<b>Model Number</b>	SBE 04C

### Services Requested:

1. Evaluate/Repair Instrumentation.
2. Perform Routine Calibration Service.

### Problems Found:

--

### Services Performed:

1. Performed initial diagnostic evaluation.
2. Performed "Post Cruise" calibration of the conductivity sensor.

### Special Notes:

--