



SEA-BIRD ELECTRONICS, INC.

13431 NE 20th St. Bellevue, Washington 98005 USA

Phone: (425) 643-9866 Fax: (425) 643-9954 www.seabird.com

Service
Report

RMA Number

86396

Customer Information:

Company	US Department of Commerce, NOAA	Date	9/9/2015
Contact	Grant Rawson		
PO Number	TBD		

Serial Number	03P2958
Model Number	SBE 03Plus

Services Requested:

1. Evaluate/Repair Instrumentation.
2. Perform Routine Calibration Service.

Problems Found:

--

Services Performed:

1. Performed initial diagnostic evaluation.
2. Performed "Post Cruise" calibration of the temperature sensor.

Special Notes:

--



SEA-BIRD ELECTRONICS, INC.

13431 NE 20th St. Bellevue, Washington 98005 USA

Phone: (425) 643-9866 Fax: (425) 643-9954 www.seabird.com

Service
Report

RMA Number

86396

Customer Information:

Company US Department of Commerce, NOAA **Date** 9/9/2015

Contact Grant Rawson

PO Number TBD

Serial Number	03P5171
Model Number	SBE 03Plus

Services Requested:

1. Evaluate/Repair Instrumentation.
2. Perform Routine Calibration Service.

Problems Found:

--

Services Performed:

1. Performed initial diagnostic evaluation.
2. Performed "Post Cruise" calibration of the temperature sensor.

Special Notes:

--



SEA-BIRD ELECTRONICS, INC.

13431 NE 20th St. Bellevue, Washington 98005 USA

Phone: (425) 643-9866 Fax: (425) 643-9954 www.seabird.com

Service
Report

RMA Number

86396

Customer Information:

Company US Department of Commerce, NOAA **Date** 9/9/2015

Contact Grant Rawson

PO Number TBD

Serial Number 03P5237

Model Number SBE 03P

Services Requested:

1. Evaluate/Repair Instrumentation.
2. Perform Routine Calibration Service.

Problems Found:

--

Services Performed:

1. Performed initial diagnostic evaluation.
2. Performed "Post Cruise" calibration of the temperature sensor.

Special Notes:

--



SEA-BIRD ELECTRONICS, INC.

13431 NE 20th St. Bellevue, Washington 98005 USA

Phone: (425) 643-9866 Fax: (425) 643-9954 www.seabird.com

Service
Report

RMA Number

86396

Customer Information:

Company US Department of Commerce, NOAA **Date** 9/9/2015

Contact Grant Rawson

PO Number TBD

Serial Number 03P5855

Model Number SBE 03Plus

Services Requested:

1. Evaluate/Repair Instrumentation.
2. Perform Routine Calibration Service.

Problems Found:

--

Services Performed:

1. Performed initial diagnostic evaluation.
2. Performed "Post Cruise" calibration of the temperature sensor.

Special Notes:

--



SEA-BIRD ELECTRONICS, INC.

13431 NE 20th St. Bellevue, Washington 98005 USA

Phone: (425) 643-9866 Fax: (425) 643-9954 www.seabird.com

Service
Report

RMA Number

86396

Customer Information:

Company US Department of Commerce, NOAA **Date** 9/9/2015

Contact Grant Rawson

PO Number TBD

Serial Number 041335

Model Number SBE 04-02/0

Services Requested:

1. Evaluate/Repair Instrumentation.
2. Perform Routine Calibration Service.

Problems Found:

--

Services Performed:

1. Performed initial diagnostic evaluation.
2. Performed "Post Cruise" calibration of the conductivity sensor.

Special Notes:

--



SEA-BIRD ELECTRONICS, INC.

13431 NE 20th St. Bellevue, Washington 98005 USA

Phone: (425) 643-9866 Fax: (425) 643-9954 www.seabird.com

Service
Report

RMA Number

86396

Customer Information:

Company US Department of Commerce, NOAA **Date** 9/9/2015

Contact Grant Rawson

PO Number TBD

Serial Number 044223

Model Number SBE 04C

Services Requested:

1. Evaluate/Repair Instrumentation.
2. Perform Routine Calibration Service.

Problems Found:

--

Services Performed:

1. Performed initial diagnostic evaluation.
2. Performed "Post Cruise" calibration of the conductivity sensor.

Special Notes:

--



SEA-BIRD ELECTRONICS, INC.

13431 NE 20th St. Bellevue, Washington 98005 USA

Phone: (425) 643-9866 Fax: (425) 643-9954 www.seabird.com

Service
Report

RMA Number

86396

Customer Information:

Company	US Department of Commerce, NOAA	Date	9/9/2015
Contact	Grant Rawson		
PO Number	TBD		

Serial Number	044229
Model Number	SBE 04

Services Requested:

1. Evaluate/Repair Instrumentation.
2. Perform Routine Calibration Service.

Problems Found:

--

Services Performed:

1. Performed initial diagnostic evaluation.
2. Performed "Post Cruise" calibration of the conductivity sensor.

Special Notes:

--



SEA-BIRD ELECTRONICS, INC.

13431 NE 20th St. Bellevue, Washington 98005 USA

Phone: (425) 643-9866 Fax: (425) 643-9954 www.seabird.com

Service
Report

RMA Number

86396

Customer Information:

Company US Department of Commerce, NOAA **Date** 9/9/2015

Contact Grant Rawson

PO Number TBD

Serial Number 044346

Model Number SBE 04C

Services Requested:

1. Evaluate/Repair Instrumentation.
2. Perform Routine Calibration Service.

Problems Found:

--

Services Performed:

1. Performed initial diagnostic evaluation.
2. Performed "Post Cruise" calibration of the conductivity sensor.

Special Notes:

--



SEA-BIRD ELECTRONICS, INC.

13431 NE 20th St. Bellevue, Washington 98005 USA

Phone: (425) 643-9866 Fax: (425) 643-9954 www.seabird.com

Service
Report

RMA Number

86396

Customer Information:

Company US Department of Commerce, NOAA **Date** 9/9/2015

Contact Grant Rawson

PO Number TBD

Serial Number	432082
Model Number	SBE 43

Services Requested:

1. Evaluate/Repair Instrumentation.
2. Perform Routine Calibration Service.

Problems Found:

--

Services Performed:

1. Performed initial diagnostic evaluation.
2. Performed "Post Cruise" calibration of the oxygen sensor.
3. Performed full diagnostic evaluation.

Special Notes:

--



SEA-BIRD ELECTRONICS, INC.

13431 NE 20th St. Bellevue, Washington 98005 USA

Phone: (425) 643-9866 Fax: (425) 643-9954 www.seabird.com

Service
Report

RMA Number

86396

Customer Information:

Company US Department of Commerce, NOAA **Date** 9/9/2015

Contact Grant Rawson

PO Number TBD

Serial Number	432691
Model Number	SBE 43

Services Requested:

--

Problems Found:

--

Services Performed:

1. Performed initial diagnostic evaluation.
2. Performed "Post Cruise" calibration of the oxygen sensor.
3. Performed full diagnostic evaluation.

Special Notes:

--