



SEA-BIRD ELECTRONICS, INC.

13431 NE 20th St. Bellevue, Washington 98005 USA

Phone: (425) 643-9866 Fax: (425) 643-9954 www.seabird.com

Service
Report

RMA Number

89389

Customer Information:

Company	US Department of Commerce, NOAA	Date	3/31/2016
Contact	Grant Rawson		
PO Number	TBD		

Serial Number	031692
Model Number	SBE 03-02/F

Services Requested:

1. Evaluate/Repair Instrumentation.
2. Perform Routine Calibration Service.

Problems Found:

--

Services Performed:

1. Performed initial diagnostic evaluation.
2. Performed "Post Cruise" calibration of the temperature sensor.

Special Notes:

--



SEA-BIRD ELECTRONICS, INC.

13431 NE 20th St. Bellevue, Washington 98005 USA

Phone: (425) 643-9866 Fax: (425) 643-9954 www.seabird.com

Service
Report

RMA Number

89389

Customer Information:

Company US Department of Commerce, NOAA **Date** 3/31/2016

Contact Grant Rawson

PO Number TBD

Serial Number 03P4799

Model Number SBE 03Plus

Services Requested:

1. Evaluate/Repair Instrumentation.
2. Perform Routine Calibration Service.

Problems Found:

--

Services Performed:

1. Performed initial diagnostic evaluation.
2. Performed "Post Cruise" calibration of the temperature sensor.

Special Notes:

--



SEA-BIRD ELECTRONICS, INC.

13431 NE 20th St. Bellevue, Washington 98005 USA

Phone: (425) 643-9866 Fax: (425) 643-9954 www.seabird.com

Service
Report

RMA Number

89389

Customer Information:

Company US Department of Commerce, NOAA **Date** 3/31/2016

Contact Grant Rawson

PO Number TBD

Serial Number 03P5140

Model Number SBE 03Plus

Services Requested:

1. Evaluate/Repair Instrumentation.
2. Perform Routine Calibration Service.

Problems Found:

--

Services Performed:

1. Performed initial diagnostic evaluation.
2. Performed "Post Cruise" calibration of the temperature sensor.

Special Notes:

--



SEA-BIRD ELECTRONICS, INC.

13431 NE 20th St. Bellevue, Washington 98005 USA

Phone: (425) 643-9866 Fax: (425) 643-9954 www.seabird.com

Service
Report

RMA Number

89389

Customer Information:

Company US Department of Commerce, NOAA **Date** 3/31/2016

Contact Grant Rawson

PO Number TBD

Serial Number 03P5889

Model Number SBE 03Plus

Services Requested:

1. Evaluate/Repair Instrumentation.
2. Perform Routine Calibration Service.

Problems Found:

--

Services Performed:

1. Performed initial diagnostic evaluation.
2. Performed "Post Cruise" calibration of the temperature sensor.

Special Notes:

--



SEA-BIRD ELECTRONICS, INC.

13431 NE 20th St. Bellevue, Washington 98005 USA

Phone: (425) 643-9866 Fax: (425) 643-9954 www.seabird.com

Service
Report

RMA Number

89389

Customer Information:

Company	US Department of Commerce, NOAA	Date	3/31/2016
Contact	Grant Rawson		
PO Number	TBD		

Serial Number	03P5898
Model Number	SBE 03

Services Requested:

1. Evaluate/Repair Instrumentation.
2. Perform Routine Calibration Service.

Problems Found:

--

Services Performed:

1. Performed initial diagnostic evaluation.
2. Performed "Post Cruise" calibration of the temperature sensor.

Special Notes:

--



SEA-BIRD ELECTRONICS, INC.

13431 NE 20th St. Bellevue, Washington 98005 USA

Phone: (425) 643-9866 Fax: (425) 643-9954 www.seabird.com

Service
Report

RMA Number

89389

Customer Information:

Company US Department of Commerce, NOAA **Date** 3/31/2016

Contact Grant Rawson

PO Number TBD

Serial Number	041346
Model Number	SBE 04-02/0

Services Requested:

1. Evaluate/Repair Instrumentation.
2. Perform Routine Calibration Service.

Problems Found:

--

Services Performed:

1. Performed initial diagnostic evaluation.
2. Performed "Post Cruise" calibration of the conductivity sensor.

Special Notes:

--



SEA-BIRD ELECTRONICS, INC.

13431 NE 20th St. Bellevue, Washington 98005 USA

Phone: (425) 643-9866 Fax: (425) 643-9954 www.seabird.com

Service
Report

RMA Number

89389

Customer Information:

Company	US Department of Commerce, NOAA	Date	3/31/2016
----------------	---------------------------------	-------------	-----------

Contact	Grant Rawson
----------------	--------------

PO Number	TBD
------------------	-----

Serial Number	041374
----------------------	--------

Model Number	SBE 04-02/0
---------------------	-------------

Services Requested:

1. Evaluate/Repair Instrumentation.
2. Perform Routine Calibration Service.

Problems Found:

--

Services Performed:

1. Performed initial diagnostic evaluation.
2. Performed "Post Cruise" calibration of the conductivity sensor.

Special Notes:

--



SEA-BIRD ELECTRONICS, INC.

13431 NE 20th St. Bellevue, Washington 98005 USA

Phone: (425) 643-9866 Fax: (425) 643-9954 www.seabird.com

Service
Report

RMA Number

89389

Customer Information:

Company US Department of Commerce, NOAA **Date** 3/31/2016

Contact Grant Rawson

PO Number TBD

Serial Number 044223

Model Number SBE 04C

Services Requested:

1. Evaluate/Repair Instrumentation.
2. Perform Routine Calibration Service.

Problems Found:

--

Services Performed:

1. Performed initial diagnostic evaluation.
2. Performed "Post Cruise" calibration of the conductivity sensor.

Special Notes:

--



SEA-BIRD ELECTRONICS, INC.

13431 NE 20th St. Bellevue, Washington 98005 USA

Phone: (425) 643-9866 Fax: (425) 643-9954 www.seabird.com

Service
Report

RMA Number	89389
-------------------	-------

Customer Information:

Company	US Department of Commerce, NOAA	Date	3/31/2016
Contact	Grant Rawson		
PO Number	TBD		

Serial Number	044229
Model Number	SBE 04

Services Requested:

1. Evaluate/Repair Instrumentation.
2. Perform Routine Calibration Service.

Problems Found:

--

Services Performed:

1. Performed initial diagnostic evaluation.
2. Performed "Post Cruise" calibration of the conductivity sensor.

Special Notes:

--



SEA-BIRD ELECTRONICS, INC.

13431 NE 20th St. Bellevue, Washington 98005 USA

Phone: (425) 643-9866 Fax: (425) 643-9954 www.seabird.com

Service
Report

RMA Number	89389
-------------------	-------

Customer Information:

Company	US Department of Commerce, NOAA	Date	3/31/2016
----------------	---------------------------------	-------------	-----------

Contact	Grant Rawson
----------------	--------------

PO Number	TBD
------------------	-----

Serial Number	051028
Model Number	SBE 05T

Services Requested:

1. Evaluate/Repair Instrumentation.

Problems Found:

--

Services Performed:

1. Performed initial diagnostic evaluation.
2. Performed internal inspection and O-ring and thrust washer replacements.
3. Performed hydrostatic pressure test.

Special Notes:

--



SEA-BIRD ELECTRONICS, INC.

13431 NE 20th St. Bellevue, Washington 98005 USA

Phone: (425) 643-9866 Fax: (425) 643-9954 www.seabird.com

Service
Report

RMA Number

89389

Customer Information:

Company US Department of Commerce, NOAA **Date** 3/31/2016

Contact Grant Rawson

PO Number TBD

Serial Number	057705
Model Number	SBE 05T

Services Requested:

1. Evaluate/Repair Instrumentation.

Problems Found:

Services Performed:

1. Performed initial diagnostic evaluation.
2. Performed internal inspection and O-ring and thrust washer replacements.
3. Performed hydrostatic pressure test.

Special Notes:



SEA-BIRD ELECTRONICS, INC.

13431 NE 20th St. Bellevue, Washington 98005 USA

Phone: (425) 643-9866 Fax: (425) 643-9954 www.seabird.com

Service
Report

RMA Number

89389

Customer Information:

Company US Department of Commerce, NOAA **Date** 3/31/2016

Contact Grant Rawson

PO Number TBD

Serial Number 057889

Model Number SBE 05T

Services Requested:

1. Evaluate/Repair Instrumentation.

Problems Found:

Services Performed:

1. Performed initial diagnostic evaluation.
2. Performed internal inspection and O-ring and thrust washer replacements.
3. Performed hydrostatic pressure test.

Special Notes: