

13431 NE 20th Street Bellevue, WA 98005 United States Phone +1-425-643-9866

www.seabird.com

1005512369 22-MAR-2021

316348515

Service Request Date Sales Order

PO Number:

1333MJ20FNRMA0011

CUSTOMER INFORMATION

SERVICE REPORT

Name: NOAA - ATLANTIC OCEANOGRAPHIC AND METEOROLOGICAL LAB

Account : 40279759 GRANT RAWSON

GRANT.RAWSON@NOAA.GOV

(305) 361-4363

Bill To Address

4301 RICKENBACKER CAUSEWAY

MIAMI,FL,33149,US

Ship To Address 4301 RICKENBACKER CAUSEWAY MIAMI,FL,33149,US

PRODUCT INFORMATION

Item: APL-GLIDER.LEGACY

Item Description: (LEGACY) APL Glider

Serial: 0317

Special Notes

Services Requested: Conductivity Calibration Temperature Calibration

Problems Found:

The temperature probe was found to have failed.

Services Performed:

Performed initial diagnostic evaluation. Performed "POST" cruise calibration. Replaced temperature probe. Performed a "Final" Calibration.

| Item | Item Description | Qty |
|---------------|--|-----|
| CAL_SEAGLIDER | Calibrate Seaglider conductivity and temperature sensors | 1 |
| | | |

| Item | Item Description | Qty |
|--------|---|-----|
| 802134 | VM GLIDER THERM PROBE ASSY,V3,SHIELDED,FENWAL | 1 |



13431 NE 20th Street Bellevue, WA 98005 United States Phone +1-425-643-9866

Service Request

Sales Order

Date

www.seabird.com

1005512369 22-MAR-2021 316348515

SERVICE REPORT

PRODUCT INFORMATION

Item: APL-GLIDER.LEGACY

Item Description: (LEGACY) APL Glider

Serial: 0313

Special Notes
Services Requested:
Conductivity Calibration
Temperature Calibration

Problems Found:

The temperature probe was found to have failed.

Services Performed:
Performed initial diagnostic evaluation.
Performed "POST" cruise calibration.
Replaced temperature probe.
Performed a "Final" Calibration.

| Item | Item Description | Qty |
|---------------|--|-----|
| CAL_SEAGLIDER | Calibrate Seaglider conductivity and temperature sensors | 1 |
| REPGLIDERPROB | Replace SBE Glider thermistor probe | 1 |
| | | |

| Item | Item Description | Qty |
|--------|---|-----|
| 802134 | VM GLIDER THERM PROBE ASSY,V3,SHIELDED,FENWAL | 1 |



SERVICE REPORT

Sea-Bird Electronics, Inc.

13431 NE 20th Street Bellevue, WA 98005 United States Phone +1-425-643-9866

www.seabird.com

Service Request Date Sales Order 1005512369 22-MAR-2021 316348515

PRODUCT INFORMATION

Item: APL-GLIDER.LEGACY

Item Description: (LEGACY) APL Glider

Serial: 0350

Special Notes Services Requested: Conductivity Calibration Temperature Calibration

Problems Found: No problems found.

Services Performed:

Performed initial diagnostic evaluation. Performed "POST" cruise calibration.

| Item | Item Description | Qty |
|---------------|--|-----|
| CAL_SEAGLIDER | Calibrate Seaglider conductivity and temperature sensors | 1 |
| | | |

| Item | Item Description | Qty |
|------|------------------|-----|
| | | |



13431 NE 20th Street Bellevue, WA 98005 United States Phone +1-425-643-9866

www.seabird.com

Service Request
Date
Sales Order

1005512369 22-MAR-2021 316348515

SERVICE REPORT

PRODUCT INFORMATION

Item: APL-GLIDER.LEGACY

Item Description: (LEGACY) APL Glider

Serial: 0266

Special Notes
Services Requested:
Conductivity Calibration
Temperature Calibration

Problems Found:

The temperature was found to have excessive drift.

Services Performed:
Performed initial diagnostic evaluation.
Performed "POST" cruise calibration.
Replaced temperature probe.
Performed a "Final" Calibration.

| Item | Item Description | Qty |
|---------------|--|-----|
| CAL_SEAGLIDER | Calibrate Seaglider conductivity and temperature sensors | 1 |
| REPGLIDERPROB | Replace SBE Glider thermistor probe | 1 |
| | | |

| • | | |
|--------|---|-----|
| Item | Item Description | Qty |
| 802134 | VM GLIDER THERM PROBE ASSY,V3,SHIELDED,FENWAL | 1 |



SERVICE REPORT

Sea-Bird Electronics, Inc.

13431 NE 20th Street Bellevue, WA 98005 United States Phone +1-425-643-9866

www.seabird.com

Service Request Date Sales Order 1005512369 22-MAR-2021 316348515

Item: APL-GLIDER.LEGACY

PRODUCT INFORMATION

Item Description: (LEGACY) APL Glider

Serial: 0265

Special Notes
Services Requested:
Conductivity Calibration
Temperature Calibration

Problems Found:

Found to require temperature and conductivity boards modification.

Services Performed:

Performed initial diagnostic evaluation.

Modified temperature and conductivity boards.

Performed "POST" cruise calibration.

| Item | Item Description | Qty |
|---------------|--|-----|
| CAL_SEAGLIDER | Calibrate Seaglider conductivity and temperature sensors | 1 |
| | | |

| Item | Item Description | Qty |
|--------|---------------------------------------|-----|
| 235735 | MORRISON SEAL RETAINER, UW/APL GLIDER | 1 |



13431 NE 20th Street Bellevue, WA 98005 United States Phone +1-425-643-9866

www.seabird.com

Service Request
Date
Sales Order

1005512369 22-MAR-2021 316348515

SERVICE REPORT

PRODUCT INFORMATION

Item: APL-GLIDER.LEGACY

Item Description: (LEGACY) APL Glider

Serial: 0353

Special Notes
Services Requested:
Conductivity Calibration
Temperature Calibration

Problems Found:

High temperature residuals. Board and temperature probe replacement is required.

Services Performed:

Performed initial diagnostic evaluation. Performed "POST" cruise calibration.

Replaced temperature probe and temperature board.

Performed a "Final" Calibration.

| Item | Item Description | Qty |
|---------------|--|-----|
| CAL_SEAGLIDER | Calibrate Seaglider conductivity and temperature sensors | 1 |
| | | |

| Item | Item Description | Qty |
|--------|---|-----|
| 802134 | VM GLIDER THERM PROBE ASSY,V3,SHIELDED,FENWAL | 1 |
| 41028T | UW/APL GLIDER WBO TEMP ELEC'S ASSY, TESTED | 1 |



13431 NE 20th Street Bellevue, WA 98005 United States Phone +1-425-643-9866

www.seabird.com

Service Request Date Sales Order 1005512369 22-MAR-2021 316348515

SERVICE REPORT

PRODUCT INFORMATION

Item: APL-GLIDER.LEGACY

Item Description: (LEGACY) APL Glider

Serial: 0316

Special Notes
Services Requested:
Conductivity Calibration
Temperature Calibration

Problems Found:

The conductivity cell was found to be cracked.

Services Performed:
Performed initial diagnostic evaluation.
Performed "POST" cruise calibration.
Replaced the conductivity cell.
Performed a "Final" Calibration.

| Item | Item Description | Qty |
|---------------|---|-----|
| REPGLIDERCELL | Extra charge to replace broken SBE Glider conductivity cell | 1 |
| CAL_SEAGLIDER | Calibrate Seaglider conductivity and temperature sensors | 1 |

| Item | Item Description | Qty |
|--------|---|-----|
| 41119T | UW/APL GLIDER ISOLATED WBO COND ELECT, TESTED | 1 |
| 41028T | UW/APL GLIDER WBO TEMP ELEC'S ASSY, TESTED | 1 |
| 802761 | ALACE COND CELL ASSEMBLY, NO WRAP, SHIELDED WIRES | 1 |
| | | |



13431 NE 20th Street Bellevue, WA 98005 United States Phone

+1-425-643-9866

www.seabird.com

1005512369 22-MAR-2021 316348515

SERVICE REPORT

Service Request Date Sales Order

PRODUCT INFORMATION

Item: APL-GLIDER.LEGACY

Item Description: (LEGACY) APL Glider

Serial: 0349

Special Notes
Services Requested:
Conductivity Calibration
Temperature Calibration

Problems Found:

The temperature was found to have excessive drift.

Services Performed:
Performed initial diagnostic evaluation.
Performed "POST" cruise calibration.
Replaced the temperature probe.
Performed a "Final" Calibration.

| Item | Item Description | Qty |
|---------------|--|-----|
| CAL_SEAGLIDER | Calibrate Seaglider conductivity and temperature sensors | 1 |
| | | |

| Onionioa itomo | | |
|----------------|---|-----|
| Item | Item Description | Qty |
| 802134 | VM GLIDER THERM PROBE ASSY,V3,SHIELDED,FENWAL | 1 |



13431 NE 20th Street Bellevue, WA 98005 United States Phone +1-425-643-9866

Date

Sales Order

www.seabird.com

Service Request 1005512369 22-MAR-2021 316348515

SERVICE REPORT

PRODUCT INFORMATION

Item: APL-GLIDER.LEGACY

Item Description: (LEGACY) APL Glider

Serial: 0338

Special Notes Services Requested: Conductivity Calibration **Temperature Calibration**

Services Performed:

Performed initial diagnostic evaluation. Performed "POST" cruise calibration.

| Item | Item Description | Qty |
|---------------|--|-----|
| CAL_SEAGLIDER | Calibrate Seaglider conductivity and temperature sensors | 1 |
| | | |

| Item | Item Description | Qty |
|------|------------------|-----|
| | | |