

13431 NE 20th Street Bellevue, WA 98005 United States +1-425-643-9866 www.seabird.com

(Do Not Send Payments To This Physical Address – See Remit to Information)

 Service Request
 1005518923

 Date
 08-NOV-2023

 Sales Order
 320741385

SEABIRD 1333MJ22FNRMA0017

Phone

PO Number:

SERVICE REPORT

**CUSTOMER INFORMATION** 

Name: NOAA - AMOL ATLANTIC OCEANOGRAPHIC and METEOROLOGICAL

LAB

Account: 40279759 GRANT RAWSON

GRANT.RAWSON@NOAA.GOV

(305) 361-4363

**Bill To Address** 

NOAA - AMOL ATLANTIC OCEANOGRAPHIC and METEOROLOGICAL LAB 4301 RICKENBACKER CAUSEWAY MIAMI,FL,33149,US Ship To Address

NOAA - AMOL ATLANTIC OCEANOGRAPHIC and METEOROLOGICAL LAB 4301 RICKENBACKER CAUSEWAY MIAMI,FL,33149,US

#### PRODUCT INFORMATION

Item: 03F.LEGACY

Item Description: (LEGACY) SBE 03F Temperature Sensor

Serial: 031692

**Special Notes** 

Services Requested:

CAL 3

CONCERT/S (requested by email)

No problems found.

Services Performed:
Perform initial diagnostic evaluation.
Performed "POST" cruise calibration.
Replaced the O-rings.
Performed a hydrostatic pressure test.

Performed a "Final" Calibration.

Item	Item Description	Qty
CAL_3	SBE 3 Temperature sensor calibration; 11 points -1 to 31deg.C	1
CONCERT/S	Confirm and recertify sensor including opening the main housing, replacing end cap "piston" o-rings, and making minor internal repairs or modifications. Hydrostatic pressure test following closure. Cost of major repairs or modifications is not included.	1

Item	Item Description	Qty



**SERVICE REPORT** 

# Sea-Bird Electronics, Inc.

13431 NE 20th Street Bellevue, WA 98005 United States

www.seabird.com

Phone

(Do Not Send Payments To This Physical Address – See Remit to Information)

**Service Request Date** 

**Sales Order** 

1005518923 08-NOV-2023

320741385

+1-425-643-9866

# **PRODUCT INFORMATION**

Item: 03P.210

Item Description: SBE3PLUS TEMP, GE PROBE, 6800M, XSG

Serial: 03-5207

**Special Notes** 

Services Requested: CAL\_3

CONCERT/S (requested by email)

No problems found.

Services Performed:

Perform initial diagnostic evaluation. Performed "POST" cruise calibration.

Replaced the O-rings.

Performed a hydrostatic pressure test.

Performed a "Final" Calibration.

Item	Item Description	Qty
CAL_3	SBE 3 Temperature sensor calibration; 11 points -1 to 31deg.C	1
CONCERT/S	Confirm and recertify sensor including opening the main housing, replacing end cap "piston" o-rings, and making minor internal repairs or modifications. Hydrostatic pressure test following closure. Cost of major repairs or modifications is not included.	1

Item	Item Description	Qty



13431 NE 20th Street Bellevue, WA 98005 United States

Phone

(Do Not Send Payments To This Physical Address – See Remit to Information)

**Service Request Date** 

08-NOV-2023 **Sales Order** 

+1-425-643-9866

www.seabird.com

1005518923

320741385

**SERVICE REPORT** 

# PRODUCT INFORMATION

Item: 03P.LEGACY

Item Description: (LEGACY) SBE 03Plus Temperature Sensor

**Serial:** 03P5140

**Special Notes** Services Requested:

CAL\_3

Problems Found:

The temperature was found to have excessive drift.

Services Performed:

Perform initial diagnostic evaluation. Performed "POST" cruise calibration. Replaced the temperature probe.

Replaced the O-rings.

Performed a hydrostatic pressure test.

Performed a "Final" Calibration.

Item	Item Description	Qty
CAL_3	SBE 3 Temperature sensor calibration; 11 points -1 to 31deg.C	1
CONCERT/S	Confirm and recertify sensor including opening the main housing, replacing end cap "piston" o-rings, and making minor internal repairs or modifications. Hydrostatic pressure test following closure. Cost of major repairs or modifications is not included.	1
REP3PROB	Replace SBE 3 thermistor probe	1

Item	Item Description	Qty
80004	FAST TEMP 70 MS THERMISTOR PROBE ASSEMBLY	1



13431 NE 20th Street Bellevue, WA 98005 United States

(Do Not Send Payments To This Physical Address – See Remit to Information)

ess – See Remit to Information
Service Request

Phone

Date Sales Order 1005518923

+1-425-643-9866

www.seabird.com

08-NOV-2023 320741385

# SERVICE REPORT

# PRODUCT INFORMATION

Item: 03F.LEGACY

Item Description: (LEGACY) SBE 03F Temperature Sensor

**Serial:** 031075

Special Notes
Services Requested:

CAL\_3

CONCERT/S (requested by email)

No problems found.

Services Performed: Perform initial diagnostic evaluation. Performed "POST" cruise calibration. Replaced the O-rings.

Performed a hydrostatic pressure test.

Performed a "Final" Calibration.

Item	Item Description	Qty
CAL_3	SBE 3 Temperature sensor calibration; 11 points -1 to 31deg.C	1
CONCERT/S	Confirm and recertify sensor including opening the main housing, replacing end cap "piston" o-rings, and making minor internal repairs or modifications. Hydrostatic pressure test following closure. Cost of major repairs or modifications is not included.	1

Item	Item Description	Qty



13431 NE 20th Street Bellevue, WA 98005 United States

www.seabird.com

(Do Not Send Payments To This Physical Address – See Remit to Information)

**SERVICE REPORT** 

Service Request Date Sales Order

Phone

**1005518923** 08-NOV-2023 320741385

+1-425-643-9866

# PRODUCT INFORMATION

Item: 03F.LEGACY

Item Description: (LEGACY) SBE 03F Temperature Sensor

**Serial:** 031701

Special Notes
Services Requested:

CAL\_3

CONCERT/S (requested by email)

No problems found.

Services Performed:
Perform initial diagnostic evaluation.
Performed "POST" cruise calibration.
Replaced the O-rings.
Performed a hydrostatic pressure test.
Performed a "Final" Calibration.

Item	Item Description	Qty
CAL_3	SBE 3 Temperature sensor calibration; 11 points -1 to 31deg.C	1
CONCERT/S	Confirm and recertify sensor including opening the main housing, replacing end cap "piston" o-rings, and making minor internal repairs or modifications. Hydrostatic pressure test following closure. Cost of major repairs or modifications is not included.	1

Item	Item Description	Qty



13431 NE 20th Street Bellevue, WA 98005 United States

(Do Not Send Payments To This Physical Address – See Remit to Information)

Phone

**Service Request Date Sales Order** 

1005518923

+1-425-643-9866

www.seabird.com

08-NOV-2023 320741385

# **SERVICE REPORT**

# PRODUCT INFORMATION

Item: 03F.LEGACY

Item Description: (LEGACY) SBE 03F Temperature Sensor

Serial: 031609

**Special Notes** Services Requested:

CAL\_3

Problems Found:

The temperature was found to have excessive drift.

Services Performed:

Perform initial diagnostic evaluation. Performed "POST" cruise calibration. Replaced the temperature probe.

Replaced the O-rings.

Performed a hydrostatic pressure test.

Performed a "Final" Calibration.

Item	Item Description	Qty
CAL_3	SBE 3 Temperature sensor calibration; 11 points -1 to 31deg.C	1
CONCERT/S	Confirm and recertify sensor including opening the main housing, replacing end cap "piston" o-rings, and making minor internal repairs or modifications. Hydrostatic pressure test following closure. Cost of major repairs or modifications is not included.	1
REP3PROB	Replace SBE 3 thermistor probe	1

Item	Item Description	Qty
80004	FAST TEMP 70 MS THERMISTOR PROBE ASSEMBLY	1



13431 NE 20th Street Bellevue, WA 98005 United States

www.seabird.com

(Do Not Send Payments To This Physical Address – See Remit to Information)

SERVICE REPORT

Service Request Date Sales Order

Phone

**1005518923** 08-NOV-2023 320741385

+1-425-643-9866

# PRODUCT INFORMATION

Item: 04C.LEGACY

Item Description: (LEGACY) SBE 04C Conductivity Sensor

**Serial:** 041374

**Special Notes**Services Requested:

CAL\_4C

CONCERT/S (requested by email)

No problems found.

Services Performed:
Perform initial diagnostic evaluation.
Performed "POST" cruise calibration.
Replaced the O-rings.
Performed a hydrostatic pressure test.
Performed a "Final" Calibration.

Item	Item Description	Qty



13431 NE 20th Street Bellevue, WA 98005 United States

www.seabird.com

(Do Not Send Payments To This Physical Address – See Remit to Information)

**SERVICE REPORT** 

Service Request Date Sales Order

Phone

**1005518923** 08-NOV-2023 320741385

+1-425-643-9866

# PRODUCT INFORMATION

Item: 04C.LEGACY

Item Description: (LEGACY) SBE 04C Conductivity Sensor

**Serial:** 041387

Special Notes
Services Requested:

CAL\_4C

CONCERT/S (requested by email)

No problems found.

Services Performed:
Perform initial diagnostic evaluation.
Performed "POST" cruise calibration.
Replaced the O-rings.
Performed a hydrostatic pressure test.

Performed a "Final" Calibration.

Item	Item Description	Qty
CAL_4C	SBE 4C Conductivity Calibration for CTD sensors (includes 6-point 35 PSU	1
	post deployment cal., and C&P with 6-point 35 PSU re-cal, if necessary)	
CONCERT/S	Confirm and recertify sensor including opening the main housing, replacing end cap "piston" o-rings, and making minor internal repairs or modifications. Hydrostatic pressure test following closure. Cost of major repairs or modifications is not included.	1

Item	Item Description	Qty



13431 NE 20th Street Bellevue, WA 98005 United States

(Do Not Send Payments To This Physical Address – See Remit to Information)

Service Request

Phone

Date Sales Order www.seabird.com

+1-425-643-9866

**1005518923** 08-NOV-2023 320741385

# **SERVICE REPORT**

# **PRODUCT INFORMATION**

Item: 04C.LEGACY

Item Description: (LEGACY) SBE 04C Conductivity Sensor

**Serial:** 042980

**Special Notes** Services Requested:

CAL\_4C

Problems Found: Internal water damage.

Services Performed:

Perform initial diagnostic evaluation.

Replaced the housing, conductivty cell, electronic board set, and anode.

Replaced the O-rings.

Performed a hydrostatic pressure test.

Performed a "Final" Calibration.

Item	Item Description	Qty

Item	Item Description	Qty
80994T	SBE-4 (ver. 2) conductivity electronics	1
80009.2	CONDUCTIVITY CELL, 6800M ALUMINUM ASSEMBLY	1
23548	Zinc anode ring (sensors with tubing connector)	1
23026C	SBE4 COND HOUSING 6800M, HARDCOATED	1
CAL_4C	SBE 4C Conductivity Calibration for CTD sensors (includes 6-point 35 PSU post deployment cal., and C&P with 6-point 35 PSU re-cal, if necessary)	1



13431 NE 20th Street Bellevue, WA 98005 United States

www.seabird.com

(Do Not Send Payments To This Physical Address – See Remit to Information)

**SERVICE REPORT** 

Service Request Date Sales Order

Phone

**1005518923** 08-NOV-2023 320741385

+1-425-643-9866

# PRODUCT INFORMATION

Item: 04C.LEGACY

Item Description: (LEGACY) SBE 04C Conductivity Sensor

**Serial:** 041335

**Special Notes** Services Requested: CAL\_4C

CONCERT/S (requested by email)

No problems found.

Services Performed:
Perform initial diagnostic evaluation.
Performed "POST" cruise calibration.
Replaced the O-rings.
Performed a hydrostatic pressure test.
Performed a "Final" Calibration.

Item	Item Description	Qty
CAL_4C	SBE 4C Conductivity Calibration for CTD sensors (includes 6-point 35 PSU post deployment cal., and C&P with 6-point 35 PSU re-cal, if necessary)	1
CONCERT/S	Confirm and recertify sensor including opening the main housing, replacing end cap "piston" o-rings, and making minor internal repairs or modifications. Hydrostatic pressure test following closure. Cost of major repairs or modifications is not included.	1

Item	Item Description	Qty



13431 NE 20th Street Bellevue, WA 98005 United States

(Do Not Send Payments To This Physical Address – See Remit to Information)

**Service Request Date Sales Order** 

Phone

1005518923 08-NOV-2023 320741385

+1-425-643-9866

www.seabird.com

**SERVICE REPORT** 

# PRODUCT INFORMATION

Item: 04C.LEGACY

Item Description: (LEGACY) SBE 04C Conductivity Sensor

**Serial:** 041346

**Special Notes** Services Requested:

CAL\_4C

Problems Found:

Sensor was found to have internal water damage.

The housing, end cap, and conductivity cell require replacement.

Services Performed:

Perform initial diagnostic evaluation.

Replaced the housing, end cap, and conductivty cell.

Replaced the O-rings.

Performed a hydrostatic pressure test.

Performed a "Final" Calibration.

Item	Item Description	Qty
23024C	SBE4 COND. ENDCAP 6800M, HARDCOATED	1
23026C	SBE4 COND HOUSING 6800M, HARDCOATED	1
REP4CEL/A	Replace broken SBE 4 cell (aluminum tray). Requires calibration	1
CONCERT/S	Confirm and recertify sensor including opening the main housing, replacing end cap "piston" o-rings, and making minor internal repairs or modifications. Hydrostatic pressure test following closure. Cost of major repairs or modifications is not included.	1
CAL_4C	SBE 4C Conductivity Calibration for CTD sensors (includes 6-point 35 PSU post deployment cal., and C&P with 6-point 35 PSU re-cal, if necessary)	1

Item	Item Description	Qty
80009.2	CONDUCTIVITY CELL, 6800M ALUMINUM ASSEMBLY	1



13431 NE 20th Street Bellevue, WA 98005 United States

www.seabird.com

(Do Not Send Payments To This Physical Address – See Remit to Information)

**Service Request** 

Phone

1005518923 08-NOV-2023 320741385

+1-425-643-9866

**SERVICE REPORT** 

**Date Sales Order** 

# PRODUCT INFORMATION

Item: 43.LEGACY

Item Description: (LEGACY) SBE 43 Oxygen Sensor

Serial: 432082

**Special Notes** 

Services Requested: CAL\_43

CONCERT/S (requested by email)

No problems found.

Services Performed: Perform initial diagnostic evaluation. Performed "POST" cruise calibration. Replaced the O-rings.

Performed a hydrostatic pressure test.

Performed a "Final" Calibration.

Item	Item Description	Qty
CAL_43	SBE 43 dissolved oxygen sensor calibration	1
CONCERT/S	Confirm and recertify sensor including opening the main housing, replacing end cap "piston" o-rings, and making minor internal repairs or modifications. Hydrostatic pressure test following closure. Cost of major repairs or modifications is not included.	1

Item	Item Description	Qty



13431 NE 20th Street Bellevue, WA 98005 United States

(Do Not Send Payments To This Physical Address – See Remit to Information)

Service Request

Phone

Date Sales Order www.seabird.com 1005518923

+1-425-643-9866

08-NOV-2023 320741385

# **SERVICE REPORT**

# PRODUCT INFORMATION

Item: 43.LEGACY

Item Description: (LEGACY) SBE 43 Oxygen Sensor

Serial: 432083

Special Notes

Services Requested:

CAL\_43

CONCERT/S (requested by email)

No problems found.

Services Performed:

Perform initial diagnostic evaluation.

Performed "POST" cruise calibration.

Replaced the O-rings.

Performed a hydrostatic pressure test.

Performed a "Final" Calibration.

Item	Item Description	Qty
CAL_43	SBE 43 dissolved oxygen sensor calibration	1
CONCERT/S	Confirm and recertify sensor including opening the main housing, replacing end cap "piston" o-rings, and making minor internal repairs or modifications. Hydrostatic pressure test following closure. Cost of major repairs or modifications is not included.	1

Item	Item Description	Qty



13431 NE 20th Street Bellevue, WA 98005 United States

www.seabird.com

(Do Not Send Payments To This Physical Address – See Remit to Information)

**SERVICE REPORT** 

**Service Request Date Sales Order** 

Phone

1005518923 08-NOV-2023 320741385

+1-425-643-9866

# PRODUCT INFORMATION

Item: 43.LEGACY

Item Description: (LEGACY) SBE 43 Oxygen Sensor

**Serial:** 43-2940

**Special Notes** Services Requested:

CAL\_43 CONCERT/S (requested by email)

No problems found:

Services Performed: Perform initial diagnostic evaluation. Performed "POST" cruise calibration. Replaced the O-rings. Performed a hydrostatic pressure test. Performed a "Final" Calibration.

Item	Item Description	Qty
CAL_43	SBE 43 dissolved oxygen sensor calibration	1
CONCERT/S	Confirm and recertify sensor including opening the main housing, replacing end cap "piston" o-rings, and making minor internal repairs or modifications. Hydrostatic pressure test following closure. Cost of major repairs or modifications is not included.	1

Item	Item Description	Qty



**SERVICE REPORT** 

# Sea-Bird Electronics, Inc.

13431 NE 20th Street Bellevue, WA 98005 United States

(Do Not Send Payments To This Physical Address – See Remit to Information)

**Service Request** 

Phone

**Date Sales Order**  www.seabird.com 1005518923

+1-425-643-9866

08-NOV-2023 320741385

# PRODUCT INFORMATION

Item: 43.LEGACY

Item Description: (LEGACY) SBE 43 Oxygen Sensor

Serial: 432085

**Special Notes** Services Requested:

CAL\_43

Problems Found:

The membrane was found to be punctured.

Services Performed:

Perform initial diagnostic evaluation. Performed "POST" cruise calibration. Replaced the lid and membrane assembly (0.5 mil).

Replaced the electrolyte with new fluid.

Replaced the O-rings.

Performed a hydrostatic pressure test.

Performed a "Final" Calibration.

Item	Item Description	Qty
CAL_43	SBE 43 dissolved oxygen sensor calibration	1

Item	Item Description	Qty
801576	SBE43 LID & MEMBRANE SUB-ASSY, .5MIL MEMBRANE	1
22085	BATTERY, SANYO CR14250SE-SP1-1, 850 mA-h	2



**SERVICE REPORT** 

# Sea-Bird Electronics, Inc.

13431 NE 20th Street Bellevue, WA 98005 United States

(Do Not Send Payments To This Physical Address – See Remit to Information)

Service Request

Phone

Date Sales Order www.seabird.com

+1-425-643-9866

**1005518923** 08-NOV-2023

320741385

# PRODUCT INFORMATION

Item: 43.LEGACY

Item Description: (LEGACY) SBE 43 Oxygen Sensor

**Serial:** 43-2934

Special Notes
Services Requested:

CAL\_43

CAL\_43

Problems Found:

The Anode/Getter sub-assembly was found to have failed.

Services Performed:

Perform initial diagnostic evaluation.

Replaced the SBE 43 Anode sub assembly.

Replaced the SBE 43 Getter sub assembly.

Replaced the lid and membrane assembly (0.5 mil).

Replaced the electrolyte with new fluid.

Replaced the O-rings.

Performed a hydrostatic pressure test.

Performed a "Final" Calibration.

Item	Item Description	Qty
CAL_43	SBE 43 dissolved oxygen sensor calibration	1

Item	Item Description	Qty
801576	SBE43 LID & MEMBRANE SUB-ASSY, .5MIL MEMBRANE	1
801230	SBE43 ANODE SUB-ASSEMBLY / DWG 41092	1
801229	SBE43 GETTER SUB-ASSEMBLY / DWG 41091	1



13431 NE 20th Street Bellevue, WA 98005 United States

www.seabird.com

(Do Not Send Payments To This Physical Address – See Remit to Information)

**SERVICE REPORT** 

Service Request Date Sales Order

Phone

**1005518923** 08-NOV-2023 320741385

+1-425-643-9866

# PRODUCT INFORMATION

Item: 43.LEGACY

Item Description: (LEGACY) SBE 43 Oxygen Sensor

Serial: 432691

Special Notes
Services Requested:

CAL\_43

CONCERT/S (requested by email)

No problems found.

Services Performed:
Perform initial diagnostic evaluation.
Performed "POST" cruise calibration.
Replaced the O-rings.
Performed a hydrostatic pressure test.
Performed a "Final" Calibration.

Item	Item Description	Qty
CAL_43	SBE 43 dissolved oxygen sensor calibration	1
CONCERT/S	Confirm and recertify sensor including opening the main housing, replacing end cap "piston" o-rings, and making minor internal repairs or modifications. Hydrostatic pressure test following closure. Cost of major repairs or modifications is not included.	1

Item	Item Description	Qty